



Figure 6

BRIDGE DEFICIENCIES



ISOTHERMAL RPO

(McDowell, Polk & Rutherford Counties)

CTP Analysis and Information

DRAFT WORKING MAP
Plan Date: August 13, 2019

Bridge Features

- # Deficient Bridge
- Bridge
- Other Structure

Other Features

- Study Road
- Durham - Chapel Hill - Carrboro MPO



Full report at:
<https://qrco.de/bbAY17>



0 1 2 4
Miles

Sheet 3 of 4

Base map date: March 18, 2018

Legal Disclaimer

This product contains mapping data for informational and planning purposes only, and is subject to change. Users should review or consult the primary data sources to ascertain the usability of the information.