# OPENX SAMPLE PLANSET

Please note that the inventories presented are simplified geotechnical products (no profiles or cross sections). The only notable item using ORD is the plan sheet. Future projects will likely have cross sections and/or profiles provided. Please contact Geotech for any project specific guideline.

Refer to applicable Manuals, Standards, and Guidelines for actual design requirements. This sample is not a substitute for compliance with engineering standards.

-000 REFERENCE

7093 Ó

#### STATE OF NORTH CAROLINA

DEPARTMENT OF TRANSPORTATION **DIVISION OF HIGHWAYS** GEOTECHNICAL ENGINEERING UNIT

#### **CONTENTS**

<u>HEET NO.</u>	<u>DESCRIPTION</u>
1	TITLE SHEET
2	LEGEND (SOIL & ROCK)
2A	SUPPLEMENTAL LEGEND (GS
3	SITE PLAN
4-10	BORE LOG(S), CORE REPORT( & CORE PHOTOGRAPH(S)
II	SOIL TEST RESULTS
12	ROCK TEST RESULTS
13	SITE PHOTOGRAPH(S)

### **STRUCTURE** SUBSURFACE INVESTIGATION

COUNTY **ROCKINGHAM** 

PROJECT DESCRIPTION REPLACE BRIDGE 780035 ON NC 770 OVER MAYO RIVER

STATE PROJECT REFERENCE NO. BR-0093

#### **CAUTION NOTICE**

THE SUBSURFACE INFORMATION AND THE SUBSURFACE INVESTIGATION ON WHICH IT IS BASED WERE MADE FOR THE PURPOSE OF STUDY, PLANNING AND DESIGN, AND NOT FOR CONSTRUCTION OR PAY PURPOSES, THE VARIOUS FIELD BORING LOGS, ROCK CORES AND SOIL TEST DATA AVAILABLE MAY BE REVIEWED OR INSPECTED IN RALEIGH BY CONTACTING THE N. C. DEPARTMENT OF TRANSPORTATION, GEOTECHNICAL ENGINEERING UNIT AT 1919) 707-6850. THE SUBSURFACE PLANS AND REPORTS, FIELD BORING LOGS, ROCK CORES AND SOIL TEST DATA ARE NOT PART OF THE CONTRACT.

CENERAL SOIL AND ROCK STRATA DESCRIPTIONS AND INDICATED BOUNDARIES ARE BASED ON A GEOTECHNICAL INTERPRETATION OF ALL AVAILABLE SUBSURFACE DATA AND MAY NOT NECESSARILY REFLECT THE ACTUAL SUBSURFACE CONDITIONS BETWEEN BORINGS OR BETWEEN SAMPLED STRATA WITHIN THE BOREHOLE. THE LABDRATORY SAMPLE DATA AND THE IN SITU (IN-PLACE) TEST DATA CAN BE RELIED ON ONLY TO THE DEGREE OF RELIABILITY INHERENT IN THE STANDARD TEST METHOD. THE OBSERVED WATER LEVELS OR SOIL MOISTURE CONDITIONS NIDICATED IN THE SUBSURFACE INVESTIGATIONS ARE AS RECORDED AT THE TIME OF THE INVESTIGATION. THESE WATER LEVELS OR SOIL MOISTURE CONDITIONS MAY VARY CONSIDERABLY WITH TIME ACCORDING TO CLIMATIC CONDITIONS INCLUDING TEMPERATURES, PRECIPITATION AND WIND, AS WELL AS OTHER NON-CLIMATIC FACTORS.

THE BIDDER OR CONTRACTOR IS CAUTIONED THAT DETAILS SHOWN ON THE SUBSURFACE PLANS ARE PRELIMINARY ONLY AND IN MANY CASES THE FINAL DESIGN DETAILS ARE DIFFERENT. FOR BIDDING AND CONSTRUCTION PURPOSES, REFER TO THE CONSTRUCTION PLANS AND DOCUMENTS FOR FINAL DESIGN INFORMATION ON THIS PROJECT. THE DEPARTMENT DOES NOT WARRANT OR GUARANTEE THE SUFFICIENCY OR ACCURACY OF THE INVESTIGATION MADE, NOR THE INTERPRETATIONS MADE, OR OPINION OF THE DEPARTMENT AS TO THE TYPE OF MATERIALS AND CONDITIONS TO BE ENCOUNTERED. THE BIDDER OR CONTRACTOR IS CAUTIONED TO MAKE SUCH INDEPENDENT SUBSURFACE INVESTIGATIONS AS HE DEEMS NECESSARY TO SATISTY HIMSELF AS TO CONDITIONS TO BE ENCOUNTERED ON THE PROJECT. THE CONTRACTOR SHALL HAVE NO CLAIM FOR ADDITIONAL COMPENSATION OR FOR AN EXTENSION OF TIME FOR ANY REASON RESULTING FROM THE ACTUAL CONDITIONS FOOD THE PROJECT. THE SITE DIFFERING FROM THOSE INDICATED IN THE SUBSURFACE INFORMATION.

- NOTES:

  1. THE INFORMATION CONTAINED HEREIN IS NOT IMPLIED OR GUARANTEED BY THE N. C. DEPARTMENT OF TRANSPORTATION AS ACCURATE NOR IS IT CONSIDERED PART OF THE PLANS, SPECIFICATIONS OR CONTRACT FOR THE PROJECT.

  2. BY HAVING REQUESTED THIS INFORMATION, THE CONTRACTOR SPECIFICALLY WAIVES ANY CLAIMS FOR INCREASED COMPENSATION OR EXTENSION OF TIME BASED ON DIFFERENCES BETWEEN THE CONDITIONS INDICATED HEREIN AND THE ACTUAL CONDITIONS AT THE PROJECT SITE.

R. MAFFIA C. SWAFFORD CATLIN ENGINEERS

& SCIENTISTS


INVESTIGATED BY \_\_C. SWAFFORD

DRAWN BY \_C. SWAFFORD

SUBMITTED BY SCHNABEL ENG.

DATE **\_JUNE** 2023





PROJECT REFERENCE NO. SHEET NO. 2

# NORTH CAROLINA DEPARTMENT OF TRANSPORTATION DIVISION OF HIGHWAYS GEOTECHNICAL ENGINEERING UNIT

### SUBSURFACE INVESTIGATION

SOIL AND ROCK LEGEND, TERMS, SYMBOLS, AND ABBREVIATIONS

SOIL DESCRIPTION  SOIL IS CONSIDERED UNCONSOLIDATED, SEMI-CONSOLIDATED, OR WEATHERED EARTH MATERIALS THAT CAN	GRADATION  WELL CRADED - INDICATES A COOR REPRESENTATION OF PARTICLE SIZES FROM FINE TO COARSE	ROCK DESCRIPTION  HARD ROCK IS NON-COASTAL PLAIN MATERIAL THAT WOULD YIELD SPT REFUSAL IF TESTED. AN INFERRED	TERMS AND DEFINITIONS
BE PENETRATED WITH A CONTINUOUS FLIGHT POWER AUGER AND YIELD LESS THAN 100 BLOWS PER FOOT	<u>WELL GRADED</u> - INDICATES A GOOD REPRESENTATION OF PARTICLE SIZES FROM FINE TO COARSE. <u>UNIFORMLY GRADED</u> - INDICATES THAT SOIL PARTICLES ARE ALL APPROXIMATELY THE SAME SIZE.	ROCK LINE INDICATES THE LEVEL AT WHICH NON-COASTAL PLAIN MATERIAL WOULD YIELD SPT REFUSAL.	ALLUVIUM (ALLUV.) - SOILS THAT HAVE BEEN TRANSPORTED BY WATER.
ACCORDING TO THE STANDARD PENETRATION TEST (AASHTO T 206, ASTM DI586). SOIL CLASSIFICATION IS BASED ON THE AASHTO SYSTEM. BASIC DESCRIPTIONS GENERALLY INCLUDE THE FOLLOWING:	GAP-GRADED - INDICATES A MIXTURE OF UNIFORM PARTICLE SIZES OF TWO OR MORE SIZES.	SPT REFUSAL IS PENETRATION BY A SPLIT SPOON SAMPLER EQUAL TO OR LESS THAN 0.1 FOOT PER 60 BLOWS IN NON-COASTAL PLAIN MATERIAL. THE TRANSITION BETWEEN SOIL AND ROCK IS OFTEN	AGUIFER - A WATER BEARING FORMATION OR STRATA.  ARENACEOUS - APPLIED TO ROCKS THAT HAVE BEEN DERIVED FROM SAND OR THAT CONTAIN SAND.
CONSISTENCY, COLOR, TEXTURE, MOISTURE, AASHTO CLASSIFICATION, AND OTHER PERTINENT FACTORS SUCH AS MINERALOGICAL COMPOSITION, ANGULARITY, STRUCTURE, PLASTICITY, ETC. FOR EXAMPLE,	ANGULARITY OF GRAINS	REPRESENTED BY A ZONE OF WEATHERED ROCK.  ROCK MATERIALS ARE TYPICALLY DIVIDED AS FOLLOWS:	ARGILLACEOUS - APPLIED TO ALL ROCKS OR SUBSTANCES COMPOSED OF CLAY MINERALS, OR HAVING
VERY STIFF,GRAY, SILTY CLAY, MOIST WITH INTERBEDDED FINE SAND LAYERS, HIGHLY PLASTIC, A-7-6	THE ANGULARITY OR ROUNDNESS OF SOIL GRAINS IS DESIGNATED BY THE TERMS:	WEATHERED NON-COASTAL PLAIN MATERIAL THAT WOULD YIELD SPT N VALUES >	A NOTABLE PROPORTION OF CLAY IN THEIR COMPOSITION, SUCH AS SHALE, SLATE, ETC.
SOIL LEGEND AND AASHTO CLASSIFICATION	ANGULAR, SUBANGULAR, SUBROUNDED, OR ROUNDED.  MINERALOGICAL COMPOSITION	ROCK (WR) 100 BLOWS PER FOOT IF TESTED.	ARTESIAN - GROUND WATER THAT IS UNDER SUFFICIENT PRESSURE TO RISE ABOVE THE LEVEL AT
GENERAL GRANULAR MATERIALS SILT-CLAY MATERIALS ORGANIC MATERIALS CLASS. (≤ 35% PASSING *200) (> 35% PASSING *200) ORGANIC MATERIALS	MINERAL NAMES SUCH AS QUARTZ, FELDSPAR, MICA, TALC, KAQLIN, ETC.	CRYSTALLINE FINE TO COARSE GRAIN IGNEOUS AND METAMORPHIC ROCK THAT WOULD YIELD SPT REFUSAL IF TESTED. ROCK TYPE INCLUDES GRANITE,	WHICH IT IS ENCOUNTERED, BUT WHICH DOES NOT NECESSARILY RISE TO OR ABOVE THE GROUND SURFACE.
GROUP A-1 A-3 A-2 A-4 A-5 A-6 A-7 A-1, A-2 A-4, A-5	ARE USED IN DESCRIPTIONS WHEN THEY ARE CONSIDERED OF SIGNIFICANCE.	GNEISS, GABBRO, SCHIST, ETC.	CALCAREOUS (CALC.) - SOILS THAT CONTAIN APPRECIABLE AMOUNTS OF CALCIUM CARBONATE.
CLASS. A-1-0 A-1-6 A-2-4 A-2-5 A-2-6 A-2-7 A-7-5 A-3 A-6, A-7	COMPRESSIBILITY	NON-CRYSTALLINE FINE TO COARSE GRAIN METAMORPHIC AND NON-COASTAL PLAIN SEDIMENTARY ROCK THAT WOULD YELLD SPT REFUSAL IF TESTED.	COLLUVIUM - ROCK FRAGMENTS MIXED WITH SOIL DEPOSITED BY GRAVITY ON SLOPE OR AT BOTTOM
SYMBOL 0000d00000	SLIGHTLY COMPRESSIBLE LL < 31 MODERATELY COMPRESSIBLE LL = 31 - 50	ROCK (NCR)  ROCK TYPE INCLUDES PHYLLITE, SLATE, SANDSTONE, ETC.  COASTAL PLAIN  COASTAL PLAIN SEDIMENTS CEMENTED INTO ROCK, BUT MAY NOT YIELD	OF SLOPE.
7. PASSING	HIGHLY COMPRESSIBLE LL > 50	SEDIMENTARY ROCK SPT REFUSAL, ROCK TYPE INCLUDES LIMESTONE, SANDSTONE, CEMENTED	CORE RECOVERY (REC.) - TOTAL LENGTH OF ALL MATERIAL RECOVERED IN THE CORE BARREL DIVIDED BY TOTAL LENGTH OF CORE RUN AND EXPRESSED AS A PERCENTAGE.
*10 50 MX GRANULAR SILT MUCK, CLAY MUCK, SOILS PEAT	PERCENTAGE OF MATERIAL	CCP) SHELL BEDS, ETC.  WEATHERING	DIKE - A TABULAR BODY OF IGNEOUS ROCK THAT CUTS ACROSS THE STRUCTURE OF ADJACENT
#200   15 MX   25 MX   10 MX   35 MX   35 MX   35 MX   35 MX   36 MN   36 MN   36 MN   36 MN   36 MN	GRANULAR SILT - CLAY ORGANIC MATERIAL SOILS SOILS OTHER MATERIAL	FRESH ROCK FRESH, CRYSTALS BRIGHT, FEW JOINTS MAY SHOW SLIGHT STAINING, ROCK RINGS UNDER	ROCKS OR CUTS MASSIVE ROCK.
MATERIAL	TRACE OF ORGANIC MATTER 2 - 3% 3 - 5% TRACE 1 - 10% LITTLE ORGANIC MATTER 3 - 5% 5 - 12% LITTLE 10 - 20%	HAMMER IF CRYSTALLINE.	DIP - THE ANGLE AT WHICH A STRATUM OR ANY PLANAR FEATURE IS INCLINED FROM THE HORIZONTAL.
PASSING *40 LL - 40 MX 41 MN 4	MODERATELY ORGANIC 5 - 10% 12 - 20% SOME 20 - 35%	VERY SLIGHT ROCK GENERALLY FRESH, JOINTS STAINED, SOME JOINTS MAY SHOW THIN CLAY COATINGS IF OPEN, (V SLI.) CRYSTALS ON A BROKEN SPECIMEN FACE SHINE BRIGHTLY. ROCK RINGS UNDER HAMMER BLOWS IF	DIP DIRECTION (DIP AZIMUTH) - THE DIRECTION OR BEARING OF THE HORIZONTAL TRACE OF THE
PI 6 MX NP 10 MX 10 MX 11 MN 11 MN 10 MX 10 MX 11 MN 11 MN 11 MN MODERATE HIGHLY	HIGHLY ORGANIC > 10% > 20% HIGHLY 35% AND ABOVE	OF A CRYSTALLINE NATURE.	LINE OF DIP, MEASURED CLOCKWISE FROM NORTH.
GROUP INDEX 0 0 0 4 MX 8 MX 12 MX 16 MX NO MX AMOUNTS OF SOULS	GROUND WATER	SLIGHT ROCK GENERALLY FRESH, JOINTS STAINED AND DISCOLORATION EXTENDS INTO ROCK UP TO	FAULT - A FRACTURE OR FRACTURE ZONE ALONG WHICH THERE HAS BEEN DISPLACEMENT OF THE SIDES RELATIVE TO ONE ANOTHER PARALLEL TO THE FRACTURE.
USUAL TYPES STONE FRACS. OF MAIOR CRAYEL AND FINE SILTY OR CLAYEY SILTY CLAYEY MATTER	✓ WATER LEVEL IN BORE HOLE IMMEDIATELY AFTER DRILLING	(SLI.) 1 INCH. OPEN JOINTS MAY CONTAIN CLAY. IN GRANITOID ROCKS SOME OCCASIONAL FELDSPAR CRYSTALS ARE DULL AND DISCOLORED. CRYSTALLINE ROCKS RING UNDER HAMMER BLOWS.	FISSILE - A PROPERTY OF SPLITTING ALONG CLOSELY SPACED PARALLEL PLANES.
MATERIALS SAND SAND GRAVEL AND SAND SOILS SOILS	STATIC WATER LEVEL AFTER 24 HOURS	MODERATE SIGNIFICANT PORTIONS OF ROCK SHOW DISCOLORATION AND WEATHERING EFFECTS. IN	FLOAT - ROCK FRAGMENTS ON SURFACE NEAR THEIR ORIGINAL POSITION AND DISLODGED FROM
GEN.RATING EXCELLENT TO GOOD FAIR TO POOR FAIR TO POOR UNSUITABLE	∇ PW     PERCHED WATER, SATURATED ZONE, OR WATER BEARING STRATA	(MOD.) GRANITOID ROCKS, MOST FELDSPARS ARE DULL AND DISCOLORED, SOME SHOW CLAY. ROCK HAS DULL SOUND UNDER HAMMER BLOWS AND SHOWS SIGNIFICANT LOSS OF STRENGTH AS COMPARED	PARENT MATERIAL.
AS SUBURADE MUUR	SPRING OR SEEP	WITH FRESH ROCK.	FLOOD PLAIN (FP) - LAND BORDERING A STREAM, BUILT OF SEDIMENTS DEPOSITED BY THE STREAM.
PI OF A-7-5 SUBGROUP IS ≤ LL - 30 ;PI OF A-7-6 SUBGROUP IS > LL - 30  CONSISTENCY OR DENSENESS	-	MODERATELY ALL ROCK EXCEPT QUARTZ DISCOLORED OR STAINED, IN GRANITOID ROCKS, ALL FELDSPARS DULL	FORMATION (FM.) - A MAPPABLE GEOLOGIC UNIT THAT CAN BE RECOGNIZED AND TRACED IN THE FIELD.
PANCE OF CTANDARD PANCE OF LINCONFINED	MISCELLANEOUS SYMBOLS	SEVERE AND DISCOLORED AND A MAJORITY SHOW KAOLINIZATION. ROCK SHOWS SEVERE LOSS OF STRENGTH (MOD. SEV.) AND CAN BE EXCAVATED WITH A GEOLOGIST'S PICK. ROCK GIVES "CLUNK" SOUND WHEN STRUCK.	JOINT - FRACTURE IN ROCK ALONG WHICH NO APPRECIABLE MOVEMENT HAS OCCURRED.
PRIMARY SOIL TYPE COMPACTIVES OF PENETRATION RESISTENCE COMPRESSIVE STRENGTH	ROADWAY EMBANKMENT (RE) 25/025 DIP & DIP DIRECTION	<u>IF TESTED, WOULD YIELD SPT REFUSAL</u>	LEDGE - A SHELF-LIKE RIDGE OR PROJECTION OF ROCK WHOSE THICKNESS IS SMALL COMPARED TO
UN-VHLUEZ (TUNSZET )	WITH SOIL DESCRIPTION OF ROCK STRUCTURES	SEVERE ALL ROCK EXCEPT QUARTZ DISCOLORED OR STAINED, ROCK FABRIC CLEAR AND EVIDENT BUT (SEV.) REDUCED IN STRENGTH TO STRONG SOIL. IN GRANITOID ROCKS ALL FELDSPARS ARE KAOLINIZED	ITS LATERAL EXTENT.
GENERALLY VERY LOOSE	SOIL SYMBOL  SOIL SYMBOL  SLOPE INDICATOR INSTALLATION	TO SOME EXTENT. SOME FRAGMENTS OF STRONG ROCK USUALLY REMAIN.	LENS - A BODY OF SOIL OR ROCK THAT THINS OUT IN ONE OR MORE DIRECTIONS.
MATERIAL MEDIUM DENSE 10 10 30 N/A	ARTIFICIAL FILL (AF) OTHER AUGER BORING CONE PENETROMETER	IF TESTED, WOULD YIELD SPT N VALUES > 100 BPF  VERY  ALL ROCK EXCEPT QUARTZ DISCOLORED OR STAINED, ROCK FABRIC ELEMENTS ARE DISCERNIBLE	MOTTLED (MOT.) - IRREGULARLY MARKED WITH SPOTS OF DIFFERENT COLORS. MOTTLING IN SOILS USUALLY INDICATES POOR AERATION AND LACK OF GOOD DRAINAGE.
(NON-COHESIVE) VERY DENSE > 50	THAN ROADWAY EMBANKMENT THOUGH BUTTING TEST	VERY ALL ROCK EXCEPT QUARTZ DISCOLORED OR STAINED. ROCK FABRIC ELEMENTS ARE DISCERNIBLE SEVERE BUT MASS IS EFFECTIVELY REDUCED TO SOIL STATUS, WITH ONLY FRAGMENTS OF STRONG ROCK	PERCHED WATER - WATER MAINTAINED ABOVE THE NORMAL GROUND WATER LEVEL BY THE PRESENCE
VERY SOFT < 2 < 0.25	— INFERRED SOIL BOUNDARY — CORE BORING ■ SOUNDING ROD	(V SEV.) REMAINING. SAPROLITE IS AN EXAMPLE OF ROCK WEATHERED TO A DEGREE THAT ONLY MINOR VESTIGES OF ORIGINAL ROCK FABRIC REMAIN. <i>IF TESTED, WOULD YIELD SPT N VALUES &lt; 100 BPE</i>	OF AN INTERVENING IMPERVIOUS STRATUM.
GENERALLY SOFT 2 TO 4 0.25 TO 0.5 SILT-CLAY MEDIUM STIFF 4 TO 8 0.5 TO 1.0	INFERRED ROCK LINE MN MONITORING WELL TEST BORING	COMPLETE ROCK REDUCED TO SOIL, ROCK FABRIC NOT DISCERNIBLE, OR DISCERNIBLE ONLY IN SMALL AND	RESIDUAL (RES.) SOIL - SOIL FORMED IN PLACE BY THE WEATHERING OF ROCK.
MATERIAL STIFF 8 TO 15 1 TO 2	A PIEZOMETER	SCATTERED CONCENTRATIONS. QUARTZ MAY BE PRESENT AS DIKES OR STRINGERS. SAPROLITE IS	ROCK QUALITY DESIGNATION (ROD) - A MEASURE OF ROCK QUALITY DESCRIBED BY TOTAL LENGTH OF ROCK SEGMENTS EQUAL TO OR GREATER THAN 4 INCHES DIVIDED BY THE TOTAL LENGTH OF CORE
(COHESIVE) VERY STIFF 15 TO 30 2 TO 4 HARD > 30 > 4	TTTTT ALLUVIAL SOIL BOUNDARY ALLUVIAL SOIL BOUNDARY SPT N-VALUE	ALSO AN EXAMPLE.	RUN AND EXPRESSED AS A PERCENTAGE.
TEXTURE OR GRAIN SIZE	RECOMMENDATION SYMBOLS	ROCK HARDNESS  VERY HARD CANNOT BE SCRATCHED BY KNIFE OR SHARP PICK, BREAKING OF HAND SPECIMENS REQUIRES	SAPROLITE (SAP.) - RESIDUAL SOIL THAT RETAINS THE RELIC STRUCTURE OR FABRIC OF THE PARENT ROCK.
U.S. STD. SIEVE SIZE 4 10 40 60 200 270	UNCLASSIFIED EXCAVATION - UNCLASSIFIED EXCAVATION -	SEVERAL HARD BLOWS OF THE GEOLOGIST'S PICK.	SILL - AN INTRUSIVE BODY OF IGNEOUS ROCK OF APPROXIMATELY UNIFORM THICKNESS AND
OPENING (MM) 4.76 2.00 0.42 0.25 0.075 0.053	The state of the s	HARD CAN BE SCRATCHED BY KNIFE OR PICK ONLY WITH DIFFICULTY, HARD HAMMER BLOWS REQUIRED	RELATIVELY THIN COMPARED WITH ITS LATERAL EXTENT, THAT HAS BEEN EMPLACED PARALLEL TO THE BEDDING OR SCHISTOSITY OF THE INTRUDED ROCKS.
BOULDER COBBLE GRAVEL COARSE FINE SILT CLAY	SHALLOW UNCLASSIFIED EXCAVATION - UNDERCUT UNCLASSIFIED EXCAVATION - EMBANKMENT OR BACKFILL	TO DETACH HAND SPECIMEN.  MODERATELY CAN BE SCRATCHED BY KNIFE OR PICK, GOUGES OR GROOVES TO 0.25 INCHES DEEP CAN BE	SLICKENSIDE - POLISHED AND STRIATED SURFACE THAT RESULTS FROM FRICTION ALONG A FAULT
(BLDR.) (COB.) (GR.) (CSE. SD.) (F SD.) (SL.) (CL.)	ABBREVIATIONS	HARD EXCAVATED BY HARD BLOW OF A GEOLOGIST'S PICK. HAND SPECIMENS CAN BE DETACHED	OR SLIP PLANE.
GRAIN MM 305 75 2.0 0.25 0.05 0.005	AR - AUGER REFUSAL MED MEDIUM VST - VANE SHEAR TEST BT - BORING TERMINATED MICA MICACEOUS WEA WEATHERED	BY MODERATE BLOWS.	STANDARD PENETRATION TEST (PENETRATION RESISTANCE) (SPT) - NUMBER OF BLOWS (N OR BPF) OF A 140 LB, HAMMER FALLING 30 INCHES REQUIRED TO PRODUCE A PENETRATION OF 1 FOOT INTO SOIL
SIZE IN. 12 3	CL CLAY MOD MODERATELY 7 - UNIT WEIGHT	MEDIUM CAN BE GROOVED OR GOUGED 0.05 INCHES DEEP BY FIRM PRESSURE OF KNIFE OR PICK POINT.  HARD CAN BE EXCAVATED IN SMALL CHIPS TO PEICES 1 INCH MAXIMUM SIZE BY HARD BLOWS OF THE	WITH A 2 INCH OUTSIDE DIAMETER SPLIT SPOON SAMPLER. SPT REFUSAL IS PENETRATION EQUAL
SOIL MOISTURE - CORRELATION OF TERMS	CPT - CONE PENETRATION TEST NP - NON PLASTIC $\gamma_{ m d}$ - DRY UNIT WEIGHT	POINT OF A GEOLOGIST'S PICK.	TO OR LESS THAN 0.1 FOOT PER 60 BLOWS.
SOIL MOISTURE SCALE FIELD MOISTURE GUIDE FOR FIELD MOISTURE DESCRIPTION  (ATTERBERG LIMITS) DESCRIPTION	CSE COARSE ORG ORGANIC  DMT - DILATOMETER TEST PMT - PRESSUREMETER TEST SAMPLE ABBREVIATIONS	SOFT CAN BE GROVED OR GOUGED READILY BY KNIFE OR PICK. CAN BE EXCAVATED IN FRAGMENTS FROM CHIPS TO SEVERAL INCHES IN SIZE BY MODERATE BLOWS OF A PICK POINT. SMALL, THIN	STRATA CORE RECOVERY (SREC.) - TOTAL LENGTH OF STRATA MATERIAL RECOVERED DIVIDED BY TOTAL LENGTH OF STRATUM AND EXPRESSED AS A PERCENTAGE.
- SATURATED - USUALLY LIQUID; VERY WET, USUALLY	DPT - DYNAMIC PENETRATION TEST SAP SAPROLITIC S - BULK e - VOID RATIO SD SAND, SANDY SS - SPLIT SPOON	PIECES CAN BE BROKEN BY FINGER PRESSURE.	STRATA ROCK QUALITY DESIGNATION (SRQD) - A MEASURE OF ROCK QUALITY DESCRIBED BY TOTAL
(SAT.) FROM BELOW THE GROUND WATER TABLE	F - FINE SL SILT, SILTY ST - SHELBY TUBE	VERY CAN BE CARVED WITH KNIFE. CAN BE EXCAVATED READILY WITH POINT OF PICK, PIECES 1 INCH SOFT OR MORE IN THICKNESS CAN BE BROKEN BY FINGER PRESSURE. CAN BE SCRATCHED READILY BY	LENGTH OF ROCK SEGMENTS WITHIN A STRATUM EQUAL TO OR GREATER THAN 4 INCHES DIVIDED BY THE TOTAL LENGTH OF STRATA AND EXPRESSED AS A PERCENTAGE.
PLASTIC CEMICOLID DEPUBLIC TO	FOSS FOSSILIFEROUS SLI SLIGHTLY RS - ROCK FRAC FRACTURED, FRACTURES TCR - TRICONE REFUSAL RT - RECOMPACTED TRIAXIAL	FINGERNALL.	TOPSOIL (TS.) - SURFACE SOILS USUALLY CONTAINING ORGANIC MATTER.
RANGE - WET - (W) SEMISOLIDE REGUIRES DRYING TO	FRAGS FRAGMENTS	FRACTURE SPACING BEDDING	BENCH MARK: BL-4 N:991691.81E:1720281.74
(P) PL PLASTIC LIMIT ATTAIN OPTIMUM MOISTURE	HI HIGHLY V - VERY RATIO	TERM         SPACING         TERM         THICKNESS           VERY WIDE         MORE THAN 10 FEET         VERY THICKLY BEDDED         4 FEET	
OM OPTIMUM MOISTURE - MOIST - (M) SOLID; AT OR NEAR OPTIMUM MOISTURE	EQUIPMENT USED ON SUBJECT PROJECT  DRILL UNITS: ADVANCING TOOLS: HAMMER TYPE:	WIDE 3 TO 10 FEET THICKLY BEDDED 1.5 - 4 FEET	ELEVATION: 678.66 FEET
SL SHRINKAGE LIMIT	CME-45C CLAY BITS TAUTOMATIC MANUAL	MODERATELY CLOSE 1 TO 3 FEET THINLY BEDDED 0.16 - 1.5 FEET CLOSE 0.16 TO 1 FOOT VERY THINLY BEDDED 0.03 - 0.16 FEET	NOTES:
- DRY - (D) REQUIRES ADDITIONAL WATER TO ATTAIN OPTIMUM MOISTURE	6. CONTINUOUS ELICHT AUGER	VERY CLOSE LESS THAN 0.16 FEET THICKLY LAMINATED 0.008 - 0.03 FEET	FIAD - FILLED IMMEDIATELY AFTER DRILLING
	X CME-55	THINLY LAMINATED < 0.008 FEET  INDURATION	- PAVEMENT / ABC STONE
PLASTICITY		FOR SEDIMENTARY ROCKS, INDURATION IS THE HARDENING OF MATERIAL BY CEMENTING, HEAT, PRESSURE, ETC.	- LI TAVEMENT / ADO STONE
PLASTICITY INDEX (PI)         DRY STRENGTH           NON PLASTIC         0-5         VERY LOW	CME-550 HARD FACED FINGER BITS  TUNGCARBIDE INSERTS	DIDDING WITH FINCED EDEES NUMEDOUG CRAINS.	
SLIGHTLY PLASTIC 6-15 SLIGHT	VANE SHEAR TEST X CASING W/ ADVANCER HAND TOOLS:	FRIABLE GENTLE BLOW BY HAMMER DISINTEGRATES SAMPLE.	
MODERATELY PLASTIC 16-25 MEDIUM HIGHLY PLASTIC 26 OR MORE HIGH	POST HOLE DIGGER	MODERATELY INDURATED  GRAINS CAN BE SEPARATED FROM SAMPLE WITH STEEL PROBE;  PROMO EACH VALUE HAMMER	
COLOR	PORTABLE HOIST X TRICONE 3 1/4 STEEL TEETH HAND AUGER TRICONE TUNG-CARB. SQUANDING POR	BREAKS EASILY WHEN HIT WITH HAMMER.  GRAINS ARE DIFFICULT TO SEPARATE WITH STEEL PROBE:	
	SUNDING NOD	INDURATED DIFFICULT TO BREAK WITH HAMMER.	
DESCRIPTIONS MAY INCLUDE COLOR OR COLOR COMBINATIONS (TAN, RED, YELLOW-BROWN, BLUE-GRAY).  MODIFIERS SUCH AS LIGHT, DARK, STREAKED, ETC. ARE USED TO DESCRIBE APPEARANCE.	X CORE BIT VANE SHEAR TEST	EXTREMELY INDURATED SHARP HAMMER BLOWS REQUIRED TO BREAK SAMPLE;	
HOSE TENS SOOT AS ETSTIT, DANKES THERED, ETS, ARE USED TO DESCRIBE AFTERNAMICE.		SAMPLE BREAKS ACROSS GRAINS.	DATE: 8-15-1-


PROJECT REFERENCE NO.	SHEET NO.
BR-0093	2A


#### NORTH CAROLINA DEPARTMENT OF TRANSPORTATION **DIVISION OF HIGHWAYS** GEOTECHNICAL ENGINEERING UNIT


#### SUBSURFACE INVESTIGATION

#### SUPPLEMENTAL LEGEND, GEOLOGICAL STRENGTH INDEX (GSI) TABLES

FROM AASHTO LRFD BRIDGE DESIGN SPECIFICATIONS AASHTO LRFD Figure 10.4.6.4-1 — Determination of GSI for Jointed Rock Mass (Marinos and Hoek, 2000) AASHTO LRFD Figure 10.4.6.4-2 — Determination of GSI for Tectonically Deformed Heterogeneous Rock Masses (Marinos and Hoek, 2000) GEOLOGICAL STRENGTH INDEX (GSI) FOR GSI FOR HETEROGENEOUS ROCK MASSES SUCH JOINTED ROCKS (Hoek and Marinos, 2000) AS FLYSCH (Marinos. P and Hoek E., 2000) staın From a description of the lithology, structure and occasionally es with compact with angular From the lithology, structure and surface POOR - Very smooth, slicken-l or highly weathered surfaces soft clay coatings or fillings conditions of the discontinuities, estimate the average value of GSI. Do not try to athered sur or fillings surface conditions (particularly of the bedding planes), choose a box in the chart. Locate the planes) be too precise. Quoting a range from 33 to 37 is more realistic than stating that position in the box that corresponds to the condition ered of the discontinuities and estimate the average value GSI = 35. Note that the table does not of GSI from the contours. Do not attempt to be too eq. apply to structurally controlled failures. Where weak planar structural planes are precise. Quoting a range from 33 to 37 is more realistic than giving GSI = 35. Note that the slightlypresent in an unfavorable orientation RACE CONDITIONS CONTINUITIES Hoek-Brown criterion does not apply to structurally with respect to the excavation face. highly coatin agment these will dominate the rock mass controlled failures. Where unfavourably oriented behaviour. The shear strength of surfaces continuous weak planar discontinuities are present, in rocks that are prone to deterioration slightly es these will dominate the behaviour of the rock mass. nsided, k ompact yular fra as a result of changes in moisture The strength of some rock masses is reduced by the 7 content will be reduced if water is 600D rough, presence of groundwater and this can be allowed for present. When working with rocks in the by a slight shift to the right in the columns for fair, fair to very poor categories, a shift to th, ed GOOD -surface: GOOD Rough, s surface poor and very poor conditions. Water pressure does the right may be made for wet conditions. FAIR weath VERY VERY sided with VERY Very FAIR Smoo-alter VERY Slick With Water pressure is dealt with by effective not change the value of GSI and it is dealt with by stress analysis. using effective stress analysis. DECREASING SURFACE QUALITY COMPOSITION AND STRUCTURE STRUCTURE INTACT OR MASSIVE - intact A. Thick bedded, very blocky sandstone .90 rock specimens or massive in 7Ó N/A N/A The effect of pelitic coatings on the bedding planes is minimized by the confinement of situ rock with few widely spaced discontinuities the rock mass. In shallow tunnels or slopes these bedding planes may cause structurally 80 controlled instability. PIE 60 BLOCKY - well interlocked un-70<sup>′</sup> disturbed rock mass consisting of cubical blocks formed by three D. Siltstone B. Sand-stone wi thin inte intersecting discontinuity sets MANA E. Weak 50 C. Sand-60 or silty shale stone with stone and siltstone /E thin inter siltstone with sandor clayey /B С lauers of stone lauers ın sımılar Shale with VERY BLOCKY - interlocked, sands tone siltstone amounts 40 partially disturbed mass with 50 multi-faceted angular blocks formed by 4 or more joint sets INTERL(  $\textbf{C}_{\bullet} \; \textbf{D}_{\bullet} \; \textbf{E}_{\bullet} \; \text{and} \; \textbf{G} \; \text{-} \; \text{may be more or}$ F. Tectonically deformed. BLOCKY/DISTURBED/SEAMY -30 less folded than illustrated but intensively folded/faulted, folded with angular blocks this does not change the strength. sheared clayey shale or siltstone formed by many intersecting Tectonic deformation, faulting and with broken and deformed DECREASING loss of continuity moves these discontinuity sets. Persistence sandstone layers forming an 30 categories to F and H. of bedding planes or schistosity almost chaotic structure 20 DISINTEGRATED - poorly interlocked, heavily broken rock mass 20 G. Undisturbed silty H. Tectonically deformed silty with mixture of angular and or clayey shale with or clayey shale forming a 10 rounded rock pieces chaotic structure with pockets or without a few very of clay. Thin layers of thin sandstone layers sandstone are transformed into small rock pieces. 10 LAMINATED/SHEARED - Lack of N/A N/A blockiness due to close spacing of weak schistosity or shear planes → Means deformation after tectonic disturbance







#### **CORE PHOTOGRAPH REPLACE BRIDGE 780035 ON NC 770 OVER MAYO RIVER**

B1-A **BOX 1 OF 2: 3.1 - 13.1 FEET** 


APPROXIMATE SCALE IN FEET

B1-A **BOX 2 OF 2: 13.1 - 23.1 FEET** 




APPROXIMATE SCALE IN FEET

		BORE LOG										
<b>WBS</b> 67093.1.1					<b>WBS</b> 67093				JNTY ROCKINGHAM	GEOLOGIST Sv		
· ·	DESCRIPTION Replace Bridge 780035 On NC 770 Over Mayo River  GROUND WTR (ft)		-			ridge 780035 On NC 770 Over M	<del>- '   </del>			GROUND WTR (		
BORING NO. B1-B	STATION 17+12	OFFSET 5 ft RT	ALIGNMENT -L-	<b>0 HR</b> . N/A	BORING NO	. B2-A		STATION 18+23	OFFSET 11 ft LT	ALIGNMENT -L-	•	<b>0 HR.</b> N
COLLAR ELEV. 638.4 ft	TOTAL DEPTH 6.0 ft	NORTHING 991,696		<b>24 HR</b> . N/A	COLLAR EL			TOTAL DEPTH 5.0 ft	<b>NORTHING</b> 991,746	EASTING 1,720		4 HR. N
	CAT4425 CME-55 84% 04/01/2023	DRILL METHOD M	lud Rotary HAMMI	ER TYPE Automatic				AT4425 CME-55 84% 04/01/2023	<del></del>	IOD Mud Rotary	HAMME	R TYPE Automation
DRILLER Edmondson, J. N		COMP. DATE 04/26/23	SURFACE WATER DEPTH 1.8	8ft	DRILLER E			<b>START DATE</b> 04/26/23	COMP. DATE 04/26/2	3 SURFACE WATE	R DEPTH 2.0f	t
(ft) ELEV (ft) 0.5ft (	7 COUNT BLOWS PER FOO 0.5ft 0.5ft 0 25 50	75 100 NO. MOI G		DEPTH (ft)	ELEV CHICAGO	DEPTH_ (ft)	BLOW COU	I	75 100 NO. M	OI G	ND ROCK DESCR	
640					640					F 638 3	ER SURFACE (04/ BROUND SURFAC	— — —
636.2 2.2 100/0.2 633.0 5.4 60/0.0 60/0.0		· · 100/0.2	- 638.4 GROUND SURFA - 636.4 Very loose to loose, gray, SA - 633.0 Gray, GNEISS, mica - 632.4 CRYSTALLINE RC Gray, GNEISS, mica - Boring Terminated with Penetration Test Refusal at E ft In Crystalline Rock (C  Deck to mudline: 3  Total casing: 42.  Drill bit refusal at 6.0	AND (A-3), with 2.0  OCK aceous 5.4  OCK aceous Standard Elevation 632.4  GNEISS)  7.8 ft 0 ft	635 4 633.3	T 5.0	60/0.0			635.8 Very loose to train trai	ALLUVIAL ALL	ND (A-3), with nica
NCDOT BORE DOUBLE BR-0093_ASDRILLED_FINAL.GPJ NC_DOT.GDT 6/22/23												




## CORE PHOTOGRAPH REPLACE BRIDGE 780035 ON NC 770 OVER MAYO RIVER


B2-B BOX 1 OF 2: 4.1 - 13.1 FEET



B2-B BOX 2 OF 2: 13.1 - 23.1 FEET



APPROXIMATE SCALE IN FEET



PROJECT REFERENCE NO.	SHEET NO.
BR-0093	11

	SOIL TEST RESULTS															
BORING ID	SAMPLE NO.	OFFSET	STATION	DEPTH INTERVAL	AASHTO CLASS.	L.L.	P.I.	C.SAND	% BY F.SAND	WEIGHT SILT	CLAY	% PAS	$\frac{SSING}{40}$ (S	IEVES)	% MOISTURE	% ORGANIC
EB 1- A	SS- 25	7' LT	16 +23	27.8-29.3	A-6(6)	35	14	8.7	<i>38.</i> 8	24. 1	28. 5	100	97	6 1	26	-
EB 1- A	SS- 26	7' LT	16 +23	32. 8- 34. 3	A-4(1)	33	4	11.2	45. 3	29. 3	14. 1	99	94	53	32	-
EB 1- B	SS- 15	8' RT	16 +26	28. 4- 29. 9	A-6(5)	33	12	7.8	40.8	24.4	27.0	95	93	57	25	-
EB2-B	SS-7	7' RT	19 +25	28.7-30.3	A-4(0)	28	3	4.4	58.9	22. 5	14. 2	100	100	47	32	-

\_\_\_

\_\_

\_\_\_

\_\_

\_\_\_

\_

REPORT ON SAMPLES OF: Rock for Quality (ASTM D 7012-14e1 Method C)

T.I.P. ID NO.: BR-0093

DESCRIPTION: Replace Bridge 780035 On NC 770 Over Mayo River
PROJECT: BR-0093
COUNTY: Rockingham

DATE SAMPLED: 4/25/2023

BORING NO	SAMPLE NO	DEPTH (FT)	ROCK TYPE	LENGTH (IN)	DIAMETER (IN)	UNIT WEIGHT (PCF)	UNCONFINED COMPRESSIVE STRENGTH (PSI)	YOUNG'S MODULUS (PSI)	SPLITTING TENSILE STRENGTH (PSI)	REMARKS
B1-A-b	RS-1	9.5-10.2	Gneiss	4.59	1.99	165.9	5,940			
B1-A-b	RS-2	19.6-20.4	Gneiss	4.58	1.99	167.9	12,150	-		
B2-B	RS-3	8.1-9.1	Gneiss	4.55	1.99	165.5	3,690	1		
B2-B	RS-4	15.6-16.3	Gneiss	4.33	1.99	164.9	7,280	1		

# SITE PHOTOGRAPH REPLACE BRIDGE 780035 ON NC 770 OVER MAYO RIVER





