

DOT SITE INSPECTION REPORT

MITIGATION SITE NAME Little Ivy Creek (Barnhill Site)	TIP # A-0010WM	WBS # 34634.2.13	INSPECTION DATE 10/21/2019
--	-------------------	---------------------	-------------------------------

COUNTY Madison	# ACRES 2.77
-------------------	-----------------

MONITORING ORGANIZATION NCDOT	INSPECTOR Gordon Marsh	PHONE 919-878-9560	EMAIL ADDRESS gmarsh@rkk.com
----------------------------------	---------------------------	-----------------------	---------------------------------

INSPECTION ACTIVITIES: <i>Complete all that apply. Describe location of visited areas if <100%.</i>			
Walked boundaries	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> N/A
Walked road frontage	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> N/A
Walked trails / roads	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> N/A
Walked interior	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> N/A
Monitored from air	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> N/A
Condition of boundaries	<input checked="" type="checkbox"/> GOOD <input type="checkbox"/> FAIR <input type="checkbox"/> POOR		
COMMENTS: Site in good condition.			

WHICH NATURAL ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION?
Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.

<input type="checkbox"/> FLOODING	<input type="checkbox"/> FIRE	<input type="checkbox"/> STORM	<input type="checkbox"/> EARTH MOVEMENT
<input type="checkbox"/> INVASIVE EXOTIC VEGETATION	<input type="checkbox"/> INSECT INFESTATION	<input type="checkbox"/> ANIMAL ACTIVITY	<input type="checkbox"/> OTHER ACTIVITIES/ CHANGES? (Please Explain)
<input checked="" type="checkbox"/> NO CHANGE			
EXPLAIN: Japanese knotweed observed.			

DOT SITE INSPECTION REPORT

WHICH MANMADE ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING?

Check all that apply. Note location and extent. Document with photos.

<input type="checkbox"/> NEW STRUCTURE / CONSTRUCTION	<input type="checkbox"/> DUMPING OR STORING	<input type="checkbox"/> NEW TRAILS OR ROADS
<input type="checkbox"/> TIMBER HARVEST/ VEGETATIVE CUTTING	<input type="checkbox"/> EXCAVATION (DREDGING, FILLING, GRADING, MINING)	<input type="checkbox"/> ALTERATION TO DRAINAGE PATTERNS/WATER QUALITY
<input type="checkbox"/> SUBDIVISION	<input type="checkbox"/> INDUSTRIAL, RESIDENTIAL, OR COMMERCIAL USE	<input type="checkbox"/> LAND CLEARING
<input type="checkbox"/> MOTORIZED VEHICLE DAMAGE	<input type="checkbox"/> TRESPASS/VANDALISM	<input type="checkbox"/> AGRICULTURAL USE
<input type="checkbox"/> ENCROACHMENT FROM ADJACENT PROPERTY	<input type="checkbox"/> ACTIVITY ON ABUTTING LAND	<input type="checkbox"/> OTHER ACTIVITIES / CHANGES? <i>(Please Explain)</i>
<input checked="" type="checkbox"/> NO CHANGE		

EXPLAIN:
 No changes observed.

REQUEST FOLLOW-UP BY PROGRAM MANAGER FOR POSSIBLE VIOLATIONS.

☐ YES ☒ NO

Were corrective actions completed for previous inspection(s)?	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> N/A	EXPLAIN:
Are you aware of any plans that may affect property?	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		EXPLAIN:
Are there concerns about boundaries by adjacent property owners?	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		EXPLAIN:
Are there changes in land use on adjacent property?	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		EXPLAIN:
Are deed restrictions being adhered to?	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		EXPLAIN:
If new property owner, do they have a written copy of the restrictions?	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> N/A	

ATTACHMENTS:

1) MAP OF PERMANENT PHOTO PLOTS
 2) PHOTOGRAPHS WITH CAPTIONS
 3) MAP AND PHOTOGRAPHS WITH CAPTIONS OF RELEVANT NATURAL AND MANMADE ACTIVITIES
 4) OTHER (SPECIFY)

1 - Site View



2 - Site View



3 - Site View



**NCDOT
Stewardship Program Mitigation
Site Reviews**

Project Name:
A-10 Barnhill Tract
TIP No. A-0010
Division No. 13
County: Madison

November 2019



Lat/Long: 35.801445, -82.530792