

DOT SITE INSPECTION REPORT

MITIGATION SITE NAME Mud Creek	TIP # A-0010WM	WBS # 34634.2.14	INSPECTION DATE 9/30/15
--	--------------------------	----------------------------	-----------------------------------

COUNTY Henderson	# ACRES 39.13
----------------------------	-------------------------

MONITORING ORGANIZATION NCDOT	INSPECTOR Pete Stafford, Hal Bain	PHONE 919-878-9560	EMAIL ADDRESS pstafford@rkk.com
---	---	------------------------------	---

INSPECTION ACTIVITIES: <i>Complete all that apply. Describe location of visited areas if <100%.</i>			
Walked boundaries ☐ YES ☐ NO ☐ N/A	Walked trails / roads ☒ YES ☐ NO ☐ N/A		
Walked road frontage ☒ YES ☐ NO ☐ N/A	Walked interior ☒ YES ☐ NO ☐ N/A		
Monitored from air ☐ YES ☐ NO ☒ N/A			
Condition of boundaries ☒ GOOD ☐ FAIR ☐ POOR			
COMMENTS: Significant amount of dumping onsite. See map.			

WHICH NATURAL ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION?
Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.

☐ FLOODING	☐ FIRE	☐ STORM	☐ EARTH MOVEMENT
☐ INVASIVE EXOTIC VEGETATION	☐ INSECT INFESTATION	☐ ANIMAL ACTIVITY	☐ OTHER ACTIVITIES/ CHANGES? <i>(Please Explain)</i>
☒ NO CHANGE			
EXPLAIN: No change from previous year.			

DOT SITE INSPECTION REPORT

WHICH MANMADE ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING?

Check all that apply. Note location and extent. Document with photos.

☐ NEW STRUCTURE / CONSTRUCTION	☒ DUMPING OR STORING	☐ NEW TRAILS OR ROADS
☐ TIMBER HARVEST/ VEGETATIVE CUTTING	☐ EXCAVATION (DREDGING, FILLING, GRADING, MINING)	☐ ALTERATION TO DRAINAGE PATTERNS/WATER QUALITY
☐ SUBDIVISION	☐ INDUSTRIAL, RESIDENTIAL, OR COMMERCIAL USE	☐ LAND CLEARING
☐ MOTORIZED VEHICLE DAMAGE	☐ TRESPASS/VANDALISM	☐ AGRICULTURAL USE
☐ ENCROACHMENT FROM ADJACENT PROPERTY	☐ ACTIVITY ON ABUTTING LAND	☐ OTHER ACTIVITIES / CHANGES? <i>(Please Explain)</i>
☒ NO CHANGE		


EXPLAIN:
 Several dumping sites were observed.

REQUEST FOLLOW-UP BY PROGRAM MANAGER FOR POSSIBLE VIOLATIONS.	☐ YES	☒ NO
--	------------------------------	--

Were corrective actions completed for previous inspection(s)?	☐ YES	☐ NO	EXPLAIN:
		☒ N/A	
Are you aware of any plans that may affect property?	☐ YES	☒ NO	EXPLAIN:
Are there concerns about boundaries by adjacent property owners?	☐ YES	☒ NO	EXPLAIN:
Are there changes in land use on adjacent property?	☐ YES	☒ NO	EXPLAIN:
Are deed restrictions being adhered to?	☒ YES	☐ NO	EXPLAIN:
If new property owner, do they have a written copy of the restrictions?	☐ YES	☐ NO	
		☒ N/A	

ATTACHMENTS:

1) MAP OF PERMANENT PHOTO PLOTS
 2) PHOTOGRAPHS WITH CAPTIONS
 3) MAP AND PHOTOGRAPHS WITH CAPTIONS OF RELEVANT NATURAL AND MANMADE ACTIVITIES
 4) OTHER (SPECIFY)



1 - Site Overview



2 - Dumping



3 - Dumping



4 - Site Overview



NCDOT
Stewardship Program Mitigation
Site Reviews
Project Name: Mud Creek
TIP No. A-0010WM
Division No. 14
County: Henderson



November 2015



0 300 600 900 1,200 Feet

Lat/Long: 35.370367, -82.473861