

# SOUTH FORK BIG PINE CREEK – CHARLES/MCGINNIS INSPECTION REPORT

MITIGATION SITE NAME South Fork Big Pine Creek – Charles/McGinnis	TIP # A-10WM	WBS # 34634.2.13	INSPECTION DATE 5/14/14
--	-----------------	---------------------	----------------------------

COUNTY Madison	# ACRES 1.11
-------------------	-----------------

MONITORING ORGANIZATION NCDOT	INSPECTOR RWG/BGM	PHONE (919) 707-6121	EMAIL ADDRESS rgriffin@ncdot.gov
----------------------------------	----------------------	-------------------------	-------------------------------------

<b>INSPECTION ACTIVITIES:</b> <i>Complete all that apply. Describe location of visited areas if &lt;100%.</i>			
Walked boundaries	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> N/A
Walked trails / roads	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> N/A
Walked road frontage	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> N/A
Walked interior	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> N/A
Monitored from air	<input type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> N/A
Condition of boundaries	<input type="checkbox"/> GOOD	<input type="checkbox"/> FAIR	<input type="checkbox"/> POOR
<b>COMMENTS:</b> Majority of site looks good. There has been some cutting along existing utility easements. There has also been cutting adjacent to field next to greenhouse. NCDOT will contact WRC for consultation with owner about easement restrictions.			

**WHICH NATURAL ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION?**  
*Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.*

<input type="checkbox"/> FLOODING	<input type="checkbox"/> FIRE	<input type="checkbox"/> STORM	<input type="checkbox"/> EARTH MOVEMENT
<input checked="" type="checkbox"/> INVASIVE EXOTIC VEGETATION	<input type="checkbox"/> INSECT INFESTATION	<input type="checkbox"/> ANIMAL ACTIVITY	<input type="checkbox"/> OTHER ACTIVITIES/ CHANGES? (Please Explain)
<input checked="" type="checkbox"/> NO CHANGE			
<b>EXPLAIN:</b> Honeysuckle, knotweed noted			

## SOUTH FORK BIG PINE CREEK – CHARLES/MCGINNIS INSPECTION REPORT

### WHICH MANMADE ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING?

*Check all that apply. Note location and extent. Document with photos.*

<input type="checkbox"/> NEW STRUCTURE / CONSTRUCTION	<input type="checkbox"/> DUMPING OR STORING	<input type="checkbox"/> NEW TRAILS OR ROADS
<input checked="" type="checkbox"/> TIMBER HARVEST/ VEGETATIVE CUTTING	<input type="checkbox"/> EXCAVATION (DREDGING, FILLING, GRADING, MINING)	<input type="checkbox"/> ALTERATION TO DRAINAGE PATTERNS/WATER QUALITY
<input type="checkbox"/> SUBDIVISION	<input type="checkbox"/> INDUSTRIAL, RESIDENTIAL, OR COMMERCIAL USE	<input type="checkbox"/> LAND CLEARING
<input type="checkbox"/> MOTORIZED VEHICLE DAMAGE	<input type="checkbox"/> TRESPASS/VANDALISM	<input type="checkbox"/> AGRICULTURAL USE
<input type="checkbox"/> ENCROACHMENT FROM ADJACENT PROPERTY	<input type="checkbox"/> ACTIVITY ON ABUTTING LAND	<input checked="" type="checkbox"/> OTHER ACTIVITIES / CHANGES? <i>(Please Explain)</i>
<input type="checkbox"/> NO CHANGE		

#### EXPLAIN:

Fork Mountain Farms reported the utility company spraying along the stream and their property in 2013  
Cutting within easement


#### REQUEST FOLLOW-UP BY PROGRAM MANAGER FOR POSSIBLE VIOLATIONS.

☒ YES

☐ NO

Were corrective actions completed for previous inspection(s)?	<input type="checkbox"/> YES  <input checked="" type="checkbox"/> N/A	<input type="checkbox"/> NO	<b>EXPLAIN:</b>
Are you aware of any plans that may affect property?	<input type="checkbox"/> YES  <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> NO	<b>EXPLAIN:</b>
Are there concerns about boundaries by adjacent property owners?	<input type="checkbox"/> YES  <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> NO	<b>EXPLAIN:</b>
Are there changes in land use on adjacent property?	<input type="checkbox"/> YES  <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> NO	<b>EXPLAIN:</b>
Are deed restrictions being adhered to?	<input type="checkbox"/> YES  <input checked="" type="checkbox"/> NO	<input checked="" type="checkbox"/> NO	<b>EXPLAIN:</b> CUTTING WITHIN EASEMENT
If new property owner, do they have a written copy of the restrictions?	<input type="checkbox"/> YES  <input checked="" type="checkbox"/> N/A	<input type="checkbox"/> NO	
<b>ATTACHMENTS:</b>			
1) MAP OF PERMANENT PHOTO PLOTS 2) PHOTOGRAPHS WITH CAPTIONS 3) MAP AND PHOTOGRAPHS WITH CAPTIONS OF RELEVANT NATURAL AND MANMADE ACTIVITIES 4) OTHER (SPECIFY)			

# **SOUTH FORK BIG PINE CREEK – CHARLES/MCGINNIS INSPECTION REPORT**





# **SOUTH FORK BIG PINE CREEK – CHARLES/MCGINNIS INSPECTION REPORT**





# **SOUTH FORK BIG PINE CREEK – CHARLES/MCGINNIS INSPECTION REPORT**





# **SOUTH FORK BIG PINE CREEK – CHARLES/MCGINNIS INSPECTION REPORT**





# **SOUTH FORK BIG PINE CREEK – CHARLES/MCGINNIS INSPECTION REPORT**





D:\GIS\Projects\000166\_NorthCarolinaDeptofTransportation\0217597\_NCDOTStewardshipMonitoring\#9\map\_docs\mxd\working\18\_Charles\_McGinnis\_Site (SouthFork Big Pine Creek).mxd | Last Updated: 10.18.2013



**South Fork Big Pine Creek - Charles / McGinnis Site**