

SUNSET BEACH BRIDGE INSPECTION REPORT

MITIGATION SITE NAME Sunset Beach Bridge	TIP # B-0682	WBS # N/A	INSPECTION DATE Sept-23-2016
---	-----------------	--------------	---------------------------------

COUNTY Brunswick	# ACRES 1.5
---------------------	----------------

MONITORING ORGANIZATION KCI for NCDOT	INSPECTOR AF/TS	PHONE (919) 783-9214	EMAIL ADDRESS alex.french@kci.com
--	--------------------	-------------------------	--------------------------------------

INSPECTION ACTIVITIES: <i>Complete all that apply. Describe location of visited areas if <100%.</i>			
Walked boundaries <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> N/A	Walked trails / roads <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> N/A		
Walked road frontage <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> N/A	Walked interior <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> N/A		
Monitored from air <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> N/A			
Condition of boundaries <input checked="" type="checkbox"/> GOOD <input type="checkbox"/> FAIR <input type="checkbox"/> POOR 			
COMMENTS: Site remains in excellent condition. No signs of trespass or dumping were observed. No NCDOT signage was visible at time of site visit.			

WHICH NATURAL ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION?
Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.

<input type="checkbox"/> FLOODING	<input type="checkbox"/> FIRE	<input type="checkbox"/> STORM	<input type="checkbox"/> EARTH MOVEMENT
<input type="checkbox"/> INVASIVE EXOTIC VEGETATION	<input type="checkbox"/> INSECT INFESTATION	<input type="checkbox"/> ANIMAL ACTIVITY	<input type="checkbox"/> OTHER ACTIVITIES/ CHANGES? <i>(Please Explain)</i>
<input checked="" type="checkbox"/> NO CHANGE			
COMMENTS:			

SUNSET BEACH BRIDGE INSPECTION REPORT

WHICH MANMADE ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING?

Check all that apply. Note location and extent. Document with photos.

<input type="checkbox"/> NEW STRUCTURE / CONSTRUCTION	<input type="checkbox"/> DUMPING OR STORING	<input type="checkbox"/> NEW TRAILS OR ROADS
<input type="checkbox"/> TIMBER HARVEST/ VEGETATIVE CUTTING	<input type="checkbox"/> EXCAVATION (DREDGING, FILLING, GRADING, MINING)	<input type="checkbox"/> ALTERATION TO DRAINAGE PATTERNS/WATER QUALITY
<input type="checkbox"/> SUBDIVISION	<input type="checkbox"/> INDUSTRIAL, RESIDENTIAL, OR COMMERCIAL USE	<input type="checkbox"/> LAND CLEARING
<input type="checkbox"/> MOTORIZED VEHICLE DAMAGE	<input type="checkbox"/> TRESPASS/VANDALISM	<input type="checkbox"/> AGRICULTURAL USE
<input type="checkbox"/> ENCROACHMENT FROM ADJACENT PROPERTY	<input type="checkbox"/> ACTIVITY ON ABUTTING LAND	<input type="checkbox"/> OTHER ACTIVITIES / CHANGES? <i>(Please Explain)</i>
<input checked="" type="checkbox"/> NO CHANGE		
EXPLAIN:		
REQUEST FOLLOW-UP BY PROGRAM MANAGER FOR POSSIBLE VIOLATIONS. <div style="float: right; text-align: right;"> <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO </div>		

Were corrective actions completed for previous inspection(s)? <input type="checkbox"/> YES <input type="checkbox"/> NO	EXPLAIN:
Are you aware of any plans that may affect property? <input type="checkbox"/> YES <input checked="" type="checkbox"/> N/A	EXPLAIN:
Are there concerns about boundaries by adjacent property owners? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	EXPLAIN:
Are there changes in land use on adjacent property? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	EXPLAIN:
Are deed restrictions being adhered to? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	EXPLAIN:
If new property owner, do they have a written copy of the restrictions? <input type="checkbox"/> YES <input type="checkbox"/> NO	EXPLAIN:
<input checked="" type="checkbox"/> N/A	
ATTACHMENTS:	
1) PHOTOGRAPHS WITH CAPTIONS 2) MAP AND PHOTOGRAPHS OF RELEVANT NATURAL AND MANMADE ACTIVITIES	

SUNSET BEACH BRIDGE INSPECTION REPORT



Photo 1 – View of western side of site.



Photo 2 – View of eastern side of site.



● Photo Point

➡➡➡ Inspection Route

☐ Sunset Beach Bridge Project Site



NCDOT
Stewardship Program Mitigation
Site Reviews
Project Name: Sunset Beach Bridge
Division No. 3
County: Brunswick

250 125 0 250 Feet

Map Created: August 2016
Image Source: NC Statewide
Orthoimagery, 2012