

THOROFARE BAY BRIDGE INSPECTION REPORT

MITIGATION SITE NAME Thoroughfare Bay Bridge	TIP # B-1098	WBS # N/A	INSPECTION DATE Oct-16-2017
-------------------------------------------------	-----------------	--------------	--------------------------------

COUNTY	# ACRES
Carteret	3.35

MONITORING ORGANIZATION KCI for NCDOT	INSPECTOR KOB/TS	PHONE (919) 783-9214	EMAIL ADDRESS tommy.seelinger@kci.com
------------------------------------------	---------------------	-------------------------	------------------------------------------

INSPECTION ACTIVITIES: <i>Complete all that apply. Describe location of visited areas if <100%.</i>			
Walked boundaries	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> N/A
Walked road frontage	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> N/A
Monitored from air	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> N/A
Condition of boundaries	<input checked="" type="checkbox"/> GOOD	<input type="checkbox"/> FAIR	<input type="checkbox"/> POOR
COMMENTS: NCDOT signs were present and visible and there are no signs of trespass on the site.			

WHICH NATURAL ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION?

Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.

<input type="checkbox"/> FLOODING	<input type="checkbox"/> FIRE	<input type="checkbox"/> STORM	<input type="checkbox"/> EARTH MOVEMENT
<input type="checkbox"/> INVASIVE EXOTIC VEGETATION	<input type="checkbox"/> INSECT INFESTATION	<input type="checkbox"/> ANIMAL ACTIVITY	<input type="checkbox"/> OTHER ACTIVITIES/ CHANGES? <i>(Please Explain)</i>
			<input checked="" type="checkbox"/> NO CHANGE

COMMENTS:

THOROFARE BAY BRIDGE INSPECTION REPORT

WHICH MANMADE ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING?

Check all that apply. Note location and extent. Document with photos.

<input type="checkbox"/> NEW STRUCTURE / CONSTRUCTION	<input type="checkbox"/> DUMPING OR STORING	<input type="checkbox"/> NEW TRAILS OR ROADS
<input type="checkbox"/> TIMBER HARVEST/ VEGETATIVE CUTTING	<input type="checkbox"/> EXCAVATION (DREDGING, FILLING, GRADING, MINING)	<input type="checkbox"/> ALTERATION TO DRAINAGE PATTERNS/WATER QUALITY
<input type="checkbox"/> SUBDIVISION	<input type="checkbox"/> INDUSTRIAL, RESIDENTIAL, OR COMMERCIAL USE	<input type="checkbox"/> LAND CLEARING
<input type="checkbox"/> MOTORIZED VEHICLE DAMAGE	<input type="checkbox"/> TRESPASS/VANDALISM	<input type="checkbox"/> AGRICULTURAL USE
<input type="checkbox"/> ENCROACHMENT FROM ADJACENT PROPERTY	<input type="checkbox"/> ACTIVITY ON ABUTTING LAND	<input type="checkbox"/> OTHER ACTIVITIES / CHANGES? <i>(Please Explain)</i>
<input checked="" type="checkbox"/> NO CHANGE		

EXPLAIN:

**REQUEST FOLLOW-UP BY PROGRAM MANAGER
FOR POSSIBLE VIOLATIONS.**

☐ YES

☒ NO

Were corrective actions completed for previous inspection(s)? <div style="float: right;"> <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> N/A </div>	EXPLAIN:
Are you aware of any plans that may affect property? <div style="float: right;"> <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO </div>	EXPLAIN:
Are there concerns about boundaries by adjacent property owners? <div style="float: right;"> <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO </div>	EXPLAIN:
Are there changes in land use on adjacent property? <div style="float: right;"> <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO </div>	EXPLAIN:
Are deed restrictions being adhered to? <div style="float: right;"> <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO </div>	EXPLAIN:
If new property owner, do they have a written copy of the restrictions? <div style="float: right;"> <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> N/A </div>	EXPLAIN:

ATTACHMENTS:

- 1) PHOTOGRAPHS WITH CAPTIONS
- 2) MAP AND PHOTOGRAPHS OF RELEVANT NATURAL AND MANMADE ACTIVITIES

THOROFARE BAY BRIDGE INSPECTION REPORT





Photo 1 – View into northeastern portion of site.


THOROFARE BAY BRIDGE INSPECTION REPORT




Photo 2- View into southern portion of site.





 Photo Point

 Inspection Route

 Northeast Creek Bridge Project Site



NCDOT
Stewardship Program Mitigation
Site Reviews
Project Name: Northeast Creek Bridge
Division No. 3
County: Onslow



400 200 0 400 Feet

Map Created: October 2017
Image Source: NC Statewide
Orthoimagery, 2016