

## DOT SITE INSPECTION REPORT

MITIGATION SITE NAME Spring Branch Bridge	TIP # B-2059	ONE ID # 065-008	INSPECTION DATE 6/23/2020
--	-----------------	---------------------	------------------------------

COUNTY New Hanover	# ACRES 0.12
-----------------------	-----------------

MONITORING ORGANIZATION NCDOT	INSPECTOR Matt Martin	PHONE 919-878-9560	EMAIL ADDRESS mmartin@rkk.com
----------------------------------	--------------------------	-----------------------	----------------------------------

<b>INSPECTION ACTIVITIES:</b> <i>Complete all that apply. Describe location of visited areas if &lt;100%.</i>			
Walked boundaries <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> N/A	Walked trails / roads <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> N/A		
Walked road frontage <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> N/A	Walked interior <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> N/A		
Monitored from air <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> N/A			
Condition of boundaries <span style="float: right;"><input checked="" type="checkbox"/> GOOD <input type="checkbox"/> FAIR <input type="checkbox"/> POOR</span>			
<b>COMMENTS:</b> No natural or manmade changes observed. Site in good condition at time of inspection.			

**WHICH NATURAL ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION?**  
*Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.*

<input type="checkbox"/> FLOODING	<input type="checkbox"/> FIRE	<input type="checkbox"/> STORM	<input type="checkbox"/> EARTH MOVEMENT
<input type="checkbox"/> INVASIVE EXOTIC VEGETATION	<input type="checkbox"/> INSECT INFESTATION	<input type="checkbox"/> ANIMAL ACTIVITY	<input type="checkbox"/> OTHER ACTIVITIES/ CHANGES? <i>(Please Explain)</i>
<input checked="" type="checkbox"/> NO CHANGE			
<b>EXPLAIN:</b> No natural changes observed.			

## DOT SITE INSPECTION REPORT

### WHICH MANMADE ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING?

*Check all that apply. Note location and extent. Document with photos.*

<input type="checkbox"/> NEW STRUCTURE / CONSTRUCTION	<input type="checkbox"/> DUMPING OR STORING	<input type="checkbox"/> NEW TRAILS OR ROADS
<input type="checkbox"/> TIMBER HARVEST/ VEGETATIVE CUTTING	<input type="checkbox"/> EXCAVATION (DREDGING, FILLING, GRADING, MINING)	<input type="checkbox"/> ALTERATION TO DRAINAGE PATTERNS/WATER QUALITY
<input type="checkbox"/> SUBDIVISION	<input type="checkbox"/> INDUSTRIAL, RESIDENTIAL, OR COMMERCIAL USE	<input type="checkbox"/> LAND CLEARING
<input type="checkbox"/> MOTORIZED VEHICLE DAMAGE	<input type="checkbox"/> TRESPASS/VANDALISM	<input type="checkbox"/> AGRICULTURAL USE
<input type="checkbox"/> ENCROACHMENT FROM ADJACENT PROPERTY	<input type="checkbox"/> ACTIVITY ON ABUTTING LAND	<input type="checkbox"/> OTHER ACTIVITIES / CHANGES? <i>(Please Explain)</i>
<input checked="" type="checkbox"/> NO CHANGE		

#### EXPLAIN:

No manmade changes observed.

#### REQUEST FOLLOW-UP BY PROGRAM MANAGER FOR POSSIBLE VIOLATIONS.

☐ YES

☒ NO

Were corrective actions  
completed for previous  
inspection(s)? ☐ YES ☒ NO ☐ N/A

#### EXPLAIN:

Are you aware of any plans  
that may affect property? ☐ YES ☒ NO

#### EXPLAIN:

Are there concerns about  
boundaries by adjacent  
property owners? ☐ YES ☒ NO

#### EXPLAIN:

Are there changes in land use  
on adjacent property? ☐ YES ☒ NO

#### EXPLAIN:

Are deed restrictions being  
adhered to? ☒ YES ☐ NO

#### EXPLAIN:

If new property owner, do  
they have a written copy of  
the restrictions? ☐ YES ☐ NO ☒ N/A

#### ATTACHMENTS:

- 1) MAP OF PERMANENT PHOTO PLOTS
- 2) PHOTOGRAPHS WITH CAPTIONS
- 3) MAP AND PHOTOGRAPHS WITH CAPTIONS OF RELEVANT NATURAL AND MANMADE ACTIVITIES
- 4) OTHER (SPECIFY)




1 - Site View



2 - Site View



3 - Site View



**Legend**

➤ Site Track

4 - Site View



5 - Site View



**NCDOT  
Stewardship Program Mitigation  
Site Reviews**

Project Name:  
Spring Branch Bridge  
TIP No. B-2059  
Division No. 3  
County: New Hanover

August 2020

