

DOT SITE INSPECTION REPORT

MITIGATION SITE NAME Murray's Mill	TIP # R-2119	WBS # 34634.2.12	INSPECTION DATE 9/17/2019
--	------------------------	----------------------------	-------------------------------------

COUNTY Catawba	# ACRES 33.35
--------------------------	-------------------------

MONITORING ORGANIZATION NCDOT	INSPECTOR Matt Martin	PHONE 919-878-9560	EMAIL ADDRESS mmartin@rkk.com
---	---------------------------------	------------------------------	---

INSPECTION ACTIVITIES: <i>Complete all that apply. Describe location of visited areas if <100%.</i>			
Walked boundaries <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> N/A	Walked trails / roads <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> N/A		
Walked road frontage <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> N/A	Walked interior <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> N/A		
Monitored from air <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> N/A			
Condition of boundaries <div style="display: inline-block; margin-left: 100px;"> <input checked="" type="checkbox"/> GOOD <input type="checkbox"/> FAIR <input type="checkbox"/> POOR </div>			
COMMENTS: No changes. Site is in good condition.			

WHICH NATURAL ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION?
Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.

<input type="checkbox"/> FLOODING	<input type="checkbox"/> FIRE	<input type="checkbox"/> STORM	<input type="checkbox"/> EARTH MOVEMENT
<input checked="" type="checkbox"/> INVASIVE EXOTIC VEGETATION	<input type="checkbox"/> INSECT INFESTATION	<input type="checkbox"/> ANIMAL ACTIVITY	<input type="checkbox"/> OTHER ACTIVITIES/ CHANGES? <i>(Please Explain)</i>
<input type="checkbox"/> NO CHANGE			
EXPLAIN: Japanese honeysuckle			

DOT SITE INSPECTION REPORT

WHICH MANMADE ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING?

Check all that apply. Note location and extent. Document with photos.

<input type="checkbox"/> NEW STRUCTURE / CONSTRUCTION	<input type="checkbox"/> DUMPING OR STORING	<input type="checkbox"/> NEW TRAILS OR ROADS
<input type="checkbox"/> TIMBER HARVEST/ VEGETATIVE CUTTING	<input type="checkbox"/> EXCAVATION (DREDGING, FILLING, GRADING, MINING)	<input type="checkbox"/> ALTERATION TO DRAINAGE PATTERNS/WATER QUALITY
<input type="checkbox"/> SUBDIVISION	<input type="checkbox"/> INDUSTRIAL, RESIDENTIAL, OR COMMERCIAL USE	<input type="checkbox"/> LAND CLEARING
<input type="checkbox"/> MOTORIZED VEHICLE DAMAGE	<input type="checkbox"/> TRESPASS/VANDALISM	<input type="checkbox"/> AGRICULTURAL USE
<input type="checkbox"/> ENCROACHMENT FROM ADJACENT PROPERTY	<input type="checkbox"/> ACTIVITY ON ABUTTING LAND	<input type="checkbox"/> OTHER ACTIVITIES / CHANGES? <i>(Please Explain)</i>
<input checked="" type="checkbox"/> NO CHANGE		

EXPLAIN:
 No changes observed.

REQUEST FOLLOW-UP BY PROGRAM MANAGER FOR POSSIBLE VIOLATIONS.

☐ YES ☒ NO

Were corrective actions completed for previous inspection(s)? <div style="float: right;"> <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> N/A </div>	EXPLAIN:
Are you aware of any plans that may affect property? <div style="float: right;"> <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO </div>	EXPLAIN:
Are there concerns about boundaries by adjacent property owners? <div style="float: right;"> <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO </div>	EXPLAIN:
Are there changes in land use on adjacent property? <div style="float: right;"> <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO </div>	EXPLAIN:
Are deed restrictions being adhered to? <div style="float: right;"> <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO </div>	EXPLAIN:
If new property owner, do they have a written copy of the restrictions? <div style="float: right;"> <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> N/A </div>	

ATTACHMENTS:

1) MAP OF PERMANENT PHOTO PLOTS
 2) PHOTOGRAPHS WITH CAPTIONS
 3) MAP AND PHOTOGRAPHS WITH CAPTIONS OF RELEVANT NATURAL AND MANMADE ACTIVITIES
 4) OTHER (SPECIFY)


1 - Site View



2 - Site View



3 - Site View



4 - Site View



5 - Site View



**NCDOT
Stewardship Program Mitigation
Site Reviews**

Project Name:
Murray's Mill
TIP No. B-2119
Division No. 12
County: Catawba

November 2019

