## **GREENE STREET BRIDGE INSPECTION REPORT**

MITIGATION SITE NAME Greene Street Bridge	TIP # R-1023WM		ONE 074-	E ID# -003	INSPECTION DATE August 30, 2019			
COUNTY Pitt					# ACRES 3.10			
MONITORING ORGANIZATION KCI for NCDOT		INSPECTOR TS/KOB		Рноме (919) 783-9214		EMAIL ADDRESS tommy.seelinger@kci.com		
<b>INSPECTION ACTIVITIES:</b> Complete all that apply. Describe location of visited areas if <100%.								
Walked boundaries XES	NO [	] N/A	Walked tra	ails / roads	YES	NO N/A		
Walked road frontage XES	NO	] N/A	Walked in	terior	YES	No N/A		
Monitored from air YES	No [	N/A						
Condition of boundaries			GOOD	FAIR P	OOR			
<b>COMMENTS:</b> No signs of trespass o location.	or dumping	observed	d. Access to	) the site is e	extremely 1	imited due to its		

**WHICH NATURAL ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION?** *Check all that apply. Note location and extent. Wherever possible, note species of concern. Document* 

.1 1 .	
with photos.	
n un photos.	

FLOODING	Fire	STORM	EARTH MOVEMENT
Invasive Exotic Vegetation	INSECT INFESTATION	ANIMAL ACTIVITY	OTHER ACTIVITIES/ CHANGES? (Please Explain)
COMMENTS:			

## **GREENE STREET BRIDGE INSPECTION REPORT**

WHICH MANMADE ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING?

Check all that apply. Note location and extent. Document with photos.						
NEW STRUCTURE / CONSTRUCTION	DUMPING OR STORING			NEW TRAILS OR ROADS		
TIMBER HARVEST/ VEGETATIVE CUTTING	EXCAVATION (DREDGING, FILLING, GRADING, MINING)			ALTERATION TO DRAINAGE PATTERNS/WATER QUALITY		
SUBDIVISION	INDUSTRIAL, RESIDENTIAL, OR COMMERCIAL USE			LAND CLEARING		
MOTORIZED VEHICLE DAMAGE	TRESPASS/VANDALISM			AGRICULTURAL USE		
ENCROACHMENT FROM ADJACENT PROPERTY	ACTIVITY ON ABUTTING LAND			OTHER ACTIVITIES / CHANGES? (Please Explain)		
				NO CHANGE		
EXPLAIN:						
<b>R</b> EQUEST FOLLOW-UP BY <b>P</b> ROGRAM <b>M</b> ANAGER FOR POSSIBLE VIOLATIONS.			YES	No		
Were corrective actions		No	EXPLAIN:			
completed for previous	YES					
inspection(s)?		N/A				
Are you aware of any plans that may affect property?	YES	No	EXPLAIN:			
Are there concerns about			EXPLAIN:			
boundaries by adjacent property owners?	YES	No				
Are there changes in land us on adjacent property?	e 🗌 YES	No	EXPLAIN:			
Are deed restrictions being adhered to?	YES	No	EXPLAIN:			
If new property owner, do they have a written copy of the restrictions?	YES	No				
	L I ES	N/A				
ATTACHMENTS:						
1) PHOTOGRAPHS WITH CAPTIONS 2) MAP AND PHOTOGRAPHS OF RELEVANT NATURAL AND MANMADE ACTIVITIES						

## **GREENE STREET BRIDGE INSPECTION REPORT**



Photo 1 – View into northern end of site from Greene St.



Photo 2 – View into southern end of site from Greene St.

