STELLA BRIDGE SITE INSPECTION REPORT

MITIGATION SITE NAME	TIP #	WBS #	INSPECTION DATE
Stella Bridge	B-2938	N/A	10/27/2014

COUNTY	# ACRES
Onslow	2.11

MONITORING ORGANIZATION	INSPECTOR	PHONE	EMAIL ADDRESS
Kimley-Horn	RLS/JLY	(919) 677-2104	ross.sullivan@kimley-horn.com

INSPECTION ACTIVITIES: *Complete all that apply. Describe location of visited areas if <100%.*

Walked boundaries	☐ YES	☒ NO	☐ N/A	Walked trails / roads	☐ YES ☒ NO ☐ N/A
Walked road frontage	☒ YES	☐ NO	☐ N/A	Walked interior	☐ YES ☒ NO ☐ N/A
Monitored from air	☐ YES	☐ NO	☒ N/A		
Condition of boundaries	☒ GOOD	☐ FAIR	☐ POOR		

COMMENTS: The site remains in excellent condition. There are no significant changes from the previous report. There continues to be mowing at western end of site despite the "No Mowing" sign and rip rap barrier (see Photo 1).

WHICH NATURAL ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION?
Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.

☐ FLOODING	☐ FIRE	☐ STORM	☐ EARTH MOVEMENT
☐ INVASIVE EXOTIC VEGETATION	☐ INSECT INFESTATION	☐ ANIMAL ACTIVITY	☐ OTHER ACTIVITIES/ CHANGES? *(Please Explain)*
			☒ NO CHANGE

EXPLAIN:
No significant natural activities/changes were observed during the site visit.

STELLA BRIDGE SITE INSPECTION REPORT

WHICH MANMADE ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING?
Check all that apply. Note location and extent. Document with photos.

☐ NEW STRUCTURE / CONSTRUCTION	☐ DUMPING OR STORING	☐ NEW TRAILS OR ROADS
☒ TIMBER HARVEST/ VEGETATIVE CUTTING	☐ EXCAVATION (DREDGING, FILLING, GRADING, MINING)	☐ ALTERATION TO DRAINAGE PATTERNS/WATER QUALITY
☐ SUBDIVISION	☐ INDUSTRIAL, RESIDENTIAL, OR COMMERCIAL USE	☐ LAND CLEARING
☐ MOTORIZED VEHICLE DAMAGE	☐ TRESPASS/VANDALISM	☐ AGRICULTURAL USE
☐ ENCROACHMENT FROM ADJACENT PROPERTY	☐ ACTIVITY ON ABUTTING LAND	☐ OTHER ACTIVITIES / CHANGES? *(Please Explain)*
		☒ NO CHANGE

EXPLAIN:
Mowing has occurred on the site at the western end of the property boundary.

REQUEST FOLLOW-UP BY PROGRAM MANAGER FOR POSSIBLE VIOLATIONS. ☐ YES ☒ NO

Were corrective actions completed for previous inspection(s)?	☐ YES	☐ NO ☒ N/A	**EXPLAIN:**
Are you aware of any plans that may affect property?	☐ YES	☒ NO	**EXPLAIN:**
Are there concerns about boundaries by adjacent property owners?	☐ YES	☒ NO	**EXPLAIN:**
Are there changes in land use on adjacent property?	☐ YES	☒ NO	**EXPLAIN:**
Are deed restrictions being adhered to?	☒ YES	☐ NO	**EXPLAIN:**
If new property owner, do they have a written copy of the restrictions?	☐ YES	☐ NO ☒ N/A	

ATTACHMENTS:

1) SITE PHOTOGRAPHS WITH CAPTIONS
2) SITE MAP

SITE PHOTOGRAPHS

Photo 1 – Looking east into the site from the western boundary. Note that someone has mowed around the "No Spray/No Mow" sign.

Photo 2 – Interior view of the site from Stella Road.

Photo 3 – Interior view of the site from Stella Road.

Photo 4 – Interior view of the site from Stella Road.

Division 3 -Stella Bridge
NCDOT Site Inspection Program
Onslow County, North Carolina
November 2014