SOUTH RIVER BRIDGE INSPECTION REPORT

MITIGATION SITE NAME	TIP #	WBS #	INSPECTION DATE
South River Bridge	B-3152	34634.2.6	9/16/2014

COUNTY	# ACRES
Sampson	0.25

MONITORING ORGANIZATION	INSPECTOR	PHONE	EMAIL ADDRESS
HDR for NCDOT	SE / VM	919-785-1118	vickie.miller@hdrinc.com

INSPECTION ACTIVITIES: *Complete all that apply. Describe location of visited areas if <100%.*

Walked boundaries	☒ YES	☐ NO	☐ N/A	Walked trails / roads	☐ YES	☒ NO	☐ N/A
Walked road frontage	☒ YES	☐ NO	☐ N/A	Walked interior	☐ YES	☒ NO	☐ N/A
Monitored from air	☐ YES	☒ NO	☐ N/A				

Condition of boundaries ☒ GOOD ☐ FAIR ☐ POOR

COMMENTS: The site is in good condition. No trespass issues were noted. The site was partially flooded during the inspection.

WHICH NATURAL ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION?
Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.

☒ FLOODING	☐ FIRE	☐ STORM	☐ EARTH MOVEMENT
☐ INVASIVE EXOTIC VEGETATION	☐ INSECT INFESTATION	☐ ANIMAL ACTIVITY	☐ OTHER ACTIVITIES/ CHANGES? *(Please Explain)*
			☐ NO CHANGE

EXPLAIN: A portion of the site was underwater during the visit.

SOUTH RIVER BRIDGE INSPECTION REPORT

WHICH MANMADE ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING?
Check all that apply. Note location and extent. Document with photos.

☐ NEW STRUCTURE / CONSTRUCTION	☐ DUMPING OR STORING	☐ NEW TRAILS OR ROADS
☐ TIMBER HARVEST/ VEGETATIVE CUTTING	☐ EXCAVATION (DREDGING, FILLING, GRADING, MINING)	☐ ALTERATION TO DRAINAGE PATTERNS/WATER QUALITY
☐ SUBDIVISION	☐ INDUSTRIAL, RESIDENTIAL, OR COMMERCIAL USE	☐ LAND CLEARING
☐ MOTORIZED VEHICLE DAMAGE	☐ TRESPASS/VANDALISM	☐ AGRICULTURAL USE
☐ ENCROACHMENT FROM ADJACENT PROPERTY	☐ ACTIVITY ON ABUTTING LAND	☐ OTHER ACTIVITIES / CHANGES? *(Please Explain)*
		☒ NO CHANGE

EXPLAIN: No change. Silt fence still remains in place at this site.

REQUEST FOLLOW-UP BY PROGRAM MANAGER FOR POSSIBLE VIOLATIONS. ☐ YES ☒ NO

Were corrective actions completed for previous inspection(s)?	☐ YES	☐ NO ☒ N/A	**EXPLAIN:**
Are you aware of any plans that may affect property?	☐ YES	☒ NO	**EXPLAIN:**
Are there concerns about boundaries by adjacent property owners?	☐ YES	☒ NO	**EXPLAIN:**
Are there changes in land use on adjacent property?	☐ YES	☒ NO	**EXPLAIN:**
Are deed restrictions being adhered to?	☒ YES	☐ NO	**EXPLAIN:**
If new property owner, do they have a written copy of the restrictions?	☐ YES	☐ NO ☒ N/A	

ATTACHMENTS:

1) MAP
2) PHOTOGRAPHS WITH CAPTIONS

View of the site from the northern boundary looking south.

View of the site from the southern boundary on the bridge looking north. Note the flooding of the site.

View of the site from the southern boundary on the bridge looking north. Note the flooding of the site.

Internal view of the site to the north of the bridge.

D:\GISProjects\000166_NorthCarolinaDeptofTransportation\0238152_NCDOTStewardshipMonitor(c)\map_docs\mxd\working\South River Bridge.mxd | Last Updated: 09.29.2014

South River Bridge Site