

## BAILEY FORK CREEK INSPECTION REPORT

|  |       |                     |                            |
|--|-------|---------------------|----------------------------|
| MITIGATION SITE NAME<br>Bailey Fork - WRC Site | TIP # | WBS #<br>34634.2.11 | INSPECTION DATE<br>5/14/14 |
|--|-------|---------------------|----------------------------|

|                 |         |
|-----------------|---------|
| COUNTY<br>Burke | # ACRES |
|-----------------|---------|

|                                  |                      |                         |                                     |
|----------------------------------|----------------------|-------------------------|-------------------------------------|
| MONITORING ORGANIZATION<br>NCDOT | INSPECTOR<br>BGM/RWG | PHONE<br>(919) 707-6121 | EMAIL ADDRESS<br>rgriffin@ncdot.gov |
|----------------------------------|----------------------|-------------------------|-------------------------------------|

|   |  |  |   |
|---|--|--|---|
| <b>INSPECTION ACTIVITIES:</b> <i>Complete all that apply. Describe location of visited areas if &lt;100%.</i>   |  |  |   |
| Walked boundaries   | <input checked="" type="checkbox"/> YES  | <input type="checkbox"/> NO            | <input type="checkbox"/> N/A            |
| Walked trails / roads   | <input type="checkbox"/> YES             | <input checked="" type="checkbox"/> NO | <input type="checkbox"/> N/A            |
| Walked road frontage  | <input checked="" type="checkbox"/> YES  | <input type="checkbox"/> NO            | <input type="checkbox"/> N/A            |
| Walked interior   | <input type="checkbox"/> YES             | <input checked="" type="checkbox"/> NO | <input type="checkbox"/> N/A            |
| Monitored from air  | <input type="checkbox"/> YES             | <input type="checkbox"/> NO            | <input checked="" type="checkbox"/> N/A |
| Condition of boundaries   | <input checked="" type="checkbox"/> GOOD | <input type="checkbox"/> FAIR          | <input type="checkbox"/> POOR           |
| <b>COMMENTS:</b> Site looks good; no cutting noted within marked boundary, overhead existing powerlines evident |  |  |   |

**WHICH NATURAL ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION?**  
*Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.*

|   |   |  |   |
|---|---|--|---|
| <input type="checkbox"/> FLOODING                   | <input type="checkbox"/> FIRE               | <input type="checkbox"/> STORM           | <input type="checkbox"/> EARTH MOVEMENT                                     |
| <input type="checkbox"/> INVASIVE EXOTIC VEGETATION | <input type="checkbox"/> INSECT INFESTATION | <input type="checkbox"/> ANIMAL ACTIVITY | <input type="checkbox"/> OTHER ACTIVITIES/ CHANGES? <i>(Please Explain)</i> |
|   |   |  | <input checked="" type="checkbox"/> NO CHANGE                               |
| <b>EXPLAIN:</b> N/A                                 |   |  |   |

## BAILEY FORK CREEK INSPECTION REPORT

### WHICH MANMADE ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING?

*Check all that apply. Note location and extent. Document with photos.*

|  |  |   |
|--|--|---|
| <input type="checkbox"/> NEW STRUCTURE / CONSTRUCTION        | <input type="checkbox"/> DUMPING OR STORING                              | <input type="checkbox"/> NEW TRAILS OR ROADS                                    |
| <input type="checkbox"/> TIMBER HARVEST/ VEGETATIVE CUTTING  | <input type="checkbox"/> EXCAVATION (DREDGING, FILLING, GRADING, MINING) | <input type="checkbox"/> ALTERATION TO DRAINAGE PATTERNS/WATER QUALITY          |
| <input type="checkbox"/> SUBDIVISION                         | <input type="checkbox"/> INDUSTRIAL, RESIDENTIAL, OR COMMERCIAL USE      | <input type="checkbox"/> LAND CLEARING  |
| <input type="checkbox"/> MOTORIZED VEHICLE DAMAGE            | <input type="checkbox"/> TRESPASS/VANDALISM                              | <input type="checkbox"/> AGRICULTURAL USE                                       |
| <input type="checkbox"/> ENCROACHMENT FROM ADJACENT PROPERTY | <input type="checkbox"/> ACTIVITY ON ABUTTING LAND                       | <input type="checkbox"/> OTHER ACTIVITIES / CHANGES?<br><i>(Please Explain)</i> |
| <input checked="" type="checkbox"/> NO CHANGE                |  |   |

**EXPLAIN:** N/A

**REQUEST FOLLOW-UP BY PROGRAM MANAGER FOR POSSIBLE VIOLATIONS.**

YES

NO

|   |   |   |                 |
|---|---|---|-----------------|
| Were corrective actions completed for previous inspection(s)?           | <input type="checkbox"/> YES            | <input type="checkbox"/> NO             | <b>EXPLAIN:</b> |
|   |   | <input checked="" type="checkbox"/> N/A |                 |
| Are you aware of any plans that may affect property?                    | <input type="checkbox"/> YES            | <input checked="" type="checkbox"/> NO  | <b>EXPLAIN:</b> |
| Are there concerns about boundaries by adjacent property owners?        | <input type="checkbox"/> YES            | <input checked="" type="checkbox"/> NO  | <b>EXPLAIN:</b> |
| Are there changes in land use on adjacent property?                     | <input type="checkbox"/> YES            | <input checked="" type="checkbox"/> NO  | <b>EXPLAIN:</b> |
| Are deed restrictions being adhered to?                                 | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO             | <b>EXPLAIN:</b> |
| If new property owner, do they have a written copy of the restrictions? | <input type="checkbox"/> YES            | <input type="checkbox"/> NO             |                 |
|   |   | <input checked="" type="checkbox"/> N/A |                 |

**ATTACHMENTS:**

- 1) MAP OF PERMANENT PHOTO PLOTS
- 2) PHOTOGRAPHS WITH CAPTIONS
- 3) MAP AND PHOTOGRAPHS WITH CAPTIONS OF RELEVANT NATURAL AND MANMADE ACTIVITIES
- 4) OTHER (SPECIFY)

## BAILEY FORK - WRC SITE



## BAILEY FORK - WRC SITE



**BAILEY FORK - WRC SITE**



D:\GIS\Projects\000166 - North Carolina Dept of Transportation\0217597 - NCDOT Stewardship Monitoring\9\map\_docs\mxd\working\24 - Bailey Fork WRC Site.mxd | Last Updated: 10/21/2013



**Bailey Fork WRC Site**

**Propst Road**

**64**



**Bailey Fork WRC Site**

NCDOT | Stewardship Monitoring | Divisions 11, 13, and 14