

BEAR CREEK INSPECTION REPORT

| | | | |
|------------------------------------|--------------|-------|------------------------------|
| MITIGATION SITE NAME BEAR CREEK | TIP # FDP | WBS # | INSPECTION DATE 8/21/2013 |
|------------------------------------|--------------|-------|------------------------------|

| | |
|------------------|------------------|
| COUNTY Lenoir | # ACRES 145.0 |
|------------------|------------------|

| | | | |
|----------------------------------|----------------------|------------------------|-------------------------------------|
| MONITORING ORGANIZATION NCDOT | INSPECTOR RWG/MPA | PHONE (919)707-6121 | EMAIL ADDRESS rgriffin@ncdot.gov |
|----------------------------------|----------------------|------------------------|-------------------------------------|

| | | | |
|---|--|--|-------------------------------|
| INSPECTION ACTIVITIES: <i>Complete all that apply.</i> | | | |
| Walked boundaries | <input type="checkbox"/> YES | <input type="checkbox"/> NO | <input type="checkbox"/> N/A |
| Walked trails / roads | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | <input type="checkbox"/> N/A |
| Walked road frontage | <input type="checkbox"/> YES | <input type="checkbox"/> NO | <input type="checkbox"/> N/A |
| Walked interior | <input type="checkbox"/> YES | <input checked="" type="checkbox"/> NO | <input type="checkbox"/> N/A |
| Monitored from air | <input type="checkbox"/> YES | <input type="checkbox"/> NO | <input type="checkbox"/> N/A |
| Condition of boundaries | <input checked="" type="checkbox"/> GOOD | <input type="checkbox"/> FAIR | <input type="checkbox"/> POOR |
| COMMENTS: No apparent signs of trespass or dumping at the site. The gate was locked at the Washington Street entrance and Promise road was closed due to construction on the Goldsboro Bypass. | | | |

WHICH NATURAL ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION?
Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.

| | | | |
|---|---|--|--|
| <input type="checkbox"/> FLOODING | <input type="checkbox"/> FIRE | <input type="checkbox"/> STORM | <input checked="" type="checkbox"/> EARTH MOVEMENT |
| <input type="checkbox"/> INVASIVE EXOTIC VEGETATION | <input type="checkbox"/> INSECT INFESTATION | <input type="checkbox"/> ANIMAL ACTIVITY | <input type="checkbox"/> OTHER ACTIVITIES/ CHANGES? <i>(Please Explain)</i> |
| | | | <input type="checkbox"/> NO CHANGE |

| |
|---|
| EXPLAIN: Goldsboro Bypass borrow pit is located immediately adjacent to the mitigation site. |
|---|

BEAR CREEK INSPECTION REPORT

WHICH MANMADE ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING?

Check all that apply. Note location and extent. Document with photos.

| | | |
|--|--|---|
| <input type="checkbox"/> NEW STRUCTURE / CONSTRUCTION | <input type="checkbox"/> DUMPING OR STORING | <input type="checkbox"/> NEW TRAILS OR ROADS |
| <input type="checkbox"/> TIMBER HARVEST/ VEGETATIVE CUTTING | <input type="checkbox"/> EXCAVATION (DREDGING, FILLING, GRADING, MINING) | <input type="checkbox"/> ALTERATION TO DRAINAGE PATTERNS/WATER QUALITY |
| <input type="checkbox"/> SUBDIVISION | <input type="checkbox"/> INDUSTRIAL, RESIDENTIAL, OR COMMERCIAL USE | <input type="checkbox"/> LAND CLEARING |
| <input type="checkbox"/> MOTORIZED VEHICLE DAMAGE | <input type="checkbox"/> TRESPASS/VANDALISM | <input type="checkbox"/> AGRICULTURAL USE |
| <input type="checkbox"/> ENCROACHMENT FROM ADJACENT PROPERTY | <input type="checkbox"/> ACTIVITY ON ABUTTING LAND | <input type="checkbox"/> OTHER ACTIVITIES / CHANGES? <i>(Please Explain)</i> |
| <input checked="" type="checkbox"/> NO CHANGE | | |

EXPLAIN:

REQUEST FOLLOW-UP BY PROGRAM MANAGER FOR POSSIBLE VIOLATIONS.

YES


NO

| | | | |
|---|---|---|--|
| Were corrective actions completed for previous inspection(s)? | <input type="checkbox"/> YES | <input type="checkbox"/> NO | EXPLAIN: |
| | | <input checked="" type="checkbox"/> N/A | |
| Are you aware of any plans that may affect property? | <input type="checkbox"/> YES | <input checked="" type="checkbox"/> NO | EXPLAIN: |
| Are there concerns about boundaries by adjacent property owners? | <input type="checkbox"/> YES | <input checked="" type="checkbox"/> NO | EXPLAIN: |
| Are there changes in land use on adjacent property? | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | EXPLAIN: Borrow pit for Goldsboro Bypass is adjacent to the site. |
| Are deed restrictions being adhered to? | <input checked="" type="checkbox"/> YES | <input type="checkbox"/> NO | EXPLAIN: |
| If new property owner, do they have a written copy of the restrictions? | <input type="checkbox"/> YES | <input type="checkbox"/> NO | |
| | | <input checked="" type="checkbox"/> N/A | |

ATTACHMENTS:

- 1) MAP OF PERMANENT PHOTO PLOTS
- 2) PHOTOGRAPHS WITH CAPTIONS
- 3) MAP AND PHOTOGRAPHS WITH CAPTIONS OF RELEVANT NATURAL AND MANMADE ACTIVITIES
- 4) OTHER (SPECIFY)

BEAR CREEK



BEAR CREEK



BEAR CREEK



Sleepy Creek

Washington Street

Bear Creek

Promise Land Rd.

70

70

