

BEAR CREEK INSPECTION REPORT

MITIGATION SITE NAME BEAR CREEK	TIP # R-9999	WBS #	INSPECTION DATE 8/10/2015
------------------------------------	-----------------	-------	------------------------------

COUNTY Lenoir	# ACRES 148.7	ONEID 054-010
------------------	------------------	------------------

MONITORING ORGANIZATION Kimley-Horn	INSPECTOR JRH/BAR	PHONE (919)678-4155	EMAIL ADDRESS Jason.Hartshorn@Kimley-Horn.com
--	----------------------	------------------------	--

INSPECTION ACTIVITIES: <i>Complete all that apply.</i>			
Walked boundaries	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> N/A
Walked trails / roads	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> N/A
Walked road frontage	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> N/A
Walked interior	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> N/A
Monitored from air	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> N/A
Condition of boundaries	<input checked="" type="checkbox"/> GOOD	<input type="checkbox"/> FAIR	<input type="checkbox"/> POOR
<p>COMMENTS: No evidence of encroachment/trespass. Boundary appeared to be undisturbed, however no NCDOT signs were observed so boundary is unmarked. Located gate adjacent to pond off Promise Land Road (see map). Gate was locked with key padlock, no apparent signs of trespass, however past disturbance was prevalent in this area, and half of a fishing pole was found on the ground.</p> <p>Washington Street Entrance: Gate was closed, and vegetation is overtaking entrance road and no sign of trespass or site access was observed. There was no lock present on the gate, but gate slide could not be manipulated to open gate and enter site. Site appears to be in great condition overall and functioning as intended.</p>			

WHICH NATURAL ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION?

Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.

<input type="checkbox"/> FLOODING	<input type="checkbox"/> FIRE	<input type="checkbox"/> STORM	<input checked="" type="checkbox"/> EARTH MOVEMENT
<input type="checkbox"/> INVASIVE EXOTIC VEGETATION	<input type="checkbox"/> INSECT INFESTATION	<input type="checkbox"/> ANIMAL ACTIVITY	<input type="checkbox"/> OTHER ACTIVITIES/ CHANGES? (Please Explain)
			<input type="checkbox"/> NO CHANGE

EXPLAIN: Goldsboro Bypass borrow pit is located immediately adjacent to the mitigation site. Access road around borrow pit is maintained and no trespass/encroachment was readily observable from the borrow pit site. No NCDOT mitigation site signage was observed.

BEAR CREEK INSPECTION REPORT

WHICH MANMADE ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING?

Check all that apply. Note location and extent. Document with photos.

<input type="checkbox"/> NEW STRUCTURE / CONSTRUCTION	<input type="checkbox"/> DUMPING OR STORING	<input type="checkbox"/> NEW TRAILS OR ROADS
<input type="checkbox"/> TIMBER HARVEST/ VEGETATIVE CUTTING	<input type="checkbox"/> EXCAVATION (DREDGING, FILLING, GRADING, MINING)	<input type="checkbox"/> ALTERATION TO DRAINAGE PATTERNS/WATER QUALITY
<input type="checkbox"/> SUBDIVISION	<input type="checkbox"/> INDUSTRIAL, RESIDENTIAL, OR COMMERCIAL USE	<input type="checkbox"/> LAND CLEARING
<input type="checkbox"/> MOTORIZED VEHICLE DAMAGE	<input type="checkbox"/> TRESPASS/VANDALISM	<input type="checkbox"/> AGRICULTURAL USE
<input type="checkbox"/> ENCROACHMENT FROM ADJACENT PROPERTY	<input type="checkbox"/> ACTIVITY ON ABUTTING LAND	<input type="checkbox"/> OTHER ACTIVITIES / CHANGES? <i>(Please Explain)</i>
<input checked="" type="checkbox"/> NO CHANGE		
EXPLAIN: No trespass or encroachment was noted.		
REQUEST FOLLOW-UP BY PROGRAM MANAGER FOR POSSIBLE VIOLATIONS.		
		<input type="checkbox"/> YES <input type="checkbox"/> NO

Were corrective actions completed for previous inspection(s)?	<input type="checkbox"/> YES	<input type="checkbox"/> NO	EXPLAIN:
		<input checked="" type="checkbox"/> N/A	
Are you aware of any plans that may affect property?	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	EXPLAIN:
Are there concerns about boundaries by adjacent property owners?	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	EXPLAIN:
Are there changes in land use on adjacent property?	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	EXPLAIN: Borrow pit for Goldsboro Bypass is adjacent to the site and has expanded significantly from previous year's report, however it appears completed and no longer actively expanding.
Are deed restrictions being adhered to?	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	EXPLAIN:
If new property owner, do they have a written copy of the restrictions?	<input type="checkbox"/> YES	<input type="checkbox"/> NO	
		<input checked="" type="checkbox"/> N/A	
ATTACHMENTS:			
<ul style="list-style-type: none"> 1) SITE PHOTOGRAPHS WITH CAPTIONS 2) SITE MAP 			

BEAR CREEK



Photo 1 – View of secure gate off of Washington Street.



Photo 2 – View of borrow pit adjacent to the site.


BEAR CREEK



Photo 3 – View of secure gate off of Promise Land Road.



Photo 4 – View of vegetation within the site.



Aerial Imagery
 R-9999 Sleepy Creek (054-011)
 and Bear Creek (054-010)
 Division 2, NCDOT
 October 2015