DOT Site Inspection Report

Mitigation Site Name	TIP #	WBS #	Inspection Date
I-2402A (Site#31)	I-2402A		11/13/15

County	# Acres
Guilford	

Monitoring Organization	Inspector	Phone	Email Address
HDR for NCDOT	VM/SE	(919) 232-6637	vickie.miller@hdrinc.com

Inspection Activities: *Complete all that apply. Describe location of visited areas if <100%.*

Walked boundaries	☒ Yes	☐ No	☐ N/A	Walked trails / roads	☐ Yes	☒ No	☐ N/A
Walked road frontage	☒ Yes	☐ No	☐ N/A	Walked interior	☐ Yes	☒ No	☐ N/A
Monitored from air	☐ Yes	☒ No	☐ N/A				

Condition of boundaries: ☒ Good ☐ Fair ☐ Poor

Comments: No trespassing issues were observed. Mowing is occurring in the upland areas.

Which natural activities / changes have taken place since last monitoring inspection?
Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.

☐ Flooding	☐ Fire	☐ Storm	☐ Earth Movement
☐ Invasive Exotic Vegetation	☐ Insect infestation	☐ Animal activity	☐ Other activities/ changes? *(Please Explain)*
			☒ No Change

Explain:

DOT SITE INSPECTION REPORT

WHICH MANMADE ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING?
Check all that apply. Note location and extent. Document with photos.

☐ NEW STRUCTURE / CONSTRUCTION	☐ DUMPING OR STORING	☐ NEW TRAILS OR ROADS
☐ TIMBER HARVEST/ VEGETATIVE CUTTING	☐ EXCAVATION (DREDGING, FILLING, GRADING, MINING)	☐ ALTERATION TO DRAINAGE PATTERNS/WATER QUALITY
☐ SUBDIVISION	☐ INDUSTRIAL, RESIDENTIAL, OR COMMERCIAL USE	☐ LAND CLEARING
☐ MOTORIZED VEHICLE DAMAGE	☐ TRESPASS/VANDALISM	☐ AGRICULTURAL USE
☐ ENCROACHMENT FROM ADJACENT PROPERTY	☐ ACTIVITY ON ABUTTING LAND	☐ OTHER ACTIVITIES / CHANGES? *(Please Explain)*
		☒ NO CHANGE

EXPLAIN:

REQUEST FOLLOW-UP BY PROGRAM MANAGER FOR POSSIBLE VIOLATIONS. ☐ YES ☒ NO

Were corrective actions completed for previous inspection(s)?	☐ YES	☐ NO ☒ N/A	**EXPLAIN:**
Are you aware of any plans that may affect property?	☐ YES	☒ NO	**EXPLAIN:**
Are there concerns about boundaries by adjacent property owners?	☐ YES	☒ NO	**EXPLAIN:**
Are there changes in land use on adjacent property?	☐ YES	☒ NO	**EXPLAIN:**
Are deed restrictions being adhered to?	☒ YES	☐ NO	**EXPLAIN:**
If new property owner, do they have a written copy of the restrictions?	☐ YES	☐ NO ☒ N/A	

ATTACHMENTS:

1) PHOTOGRAPHS WITH CAPTIONS
2) MAP AND PHOTOGRAPHS WITH CAPTIONS OF RELEVANT NATURAL AND MANMADE ACTIVITIES

I-2402A (SITE #31)

Looking southeast from the western side of the site

Looking north across easement from the south side of the site

I-2402A (SITE #31)

Looking northwest along easement from eastern end of site



I-2402A SITES 31 AND 36

GUILFORD COUNTY

PATH: \\CLTSMAIN\GIS_DATA\GIS\PROJECTS\000166_NORTHCAROLINADEPTOFTRANSPORTATION\267000_NCDOT_STEWARDSHIPMONITORING_2015\7.1_FINAL_RECORDS\MAP_DOCS\MXD\07_I_2402A_SITE31_36.MXD - USER: JTISDALE - DATE: 11/23/2015