I-2402A Site #36 Inspection Report

Mitigation Site Name	TIP #	WBS #	Inspection Date
I-2402A Site #36	I-2402A		8/08/2013

County	# Acres
Guilford	

Monitoring Organization	Inspector	Phone	Email Address
NCDOT	JCE/PA	(919)707-6121	rgriffin@ncdot.gov

Inspection Activities: *Complete all that apply.*

Walked boundaries	☒ Yes	☐ No	☐ N/A	Walked trails / roads	☐ Yes ☐ No ☒ N/A
Walked road frontage	☒ Yes	☐ No	☐ N/A	Walked interior	☐ Yes ☒ No ☐ N/A
Monitored from air	☐ Yes	☒ No	☐ N/A		
Condition of boundaries	☒ Good	☐ Fair	☐ Poor		

Comments: The boundary at this site remains in very good condition at this time. There were no dumping or trespass issues at the time of inspection. There has been some mowing adjacent to the site but is not affecting the buffer at this time.

Which natural activities / changes have taken place since last monitoring inspection?
Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.

☐ Flooding	☐ Fire	☐ Storm	☐ Earth Movement
☐ Invasive Exotic Vegetation	☐ Insect Infestation	☐ Animal Activity	☐ Other activities/ changes? *(Please Explain)*
			☒ No Change

Explain:

I-2402A Site #36 Inspection Report

Which manmade activities / changes have taken place since last monitoring?
Check all that apply. Note location and extent. Document with photos.

☐ New structure / construction	☐ Dumping or storing	☐ New trails or roads
☐ Timber harvest/ Vegetative cutting	☐ Excavation (dredging, filling, grading, mining)	☐ Alteration to drainage patterns/water quality
☐ Subdivision	☐ Industrial, residential, or commercial use	☐ LAND CLEARING
☐ Motorized vehicle damage	☐ Trespass/vandalism	☐ Agricultural use
☐ Encroachment from Adjacent property	☐ Activity on abutting land	☐ Other activities / changes? *(Please Explain)*
		☒ No Change

Explain:

Request follow-up by Program Manager for possible violations. ☐ Yes ☒ No

Were corrective actions completed for previous inspection(s)?	☐ Yes	☐ No ☒ N/A	**Explain:**
Are you aware of any plans that may affect property?	☐ Yes	☒ No	**Explain:**
Are there concerns about boundaries by adjacent property owners?	☐ Yes	☒ No	**Explain:**
Are there changes in land use on adjacent property?	☐ Yes	☒ No	**Explain:**
Are deed restrictions being adhered to?	☒ Yes	☐ No	**Explain:**
If new property owner, do they have a written copy of the restrictions?	☐ Yes	☐ No ☒ N/A	

Attachments:

1) Map of permanent photo plots
2) Photographs with captions
3) map and photographs with captions of relevant natural and Manmade activities
4) Other (specify)

I-2402A SITE #36

I-2402A Site #36