

### DOT SITE INSPECTION REPORT

<b>MITIGATION SITE NAME</b> I-2402B site#1	<b>TIP#</b> I-2402B	<b>WBS#</b> Guilford	<b>INSPECTION DATE</b> 7/30/2014
---	------------------------	-------------------------	-------------------------------------

<b>COUNTY</b> Guilford	<b>#ACRES</b>
---------------------------	---------------

<b>MONITORING ORGANIZATION</b> NCDOT	<b>INSPECTOR</b> AF/AH	<b>PHONE</b> (919)707-6121	<b>EMAIL ADDRESS</b> rgriffin@ncdot.gov
---	---------------------------	-------------------------------	--

**INSPECTION ACTIVITIES:** Complete all that apply. Describe the location of visited areas if <100%

Walked boundaries	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> N/A	Walked Trails/roads	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input type="checkbox"/> N/A
Walked road frontage	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> N/A	Walked Interior	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input type="checkbox"/> N/A
Monitored from air	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input type="checkbox"/> N/A				
Condition of boundaries				<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Fair	<input type="checkbox"/> Poor	

Comments: No Trespass or mowing issues observed. Site looks good.

**WHICH NATURAL ACTIVITIES/CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION?**

*Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.*

<input type="checkbox"/> <b>FLOODING</b>	<input type="checkbox"/> <b>FIRE</b>	<input type="checkbox"/> <b>STORM</b>	<input type="checkbox"/> <b>EARTH MOVEMENT</b>
<input type="checkbox"/> <b>INVASIVE EXOTIC VEGTATION</b>	<input type="checkbox"/> <b>INSECT INFESTATION</b>	<input type="checkbox"/> <b>ANIMAL ACTIVITY</b>	<input type="checkbox"/> <b>OTHER ACTIVITIES/ CHANGES (Explain)</b>
			<input checked="" type="checkbox"/> <b>NO CHANGE</b>

**EXPLAIN:**

## DOT SITE INSPECTION REPORT

### WHICH NATURAL ACTIVITIES/CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION?

*Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.*

<input type="checkbox"/> NEW STURCTURE/ CONSTRUCTION	<input type="checkbox"/> DUMPING OR STORING	<input type="checkbox"/> NEW TRAILS OR ROADS
<input type="checkbox"/> TIMBER HARVEST/ VEGETATIVE CUTTING	<input type="checkbox"/> EXCAVATION (DREDGING, FILLING, GRADING, MINING)	<input type="checkbox"/> ALTERATION TO DRAINAGE PATTERNS/WATER QUALITY
<input type="checkbox"/> SUBDIVISION	<input type="checkbox"/> INDUSTRIAL, RESIDENTIAL OR COMMERCIAL USE	<input type="checkbox"/> LAND CLEARING
<input type="checkbox"/> MOTORIZED VEHICLE DAMAGE	<input type="checkbox"/> TRESSPASS/VANDALISM	<input type="checkbox"/> AGRICULTURAL USE
<input type="checkbox"/> ENCROACHMENT FROM ADJACENT PROPERTY	<input type="checkbox"/> ACTIVITY ON ABUTTING LAND	<input type="checkbox"/> OTHER ACTIVITIES/ CHANGES (Please Explain)
		<input checked="" type="checkbox"/> NO CHANGE

**EXPLAIN:**

**REQUEST FOLLOW-UP BY PROGRAM MANAGER  
FOR POSSIBLE VIOLATIONS.**

YES

NO

Were corrective actions completed for previous inspection(s)?	<input type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> N/A	<b>EXPLAIN:</b>
Are you aware of any plans that may affect property?	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO		<b>EXPLAIN:</b>
Are there concerns about boundaries by adjacent property owners?	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO		<b>EXPLAIN:</b>
Are there changes in land use on adjacent property?	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO		<b>EXPLAIN: New construction on east property.</b>
Are deed restrictions being adhered to?	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO		<b>EXPLAIN:</b>
If new property owner, do they have a written copy of the restrictions?	<input type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> N/A	

**ATTACHMENTS:**

- 1) MAP OF THE PERMANENT PHOTO PLOTS
- 2) PHOTOGRAPHS WITH CAPTIONS
- 3) MAP AND PHOTOGRAPHS WITH CAPTIONS OF RELEVANT NATURAL AND MANMADE ACTIVITIES
- 4) OTHER (SPECIFY)

## DOT SITE INSPECTION REPORT

### Inspection Photographs

---



Comments:



**I-2402B Site 1**  
Guilford County

 NC DOT Stewardship Sites

0 50 100 200 300 400 Feet

