

ROANOKE ISLAND VISITOR'S CENTER INSPECTION REPORT

MITIGATION SITE NAME Roanoke Island Visitor's Center Mitigation Site	TIP # K-4003	WBS # 34258.1.1	INSPECTION DATE 10/27/2014
---	-----------------	--------------------	-------------------------------

COUNTY Hyde	ACRES 3.5
----------------	--------------

MONITORING ORGANIZATION Kimley-Horn	INSPECTOR JRH/CPM	PHONE (919)678-4155	EMAIL ADDRESS Jason.Hartshorn@Kimley-Horn.com
--	----------------------	------------------------	--

INSPECTION ACTIVITIES: Complete all that apply. Describe location of visited areas if <100%.

Walked boundaries <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> N/A	Walked trails / roads <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> N/A
Walked road frontage <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> N/A	Walked interior <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> N/A
Monitored from air <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> N/A	
Condition of boundaries	<input checked="" type="checkbox"/> GOOD <input type="checkbox"/> FAIR <input type="checkbox"/> POOR

Comments: Site remains in excellent condition. A new walking path has been constructed in the portion of the site located north of US 64, however no evidence of unauthorized activity was observed. South of US 64, site also remains in excellent condition and is functioning well.

WHICH NATURAL ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION?

Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.

<input type="checkbox"/> FLOODING	<input type="checkbox"/> FIRE	<input type="checkbox"/> STORM	<input type="checkbox"/> EARTH MOVEMENT
<input type="checkbox"/> INVASIVE EXOTIC VEGETATION	<input type="checkbox"/> INSECT INFESTATION	<input type="checkbox"/> ANIMAL ACTIVITY	<input type="checkbox"/> OTHER ACTIVITIES/ CHANGES? (Please Explain)
<input checked="" type="checkbox"/> NO CHANGE			

Comments: No changes were noted from the 2013 review.

ROANOKE ISLAND VISITOR'S CENTER INSPECTION REPORT

WHICH MANMADE ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING?

Check all that apply. Note location and extent. Document with photos.

<input type="checkbox"/> NEW STRUCTURE / CONSTRUCTION	<input type="checkbox"/> DUMPING OR STORING	<input type="checkbox"/> NEW TRAILS OR ROADS
<input type="checkbox"/> TIMBER HARVEST / VEGETATIVE CUTTING	<input type="checkbox"/> EXCAVATION (DREDGING, FILLING, GRADING, MINING)	<input type="checkbox"/> ALTERATION TO DRAINAGE PATTERNS/WATER QUALITY
<input type="checkbox"/> SUBDIVISION	<input type="checkbox"/> INDUSTRIAL, RESIDENTIAL, OR COMMERCIAL USE	<input type="checkbox"/> LAND CLEARING
<input type="checkbox"/> MOTORIZED VEHICLE DAMAGE	<input type="checkbox"/> TRESPASS/VANDALISM	<input type="checkbox"/> AGRICULTURAL USE
<input type="checkbox"/> ENCROACHMENT FROM ADJACENT PROPERTY	<input type="checkbox"/> ACTIVITY ON ABUTTING LAND	<input type="checkbox"/> OTHER ACTIVITIES / CHANGES? <i>(Please Explain)</i>
<input checked="" type="checkbox"/> NO CHANGE		

Explain: No manmade activities were observed within the site. There is a new walking trail on the north side of US 64 that leads inside the fence/barrier, however no activity was noted near the site itself.

REQUEST FOLLOW-UP BY PROGRAM MANAGER FOR POSSIBLE VIOLATIONS.	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
--	------------------------------	--

Were corrective actions completed for previous inspection(s)?	<input type="checkbox"/> YES	<input type="checkbox"/> NO	EXPLAIN:
		<input checked="" type="checkbox"/> N/A	
Are you aware of any plans that may affect property?	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	EXPLAIN:
Are there concerns about boundaries by adjacent property owners?	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	EXPLAIN:
Are there changes in land use on adjacent property?	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	EXPLAIN:
Are deed restrictions being adhered to?	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	EXPLAIN:
If new property owner, do they have a written copy of the restrictions?	<input type="checkbox"/> YES	<input type="checkbox"/> NO	
		<input checked="" type="checkbox"/> N/A	

ATTACHMENTS:

- 1) SITE PHOTOGRAPHS WITH CAPTIONS
- 2) SITE MAP

ROANOKE ISLAND VISITOR'S CENTER

Site Photographs:



Photo 1 – Interior of Site southeast of US 64 bridge.



Photo 2 – Boardwalk located in northwestern corner of the site located south of US 64. Despite easy accessibility through Site, no human disturbances were observed in the mitigation site.

ROANOKE ISLAND VISITOR'S CENTER



Photo 3 – Interior of site as viewed from southern boundary canal.



Photo 4 – Interior of northern portion of Site (north of US 64). Note Phragmites inflorescence visible in background of photo.

ROANOKE ISLAND VISITOR'S CENTER



Photo 5 – Walking trail access through barrier towards mitigation site on north side of US 64. The trail itself does not lead through the site, but does provide easy access towards the site, however no unauthorized site activity was observed.



Legend
[Red outline symbol] Division 1 Study Site

0 150 300
Feet

NC OneMap, NC Center for Geographic Information and Analysis, NC 911 Board



Division 1 - Roanoke Visitor Center
NCDOT Site Inspection Program
Dare County, North Carolina
November 2014