# UT Little River Inspection Report

| Mitigation Site Name | TIP # | WBS # | Inspection Date |
|---|---|---|---|
| UT Little River Creek | R-0210A | N/A | 11-19-2013 |

| County | # Acres |
|---|---|
| Moore | 174 LF |

| Monitoring Organization | Inspector | Phone | Email Address |
|---|---|---|---|
| NCDOT | JCE/BGM | (919)707-6121 | rgriffin@ncdot.gov |

**Inspection Activities:** *Complete all that apply. Describe location of visited areas if <100%.*

| | | | |
|---|---|---|---|
| Walked boundaries | ☒ Yes ☐ No ☐ N/A | Walked trails / roads | ☐ Yes ☒ No ☐ N/A |
| Walked road frontage | ☒ Yes ☐ No ☐ N/A | Walked interior | ☐ Yes ☒ No ☐ N/A |
| Monitored from air | ☐ Yes ☒ No ☐ N/A | | |
| Condition of boundaries | ☒ Good ☐ Fair ☐ Poor | | |

**Comments:** No issues with trespass or mowing.

**Which natural activities / changes have taken place since last monitoring inspection?**
*Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.*

| | | | |
|---|---|---|---|
| ☐ Flooding | ☐ Fire | ☐ Storm | ☐ Earth Movement |
| ☐ Invasive Exotic Vegetation | ☐ Insect Infestation | ☐ Animal Activity | ☐ Other activities/ changes? *(Please Explain)* |
| | | | ☒ No Change |

**Comments:**

# UT LITTLE RIVER INSPECTION REPORT

**WHICH MANMADE ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING?**
*Check all that apply. Note location and extent. Document with photos.*

| | | |
|---|---|---|
| ☐ NEW STRUCTURE / CONSTRUCTION | ☐ DUMPING OR STORING | ☐ NEW TRAILS OR ROADS |
| ☐ TIMBER HARVEST/ VEGETATIVE CUTTING | ☐ EXCAVATION (DREDGING, FILLING, GRADING, MINING) | ☐ ALTERATION TO DRAINAGE PATTERNS/WATER QUALITY |
| ☐ SUBDIVISION | ☐ INDUSTRIAL, RESIDENTIAL, OR COMMERCIAL USE | ☐ LAND CLEARING |
| ☐ MOTORIZED VEHICLE DAMAGE | ☐ TRESPASS/VANDALISM | ☐ AGRICULTURAL USE |
| ☐ ENCROACHMENT FROM ADJACENT PROPERTY | ☐ ACTIVITY ON ABUTTING LAND | ☐ OTHER ACTIVITIES / CHANGES? *(Please Explain)* |
| | | ☒ NO CHANGE |

**EXPLAIN:**

**REQUEST FOLLOW-UP BY PROGRAM MANAGER FOR POSSIBLE VIOLATIONS.** ☐ YES ☒ NO

| | | | |
|---|---|---|---|
| Were corrective actions completed for previous inspection(s)? | ☐ YES | ☐ NO ☒ N/A | **EXPLAIN:** |
| Are you aware of any plans that may affect property? | ☐ YES | ☒ NO | **EXPLAIN:** |
| Are there concerns about boundaries by adjacent property owners? | ☐ YES | ☒ NO | **EXPLAIN:** |
| Are there changes in land use on adjacent property? | ☐ YES | ☒ NO | **EXPLAIN:** |
| Are deed restrictions being adhered to? | ☒ YES | ☐ NO | **EXPLAIN:** |
| If new property owner, do they have a written copy of the restrictions? | ☐ YES | ☐ NO ☒ N/A | |

**ATTACHMENTS:**

1) MAP OF PERMANENT PHOTO PLOTS
2) PHOTOGRAPHS WITH CAPTIONS
3) MAP AND PHOTOGRAPHS WITH CAPTIONS OF RELEVANT NATURAL AND MANMADE ACTIVITIES
4) OTHER (SPECIFY)

R-0210A UT to LITTLE RIVER
1
1
690
NC OneMap