DOT SITE INSPECTION REPORT

MITIGATION SITE NAME	TIP#	WBS#	INSPECTION DATE
R-0609D Site #4	R-0609D	Guilford	8/6/2014

COUNTY	#ACRES
Guilford	

MONITORING ORGANIZATION	INSPECTOR	PHONE	EMAIL ADDRESS
NCDOT	AF/AH	(919)707-6121	rgriffin@ncdot.gov

INSPECTION ACTIVITIES: Complete all that apply. Describe the location of visited areas if <100%

Walked boundaries	☐ Yes	☒ No	☐ N/A	Walked Trails/roads	☐ Yes	☒ No	☐ N/A	
Walked road frontage	☒ Yes	☐ No	☐ N/A	Walked Interior	☐ Yes	☒ No	☐ N/A	
Monitored from air	☐ Yes	☒ No	☐ N/A					
Condition of boundaries	☒ Good	☐ Fair	☐ Poor					

Comments: Walked accessible easement boundaries. No Trespass or mowing issues observed. Site looks good.

WHICH NATURAL ACTIVITIES/CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION?
Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.

☐ **FLOODING**	☐ **FIRE**	☐ **STORM**	☐ **EARTH MOVEMENT**
☐ **INVASIVE EXOTIC VEGTATION**	☐ **INSECT INFESTATION**	☐ **ANIMAL ACTIVITY**	☐ **OTHER ACTIVITIES/ CHANGES (Explain)**
			☒ **NO CHANGE**

EXPLAIN:

DOT SITE INSPECTION REPORT

WHICH NATURAL ACTIVITIES/CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION?
Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.

☐ **NEW STURCTURE/ CONSTRUCTION**	☐ **DUMPING OR STORING**	☐ **NEW TRAILS OR ROADS**
☐ **TIMBER HARVEST/ VEGETATIVE CUTTING**	☐ **EXCAVATION (DREDGING, FILLING, GRADING, MINING)**	☐ **ALTERATION TO DRAINAGE PATTERNS/WATER QUALITY**
☐ **SUBDIVISION**	☐ **INDUSTRIAL, RESIDENTIAL OR COMMERCIAL USE**	☐ **LAND CLEARING**
☐ **MOTORIZED VEHICLE DAMAGE**	☐ **TRESSPASS/VANDALISM**	☐ **AGRICULTURAL USE**
☐ **ENCROACHMENT FROM ADJACENT PROPERTY**	☐ **ACTIVITY ON ABUTTING LAND**	☐ **OTHER ACTIVITIES/ CHANGES (Please Explain)**
		☒ **NO CHANGE**

EXPLAIN:

REQUEST FOLLOW-UP BY PROGRAM MANAGER FOR POSSBILE VIOLATIONS. ☐ YES ☒ NO

Were corrective actions completed for previous inspection(s)?	☐ YES ☐ NO ☒ N/A	**EXPLAIN:**
Are you aware of any plans that may affect property?	☐ YES ☒ NO	**EXPLAIN:**
Are there concerns about boundaries by adjacent property owners?	☐ YES ☒ NO	**EXPLAIN:**
Are thre changes in land use on adjacent property?	☐ YES ☒ NO	**EXPLAIN:**
Are deed restrictions being adhered to?	☒ YES ☐ NO	**EXPLAIN:**
If new property owner, do they have a written copy of the restrictions?	☐ YES ☐ NO ☒ N/A	

ATTACHMENTS:

1) MAP OF THE PERMANENT PHOTO PLOTS
2) PHOTOGRAPHS WITH CAPTIONS
3) MAP AND PHOTOGRAPHS WITH CAPTIONS OF RELEVANT NATURAL AND MANMADE ACTIVITIES
4) OTHER (SPECIFY)

Inspection Photographs

Comments:

Comments:

DOT SITE INSPECTION REPORT

Comments:

R-0609D Site #3 & #4

Guilford County

NC DOT Stewardship Sites

0 62.5 125 250 375 500 Feet

N

KCI ASSOCIATES OF NC

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION