

DOT SITE INSPECTION REPORT

MITIGATION SITE NAME	TIP#	WBS#	INSPECTION DATE
Harris Farm-HQP	R-2000	N/A	12/11/2014

COUNTY	#ACRES
Franklin	125.44

MONITORING ORGANIZATION	INSPECTOR	PHONE	EMAIL ADDRESS
KCI for NCDOT	AF/TS	(919)278-2508	april.eason@kci.com

INSPECTION ACTIVITIES: Complete all that apply. Describe the location of visited areas if <100%

Walked boundaries	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input type="checkbox"/> N/A	Walked Trails/roads	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input type="checkbox"/> N/A
Walked road frontage	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> N/A	Walked Interior	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input type="checkbox"/> N/A
Monitored from air	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input type="checkbox"/> N/A				

Condition of boundaries Good Fair Poor

Comments: No trespass activities were seen at the time of the site walk. All access gates into the site were locked making much of the boundary inaccessible.

WHICH NATURAL ACTIVITIES/CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION?
Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.

<input type="checkbox"/> FLOODING	<input type="checkbox"/> FIRE	<input type="checkbox"/> STORM	<input type="checkbox"/> EARTH MOVEMENT
<input type="checkbox"/> INVASIVE EXOTIC VEGTATION	<input type="checkbox"/> INSECT INFESTATION	<input checked="" type="checkbox"/> ANIMAL ACTIVITY	<input type="checkbox"/> OTHER ACTIVITIES/ CHANGES (Explain)
			<input type="checkbox"/> NO CHANGE

EXPLAIN: Beaver dam present at River Road crossing looking north. See photo below.

DOT SITE INSPECTION REPORT

WHICH NATURAL ACTIVITIES/CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION?

Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.

<input type="checkbox"/> NEW STURCTURE/ CONSTRUCTION	<input type="checkbox"/> DUMPING OR STORING	<input type="checkbox"/> NEW TRAILS OR ROADS
<input type="checkbox"/> TIMBER HARVEST/ VEGETATIVE CUTTING	<input type="checkbox"/> EXCAVATION (DREDGING, FILLING, GRADING, MINING)	<input type="checkbox"/> ALTERATION TO DRAINAGE PATTERNS/WATER QUALITY
<input type="checkbox"/> SUBDIVISION	<input type="checkbox"/> INDUSTRIAL, RESIDENTIAL OR COMMERCIAL USE	<input type="checkbox"/> LAND CLEARING
<input type="checkbox"/> MOTORIZED VEHICLE DAMAGE	<input type="checkbox"/> TRESSPASS/VANDALISM	<input type="checkbox"/> AGRICULTURAL USE
<input type="checkbox"/> ENCROACHMENT FROM ADJACENT PROPERTY	<input type="checkbox"/> ACTIVITY ON ABUTTING LAND	<input type="checkbox"/> OTHER ACTIVITIES/ CHANGES (Please Explain)
		<input checked="" type="checkbox"/> NO CHANGE
EXPLAIN:		
REQUEST FOLLOW-UP BY PROGRAM MANAGER FOR POSSIBLE VIOLATIONS.		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

Were corrective actions completed for previous inspection(s)? <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> N/A	EXPLAIN:
Are you aware of any plans that may affect property? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	EXPLAIN:
Are there concerns about boundaries by adjacent property owners? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	EXPLAIN:
Are there changes in land use on adjacent property? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	EXPLAIN:
Are deed restrictions being adhered to? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	EXPLAIN:
If new property owner, do they have a written copy of the restrictions? <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> N/A	

ATTACHMENTS:

- 1) PHOTOGRAPHS WITH CAPTIONS
- 2) MAP AND PHOTOGRAPHS OF RELEVANT NATURAL AND MANMADE ACTIVITIES

DOT SITE INSPECTION REPORT

Inspection Photographs



Comments: Taken from Mort Harris, looking east



Comments: Taken from George Leonard Road, looking south

DOT SITE INSPECTION REPORT



Comments: Beaver Dam at River Road crossing



Comments: Taken from Mort Harris / Dunn Road access drive, looking west

DOT SITE INSPECTION REPORT



Comments: Taken from River Road, looking south



Harris Farm
Franklin County

 NC DOT Stewardship Sites

