# DOT SITE INSPECTION REPORT

| MITIGATION SITE NAME | TIP# | WBS# | INSPECTION DATE |
|---|---|---|---|
| Cedar Point | R-2105AB | N/A | 12/15/2014 |

| COUNTY | #ACRES |
|---|---|
| Carteret | 14.5 |

| MONITORING ORGANIZATION | INSPECTOR | PHONE | EMAIL ADDRESS |
|---|---|---|---|
| KCI for NCDOT | MU/TS | (919)278-2508 | april.eason@kci.com |

**INSPECTION ACTIVITIES:** Complete all that apply. Describe the location of visited areas if <100%

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Walked boundaries | ☒ Yes | ☐ No | ☐ N/A | Walked Trails/roads | ☒ Yes | ☐ No | ☐ N/A |
| Walked road frontage | ☒ Yes | ☐ No | ☐ N/A | Walked Interior | ☒ Yes | ☐ No | ☐ N/A |
| Monitored from air | ☐ Yes | ☒ No | ☐ N/A | | | | |
| Condition of boundaries | ☒ Good | ☐ Fair | ☐ Poor | | | | |

Comments: The site is in excellent condition. No signs of trespass seen during the site visit. Signs are not present at the site.

**WHICH NATURAL ACTIVITIES/CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION?**
*Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.*

| | | | |
|---|---|---|---|
| ☐ **FLOODING** | ☐ **FIRE** | ☐ **STORM** | ☐ **EARTH MOVEMENT** |
| ☐ **INVASIVE EXOTIC VEGTATION** | ☐ **INSECT INFESTATION** | ☐ **ANIMAL ACTIVITY** | ☐ **OTHER ACTIVITIES/ CHANGES (Explain)** |
| | | | ☒ **NO CHANGE** |

**EXPLAIN:**

# DOT SITE INSPECTION REPORT

**WHICH NATURAL ACTIVITIES/CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION?**
*Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.*

| | | |
|---|---|---|
| ☐ **NEW STURCTURE/ CONSTRUCTION** | ☐ **DUMPING OR STORING** | ☐ **NEW TRAILS OR ROADS** |
| ☐ **TIMBER HARVEST/ VEGETATIVE CUTTING** | ☐ **EXCAVATION (DREDGING, FILLING, GRADING, MINING)** | ☐ **ALTERATION TO DRAINAGE PATTERNS/WATER QUALITY** |
| ☐ **SUBDIVISION** | ☐ **INDUSTRIAL, RESIDENTIAL OR COMMERCIAL USE** | ☐ **LAND CLEARING** |
| ☐ **MOTORIZED VEHICLE DAMAGE** | ☐ **TRESSPASS/VANDALISM** | ☐ **AGRICULTURAL USE** |
| ☐ **ENCROACHMENT FROM ADJACENT PROPERTY** | ☐ **ACTIVITY ON ABUTTING LAND** | ☐ **OTHER ACTIVITIES/ CHANGES (Please Explain)** |
| | | ☒ **NO CHANGE** |

**EXPLAIN:**

**REQUEST FOLLOW-UP BY PROGRAM MANAGER FOR POSSBILE VIOLATIONS.** ☐ YES ☒ NO

| | | |
|---|---|---|
| Were corrective actions completed for previous inspection(s)? | ☐ YES ☒ NO ☐ N/A | **EXPLAIN:** Signs were not installed at the site. |
| Are you aware of any plans that may affect property? | ☐ YES ☒ NO | **EXPLAIN:** |
| Are there concerns about boundaries by adjacent property owners? | ☐ YES ☒ NO | **EXPLAIN:** |
| Are there changes in land use on adjacent property? | ☐ YES ☒ NO | **EXPLAIN:** |
| Are deed restrictions being adhered to? | ☒ YES ☐ NO | **EXPLAIN:** |
| If new property owner, do they have a written copy of the restrictions? | ☐ YES ☐ NO ☒ N/A | |

**ATTACHMENTS:**

1) PHOTOGRAPHS WITH CAPTIONS

2) MAP AND PHOTOGRAPHS OF RELEVANT NATURAL AND MANMADE ACTIVITIES

## Inspection Photographs

Comments: Looking south from sand bar

Comments: Looking north from sand bar

**DOT SITE INSPECTION REPORT**

Comments: Looking north from NC 24

KCI ASSOCIATES OF NC

# Cedar Point

Carteret County

NC DOT Stewardship Sites

0 50 100 200 300 400 Feet

N

STATE OF NORTH CAROLINA DEPARTMENT OF TRANSPORTATION