

## DOWD DAIRY INSPECTION REPORT

MITIGATION SITE NAME Dowd Dairy	TIP # R-2204WM	WBS # 34634.2.6	INSPECTION DATE 9/16/2014
------------------------------------	-------------------	--------------------	------------------------------

COUNTY Bladen	# ACRES 658.0
------------------	------------------

MONITORING ORGANIZATION HDR for NCDOT	INSPECTOR SE / VM	PHONE 919-785-1118	EMAIL ADDRESS vickie.miller@hdrinc.com
------------------------------------------	----------------------	-----------------------	-------------------------------------------

<b>INSPECTION ACTIVITIES:</b> <i>Complete all that apply. Describe location of visited areas if &lt;100%.</i>			
Walked boundaries	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> N/A
Walked trails / roads	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> N/A
Walked road frontage	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> N/A
Walked interior	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> N/A
Monitored from air	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> N/A
Condition of boundaries	<input checked="" type="checkbox"/> GOOD	<input type="checkbox"/> FAIR	<input type="checkbox"/> POOR
<b>COMMENTS:</b> The site boundary remains in good condition at the time of inspection. No trespass, dumping, or hunting issues were noted. The gates were all locked. Beaver dams were noted in the perimeter ditch. A break in the fence was found just west of the far east gate.			

**WHICH NATURAL ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION?**  
*Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.*

<input type="checkbox"/> FLOODING	<input type="checkbox"/> FIRE	<input type="checkbox"/> STORM	<input type="checkbox"/> EARTH MOVEMENT
<input type="checkbox"/> INVASIVE EXOTIC VEGETATION	<input type="checkbox"/> INSECT INFESTATION	<input checked="" type="checkbox"/> ANIMAL ACTIVITY	<input type="checkbox"/> OTHER ACTIVITIES/ CHANGES? <i>(Please Explain)</i>
			<input checked="" type="checkbox"/> NO CHANGE

**EXPLAIN:** Beaver dams noted in the perimeter ditch.

## DOWD DAIRY INSPECTION REPORT

### WHICH MANMADE ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING?

*Check all that apply. Note location and extent. Document with photos.*

<input type="checkbox"/> NEW STRUCTURE / CONSTRUCTION	<input type="checkbox"/> DUMPING OR STORING	<input type="checkbox"/> NEW TRAILS OR ROADS
<input type="checkbox"/> TIMBER HARVEST/ VEGETATIVE CUTTING	<input type="checkbox"/> EXCAVATION (DREDGING, FILLING, GRADING, MINING)	<input type="checkbox"/> ALTERATION TO DRAINAGE PATTERNS/WATER QUALITY
<input type="checkbox"/> SUBDIVISION	<input type="checkbox"/> INDUSTRIAL, RESIDENTIAL, OR COMMERCIAL USE	<input type="checkbox"/> LAND CLEARING
<input type="checkbox"/> MOTORIZED VEHICLE DAMAGE	<input type="checkbox"/> TRESPASS/VANDALISM	<input type="checkbox"/> AGRICULTURAL USE
<input type="checkbox"/> ENCROACHMENT FROM ADJACENT PROPERTY	<input type="checkbox"/> ACTIVITY ON ABUTTING LAND	<input type="checkbox"/> OTHER ACTIVITIES / CHANGES? <i>(Please Explain)</i>
<input checked="" type="checkbox"/> NO CHANGE		
<b>EXPLAIN:</b>		
<b>REQUEST FOLLOW-UP BY PROGRAM MANAGER FOR POSSIBLE VIOLATIONS.</b>		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

Were corrective actions completed for previous inspection(s)?	<input type="checkbox"/> YES	<input type="checkbox"/> NO	<b>EXPLAIN:</b>
		<input checked="" type="checkbox"/> N/A	
Are you aware of any plans that may affect property?	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<b>EXPLAIN:</b>
Are there concerns about boundaries by adjacent property owners?	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<b>EXPLAIN:</b>
Are there changes in land use on adjacent property?	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<b>EXPLAIN:</b>
Are deed restrictions being adhered to?	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<b>EXPLAIN:</b>
If new property owner, do they have a written copy of the restrictions?	<input type="checkbox"/> YES	<input type="checkbox"/> NO	
		<input checked="" type="checkbox"/> N/A	

**ATTACHMENTS:**

1) MAP  
2) PHOTOGRAPHS WITH CAPTIONS

# DOWD DAIRY INSPECTION REPORT



Site boundary markings



# DOWD DAIRY INSPECTION REPORT



View of crossing toward site



:Locked access gate near eastern boundary

# DOWD DAIRY INSPECTION REPORT



View of the site at the eastern boundary




View of the canal adjacent to the road near the middle of the site.

## DOWD DAIRY INSPECTION REPORT



Additional view of the canal adjacent to the road near the middle of the site.



View of the canal adjacent to the road at the western site boundary. Beaver dams noted.

# DOWD DAIRY INSPECTION REPORT



View of the canal turning southwest from the western site boundary.



View of the site along the western boundary.

# DOWD DAIRY INSPECTION REPORT



View of the gate at the western boundary. Combination lock.



View of a channel crossing at the western site boundary.

D:\GIS\Projects\000166 - NorthCarolinaDeptofTransportation\0238152 - NCDOTStewardshipMonitor\map\_docs\mxd\working\ Dowd Dairy.mxd | Last Updated: 09/29/2014



Dowd Dairy Road

Dowd Dairy Site



**Dowd Dairy Site**