UT TO RACCOON BRANCH INSPECTION REPORT

MITIGATION SITE NAME	TIP #	WBS #	INSPECTION DATE
UT To Raccoon Branch	R-2210A	34634.2.14	8/22/14

COUNTY	# ACRES
Haywood	900 LF

MONITORING ORGANIZATION	INSPECTOR	PHONE	EMAIL ADDRESS
HDR for NCDOT	SE / VM	(919) 785-1118	vickie.miller@hdrinc.com

INSPECTION ACTIVITIES: *Complete all that apply. Describe location of visited areas if <100%.*

Walked boundaries	☒ YES	☐ NO	☐ N/A	Walked trails / roads	☒ YES ☐ NO ☐ N/A
Walked road frontage	☒ YES	☐ NO	☐ N/A	Walked interior	☐ YES ☒ NO ☐ N/A
Monitored from air	☐ YES	☒ NO	☐ N/A		
Condition of boundaries	☒ GOOD	☐ FAIR	☐ POOR		

COMMENTS:
Woody vegetation removal was noted under the utility line. The site does not have NCDOT markers.

WHICH NATURAL ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION?
Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.

☐ FLOODING	☐ FIRE	☐ STORM	☐ EARTH MOVEMENT
☒ INVASIVE EXOTIC VEGETATION	☐ INSECT INFESTATION	☐ ANIMAL ACTIVITY	☐ OTHER ACTIVITIES/ CHANGES? *(Please Explain)*
			☐ NO CHANGE

EXPLAIN: Honeysuckle was noted on the site.

UT TO RACCOON BRANCH INSPECTION REPORT

WHICH MANMADE ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING?
Check all that apply. Note location and extent. Document with photos.

☐ NEW STRUCTURE / CONSTRUCTION	☐ DUMPING OR STORING	☐ NEW TRAILS OR ROADS
☒ TIMBER HARVEST/ VEGETATIVE CUTTING	☐ EXCAVATION (DREDGING, FILLING, GRADING, MINING)	☐ ALTERATION TO DRAINAGE PATTERNS/WATER QUALITY
☐ SUBDIVISION	☐ INDUSTRIAL, RESIDENTIAL, OR COMMERCIAL USE	☐ LAND CLEARING
☐ MOTORIZED VEHICLE DAMAGE	☐ TRESPASS/VANDALISM	☐ AGRICULTURAL USE
☐ ENCROACHMENT FROM ADJACENT PROPERTY	☐ ACTIVITY ON ABUTTING LAND	☐ OTHER ACTIVITIES / CHANGES? *(Please Explain)*
		☐ NO CHANGE

EXPLAIN: Woody vegetation has been cut under the utility line and left in place.

REQUEST FOLLOW-UP BY PROGRAM MANAGER FOR POSSIBLE VIOLATIONS. ☐ YES ☒ NO

Were corrective actions completed for previous inspection(s)?	☐ YES	☐ NO ☒ N/A	**EXPLAIN:**
Are you aware of any plans that may affect property?	☐ YES	☒ NO	**EXPLAIN:** Adjacent parcel to the east is for sale.
Are there concerns about boundaries by adjacent property owners?	☐ YES	☒ NO	**EXPLAIN:**
Are there changes in land use on adjacent property?	☐ YES	☒ NO	**EXPLAIN:**
Are deed restrictions being adhered to?	☒ YES	☐ NO	**EXPLAIN:**
If new property owner, do they have a written copy of the restrictions?	☐ YES	☐ NO ☒ N/A	

ATTACHMENTS:

1) MAP OF PERMANENT PHOTO PLOTS
2) PHOTOGRAPHS WITH CAPTIONS
3) MAP AND PHOTOGRAPHS WITH CAPTIONS OF RELEVANT NATURAL AND MANMADE ACTIVITIES
4) OTHER (SPECIFY)

Taken at culvert looking upstream (facing southwest) at vegetation removal under utility lines.

Taken at culvert looking upstream (facing southwest) at vegetation removal under utility lines.

Taken at culvert looking downstream (facing northeast).



D:\GIS\Projects\000166_NorthCarolinaDeptofTransportation\0238152_NCDOTStewardshipMonitor(c)\map_docs\mxd\workingl13_UT to Raccoon Branch Site.mxd | Last Updated: 09.29.2014

UT to Raccoon Branch Site