

## GOSHEN SWAMP INSPECTION REPORT

MITIGATION SITE NAME Goshen Swamp	TIP # R-2211B	WBS # N/A	INSPECTION DATE 10-27-2014
--------------------------------------	------------------	--------------	-------------------------------

COUNTY Duplin	# ACRES 87.7
------------------	-----------------

MONITORING ORGANIZATION Kimley-Horn	INSPECTOR RLS/JLY	PHONE (919) 677-2104	EMAIL ADDRESS Ross.sullivan@kimley-horn.com
--	----------------------	-------------------------	--

<b>INSPECTION ACTIVITIES:</b> <i>Complete all that apply. Describe location of visited areas if &lt;100%.</i>			
Walked boundaries	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> N/A
Walked trails / roads	<input type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> N/A
Walked road frontage	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> N/A
Walked interior	<input type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> N/A
Monitored from air	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> N/A
Condition of boundaries	<input checked="" type="checkbox"/> GOOD	<input type="checkbox"/> FAIR	<input type="checkbox"/> POOR
<p><b>COMMENTS:</b> The site was in excellent condition at time of visit. No visible trespass issues at this time. There were signs of sparse litter along the roadside. The site is densely vegetated with no signs of encroachment from the roadside. Access into the site is limited by dense vegetation and a barbed wire fence that spans the roadside boundary (Photo 3).</p>			

**WHICH NATURAL ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION?**  
*Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.*

<input type="checkbox"/> FLOODING	<input type="checkbox"/> FIRE	<input type="checkbox"/> STORM	<input type="checkbox"/> EARTH MOVEMENT
<input checked="" type="checkbox"/> INVASIVE EXOTIC VEGETATION	<input type="checkbox"/> INSECT INFESTATION	<input type="checkbox"/> ANIMAL ACTIVITY	<input type="checkbox"/> OTHER ACTIVITIES/ CHANGES? <i>(Please Explain)</i>
<input checked="" type="checkbox"/> NO CHANGE			

<p><b>EXPLAIN:</b>          Chinese privet was observed growing thickly in the eastern portion of the property's roadside boundary (Photos 2, 4).</p>
---

## GOSHEN SWAMP INSPECTION REPORT

**WHICH MANMADE ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING?**

*Check all that apply. Note location and extent. Document with photos.*

<input type="checkbox"/> NEW STRUCTURE / CONSTRUCTION	<input type="checkbox"/> DUMPING OR STORING	<input type="checkbox"/> NEW TRAILS OR ROADS
<input type="checkbox"/> TIMBER HARVEST/ VEGETATIVE CUTTING	<input type="checkbox"/> EXCAVATION (DREDGING, FILLING, GRADING, MINING)	<input type="checkbox"/> ALTERATION TO DRAINAGE PATTERNS/WATER QUALITY
<input type="checkbox"/> SUBDIVISION	<input type="checkbox"/> INDUSTRIAL, RESIDENTIAL, OR COMMERCIAL USE	<input type="checkbox"/> LAND CLEARING
<input type="checkbox"/> MOTORIZED VEHICLE DAMAGE	<input type="checkbox"/> TRESPASS/VANDALISM	<input type="checkbox"/> AGRICULTURAL USE
<input type="checkbox"/> ENCROACHMENT FROM ADJACENT PROPERTY	<input type="checkbox"/> ACTIVITY ON ABUTTING LAND	<input type="checkbox"/> OTHER ACTIVITIES / CHANGES? <i>(Please Explain)</i>
<input checked="" type="checkbox"/> NO CHANGE		

**EXPLAIN:**

No changes were apparent from the road frontage. The property is thickly vegetated and fenced in which limits access (Photo 3).

**REQUEST FOLLOW-UP BY PROGRAM MANAGER FOR POSSIBLE VIOLATIONS.**

YES

NO

Were corrective actions completed for previous inspection(s)?	<input type="checkbox"/> YES	<input type="checkbox"/> NO	<b>EXPLAIN:</b>
		<input checked="" type="checkbox"/> N/A	
Are you aware of any plans that may affect property?	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<b>EXPLAIN:</b>
Are there concerns about boundaries by adjacent property owners?	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<b>EXPLAIN:</b>
Are there changes in land use on adjacent property?	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<b>EXPLAIN:</b>
Are deed restrictions being adhered to?	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<b>EXPLAIN:</b>
If new property owner, do they have a written copy of the restrictions?	<input type="checkbox"/> YES	<input type="checkbox"/> NO	
		<input checked="" type="checkbox"/> N/A	

**ATTACHMENTS:**

- 1) SITE PHOTOGRAPHS WITH CAPTIONS
- 2) SITE MAP

# GOSHEN SWAMP INSPECTION REPORT

## SITE PHOTOGRAPHS



Photo 1 – Looking southwest at site’s road frontage along US 117.



Photo 2 – Looking northeast at site’s road frontage along US 117. Chinese privet was growing densely along the road frontage in many places.


## GOSHEN SWAMP INSPECTION REPORT



Photo 3 – Wire fence that borders the site just inside the forest edge.



**Legend**  
[Red outline symbol] Division 3 Study Site



NC OneMap, NC Center for Geographic Information and Analysis, NC 911 Board



**Division 3 -Goshen Swamp**  
NCDOT Site Inspection Program  
Duplin County, North Carolina  
November 2014