

HAW'S RUN INSPECTION REPORT

MITIGATION SITE NAME Haw's Run Mitigation Site	TIP # R-2405WM	WBS # N/A	INSPECTION DATE 10/27/2014
---	-------------------	--------------	-------------------------------

COUNTY Onslow/Pender	# ACRES 589.9
-------------------------	------------------

MONITORING ORGANIZATION Kimley-Horn	INSPECTOR RLS/JLY	PHONE (919) 677-2104	EMAIL ADDRESS Ross.sullivan@kimley-horn.com
--	----------------------	-------------------------	--

INSPECTION ACTIVITIES: <i>Complete all that apply. Describe location of visited areas if <100%.</i>			
Walked boundaries	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> N/A
Walked trails / roads	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> N/A
Walked road frontage	<input type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> N/A
Walked interior	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> N/A
Monitored from air	<input type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> N/A
Condition of boundaries	<input checked="" type="checkbox"/> GOOD	<input type="checkbox"/> FAIR	<input type="checkbox"/> POOR
<p>COMMENTS: The site continues to remain in excellent condition. There are no trespass issues at this time. The lock and chain remain on both gates (at the site entrance from NC 50 and directly at site property boundary, see photos) and have not been disturbed.</p> <p>**Note: Nature Conservancy gate combination is 0911.</p>			

WHICH NATURAL ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION?

Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.

<input type="checkbox"/> FLOODING	<input type="checkbox"/> FIRE	<input type="checkbox"/> STORM	<input type="checkbox"/> EARTH MOVEMENT
<input type="checkbox"/> INVASIVE EXOTIC VEGETATION	<input type="checkbox"/> INSECT INFESTATION	<input type="checkbox"/> ANIMAL ACTIVITY	<input type="checkbox"/> OTHER ACTIVITIES/ CHANGES? (Please Explain)
			<input checked="" type="checkbox"/> NO CHANGE

<p>COMMENTS: Previous report states the adjacent property was burned during a forest fire in 2012. Signs of fire can be seen on neighboring property, but no effect on our site at this time. No nonnative invasive plants were observed on the site.</p>
--

HAW'S RUN INSPECTION REPORT

WHICH MANMADE ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING?

Check all that apply. Note location and extent. Document with photos.

<input type="checkbox"/> NEW STRUCTURE / CONSTRUCTION	<input type="checkbox"/> DUMPING OR STORING	<input type="checkbox"/> NEW TRAILS OR ROADS
<input type="checkbox"/> TIMBER HARVEST / VEGETATIVE CUTTING	<input type="checkbox"/> EXCAVATION (DREDGING, FILLING, GRADING, MINING)	<input type="checkbox"/> ALTERATION TO DRAINAGE PATTERNS/WATER QUALITY
<input type="checkbox"/> SUBDIVISION	<input type="checkbox"/> INDUSTRIAL, RESIDENTIAL, OR COMMERCIAL USE	<input type="checkbox"/> LAND CLEARING
<input type="checkbox"/> MOTORIZED VEHICLE DAMAGE	<input type="checkbox"/> TRESPASS/VANDALISM	<input type="checkbox"/> AGRICULTURAL USE
<input type="checkbox"/> ENCROACHMENT FROM ADJACENT PROPERTY	<input type="checkbox"/> ACTIVITY ON ABUTTING LAND	<input type="checkbox"/> OTHER ACTIVITIES / CHANGES? <i>(Please Explain)</i>
<input checked="" type="checkbox"/> NO CHANGE		

EXPLAIN:

No significant manmade activities/changes were observed during the site visit.

REQUEST FOLLOW-UP BY PROGRAM MANAGER FOR POSSIBLE VIOLATIONS.

YES

NO

Were corrective actions completed for previous inspection(s)?	<input type="checkbox"/> YES	<input type="checkbox"/> NO	EXPLAIN:
		<input checked="" type="checkbox"/> N/A	
Are you aware of any plans that may affect property?	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	EXPLAIN:
Are there concerns about boundaries by adjacent property owners?	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	EXPLAIN:
Are there changes in land use on adjacent property?	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	EXPLAIN:
Are deed restrictions being adhered to?	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	EXPLAIN:
If new property owner, do they have a written copy of the restrictions?	<input type="checkbox"/> YES	<input type="checkbox"/> NO	
		<input checked="" type="checkbox"/> N/A	

ATTACHMENTS:

- 1) SITE PHOTOGRAPHS WITH CAPTIONS
- 2) SITE MAP

HAW'S RUN INSPECTION REPORT

SITE PHOTOGRAPHS



Photo 1 – First gate off NC 50. See the attached site map for location.



Photo 2 – Second gate. This gate opens into the property.

HAW'S RUN INSPECTION REPORT



Photo 3 – Road that runs along the eastern property boundary.



Photo 4 – Looking west into the property from the eastern boundary road.


HAW'S RUN INSPECTION REPORT




Photo 5 – View of the impoundment located at the northern end of the property.



Photo 6 – Looking east across the road/powerline easement that runs through the site.



Legend
 Division 3 Study Site



NC OneMap, NC Center for Geographic Information and Analysis, NC 911 Board



Division 3 -Haw's Run
 NCDOT Site Inspection Program
 Onslow/Pender County, North Carolina
 November 2014