

PEMBROKE CREEK I & II INSPECTION REPORT

WHICH MANMADE ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING?

Check all that apply. Note location and extent. Document with photos.

<input type="checkbox"/> NEW STRUCTURE / CONSTRUCTION	<input type="checkbox"/> DUMPING OR STORING	<input type="checkbox"/> NEW TRAILS OR ROADS
<input type="checkbox"/> TIMBER HARVEST/ VEGETATIVE CUTTING	<input type="checkbox"/> EXCAVATION (DREDGING, FILLING, GRADING, MINING)	<input type="checkbox"/> ALTERATION TO DRAINAGE PATTERNS/WATER QUALITY
<input type="checkbox"/> SUBDIVISION	<input type="checkbox"/> INDUSTRIAL, RESIDENTIAL, OR COMMERCIAL USE	<input type="checkbox"/> LAND CLEARING
<input type="checkbox"/> MOTORIZED VEHICLE DAMAGE	<input type="checkbox"/> TRESPASS/VANDALISM	<input type="checkbox"/> AGRICULTURAL USE
<input type="checkbox"/> ENCROACHMENT FROM ADJACENT PROPERTY	<input type="checkbox"/> ACTIVITY ON ABUTTING LAND	<input type="checkbox"/> OTHER ACTIVITIES / CHANGES? <i>(Please Explain)</i>
<input checked="" type="checkbox"/> NO CHANGE		

Explain:

No human activities were observed in the site. Signage along the road frontage is clearly visible.

REQUEST FOLLOW-UP BY PROGRAM MANAGER FOR POSSIBLE VIOLATIONS.

YES

NO

Were corrective actions completed for previous inspection(s)?	<input type="checkbox"/> YES	<input type="checkbox"/> NO	EXPLAIN:
		<input checked="" type="checkbox"/> N/A	
Are you aware of any plans that may affect property?	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	EXPLAIN:
Are there concerns about boundaries by adjacent property owners?	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	EXPLAIN:
Are there changes in land use on adjacent property?	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	EXPLAIN:
Are deed restrictions being adhered to?	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	EXPLAIN:
If new property owner, do they have a written copy of the restrictions?	<input type="checkbox"/> YES	<input type="checkbox"/> NO	
		<input checked="" type="checkbox"/> N/A	

ATTACHMENTS:

- 1) SITE PHOTOGRAPHS WITH CAPTIONS
- 2) SITE MAP

PEMBROKE CREEK I & II INSPECTION REPORT

Site Photographs:



Photo 1 – Pembroke Creek Mitigation Site signage in place and visible from US 17.



Photo 2 –

PEMBROKE CREEK I & II INSPECTION REPORT



Photo 3 – View of Pembroke Creek Site from US 17 bridge, facing north.




Photo 4 – View of Pembroke Creek Site interior as viewed from road frontage. Access into site is difficult due to strong vegetative growth and site appears to be undisturbed.

PEMBROKE CREEK I & II INSPECTION REPORT



Photo 5 – View of Pembroke Creek Site road frontage, facing southwest along US 17.



Legend

 Division 1 Study Site

0 250 500
Feet

NC OneMap, NC Center for Geographic Information and Analysis, NC 911 Board



Division 1 - Pembroke Creek
NCDOT Site Inspection Program
Chowan County, North Carolina
November 2014