UT to Marks Creek Site's #7 & 8B Inspection Report

Mitigation Site Name	TIP #	WBS #	Inspection Date
UT to Marks Creek Site's #7 & 8B	R-2547C		8-26-2013

County	# Acres
Wake	N/A

Monitoring Organization	Inspector	Phone	Email Address
NCDOT	JCE/BGM	(919)707-6121	rgriffin@ncdot.gov

Inspection Activities: *Complete all that apply.*

Walked boundaries	☒ Yes	☐ No	☐ N/A	Walked trails / roads	☐ Yes ☐ No ☒ N/A
Walked road frontage	☒ Yes	☐ No	☐ N/A	Walked interior	☒ Yes ☐ No ☐ N/A
Monitored from air	☐ Yes	☐ No	☒ N/A		
Condition of boundaries	☒ Good	☐ Fair	☐ Poor		

Comments: Stream buffer remains in excellent condition at both sites. No trespass or dumping issues at the site. No change from previous year

Which natural activities / changes have taken place since last monitoring inspection?
Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.

☐ Flooding	☐ Fire	☐ Storm	☐ Earth Movement
☐ Invasive Exotic Vegetation	☐ Insect Infestation	☐ Animal Activity	☐ Other activities/ changes? *(Please Explain)*
			☒ No Change

Explain:

UT TO MARKS CREEK SITE'S #7 & 8B INSPECTION REPORT

WHICH MANMADE ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING?
Check all that apply. Note location and extent. Document with photos.

☐ NEW STRUCTURE / CONSTRUCTION	☐ DUMPING OR STORING	☐ NEW TRAILS OR ROADS
☐ TIMBER HARVEST/ VEGETATIVE CUTTING	☐ EXCAVATION (DREDGING, FILLING, GRADING, MINING)	☐ ALTERATION TO DRAINAGE PATTERNS/WATER QUALITY
☐ SUBDIVISION	☐ INDUSTRIAL, RESIDENTIAL, OR COMMERCIAL USE	☐ LAND CLEARING
☐ MOTORIZED VEHICLE DAMAGE	☐ TRESPASS/VANDALISM	☐ AGRICULTURAL USE
☐ ENCROACHMENT FROM ADJACENT PROPERTY	☐ ACTIVITY ON ABUTTING LAND	☐ OTHER ACTIVITIES / CHANGES? *(Please Explain)*
		☒ NO CHANGE

EXPLAIN: ATV paths exist in several locations on the site.

REQUEST FOLLOW-UP BY PROGRAM MANAGER FOR POSSIBLE VIOLATIONS. ☐ YES ☒ NO

Were corrective actions completed for previous inspection(s)?	☐ YES	☐ NO ☒ N/A	**EXPLAIN:**
Are you aware of any plans that may affect property?	☐ YES	☒ NO	**EXPLAIN:**
Are there concerns about boundaries by adjacent property owners?	☐ YES	☐ NO	**EXPLAIN:**
Are there changes in land use on adjacent property?	☐ YES	☒ NO	**EXPLAIN:**
Are deed restrictions being adhered to?	☒ YES	☐ NO	**EXPLAIN:**
If new property owner, do they have a written copy of the restrictions?	☐ YES	☐ NO ☐ N/A	

ATTACHMENTS:

1) MAP OF PERMANENT PHOTO PLOTS
2) PHOTOGRAPHS WITH CAPTIONS
3) MAP AND PHOTOGRAPHS WITH CAPTIONS OF RELEVANT NATURAL AND MANMADE ACTIVITIES
4) OTHER (SPECIFY)

Site 7

Site 7

Site 8B

Site 8B

Site 8B

Wendell Falls Blvd.
UT to Mark's Creek (Site #8B)
Knightdale Bypass
Mark's Creek Site
UT to Mark's Creek (Site #7)