

LONG BRANCH INSPECTION REPORT

MITIGATION SITE NAME Long Branch (Kit Creek Rd./NC 55)	TIP # R-2906C	WBS # N/A	INSPECTION DATE 10/24/2013
---	------------------	--------------	-------------------------------

COUNTY Wake	# ACRES 1175 LF
----------------	--------------------

MONITORING ORGANIZATION NCDOT	INSPECTOR JCE/BGM	PHONE (919)707-6121	EMAIL ADDRESS rgriffin@ncdot.gov
----------------------------------	----------------------	------------------------	-------------------------------------

INSPECTION ACTIVITIES: <i>Complete all that apply. Describe location of visited areas if <100%.</i>			
Walked boundaries	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> N/A
Walked trails / roads	<input type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> N/A
Walked road frontage	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> N/A
Walked interior	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> N/A
Monitored from air	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> N/A
Condition of boundaries	<input checked="" type="checkbox"/> GOOD	<input type="checkbox"/> FAIR	<input type="checkbox"/> POOR
<p>COMMENTS: There were no trespass issues at the time of inspection. The stream and buffer continue to look good but the beaver issues noted during last year's report were again noted during this review although not to the extent noted last year. The buffer remains in very good condition but a couple of small beaver dams exist throughout the site. Also there were some cuttings and flagging along Kit Creek road indicating some future utility work may be forthcoming.</p>			

WHICH NATURAL ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION?
Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.

<input type="checkbox"/> FLOODING	<input type="checkbox"/> FIRE	<input type="checkbox"/> STORM	<input type="checkbox"/> EARTH MOVEMENT
<input type="checkbox"/> INVASIVE EXOTIC VEGETATION	<input type="checkbox"/> INSECT INFESTATION	<input checked="" type="checkbox"/> ANIMAL ACTIVITY	<input type="checkbox"/> OTHER ACTIVITIES/ CHANGES? <i>(Please Explain)</i>
			<input type="checkbox"/> NO CHANGE

<p>COMMENTS: Beaver issues exist at the site with several large dams noted.</p>
--

LONG BRANCH INSPECTION REPORT

WHICH MANMADE ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING?

Check all that apply. Note location and extent. Document with photos.

- | | | |
|--|--|---|
| <input type="checkbox"/> NEW STRUCTURE / CONSTRUCTION | <input type="checkbox"/> DUMPING OR STORING | <input type="checkbox"/> NEW TRAILS OR ROADS |
| <input type="checkbox"/> TIMBER HARVEST/ VEGETATIVE CUTTING | <input type="checkbox"/> EXCAVATION (DREDGING, FILLING, GRADING, MINING) | <input type="checkbox"/> ALTERATION TO DRAINAGE PATTERNS/WATER QUALITY |
| <input type="checkbox"/> SUBDIVISION | <input type="checkbox"/> INDUSTRIAL, RESIDENTIAL, OR COMMERCIAL USE | <input type="checkbox"/> LAND CLEARING |
| <input type="checkbox"/> MOTORIZED VEHICLE DAMAGE | <input type="checkbox"/> TRESPASS/VANDALISM | <input type="checkbox"/> AGRICULTURAL USE |
| <input type="checkbox"/> ENCROACHMENT FROM ADJACENT PROPERTY | <input type="checkbox"/> ACTIVITY ON ABUTTING LAND | <input type="checkbox"/> OTHER ACTIVITIES / CHANGES?
<i>(Please Explain)</i> |
| <input checked="" type="checkbox"/> NO CHANGE | | |

EXPLAIN:

REQUEST FOLLOW-UP BY PROGRAM MANAGER FOR POSSIBLE VIOLATIONS.

YES


NO

Were corrective actions completed for previous inspection(s)?	<input type="checkbox"/> YES	<input type="checkbox"/> NO	EXPLAIN:
		<input checked="" type="checkbox"/> N/A	
Are you aware of any plans that may affect property?	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	EXPLAIN:
Are there concerns about boundaries by adjacent property owners?	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	EXPLAIN:
Are there changes in land use on adjacent property?	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	EXPLAIN:
Are deed restrictions being adhered to?	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	EXPLAIN:
If new property owner, do they have a written copy of the restrictions?	<input type="checkbox"/> YES	<input type="checkbox"/> NO	
		<input checked="" type="checkbox"/> N/A	


ATTACHMENTS:

- 1) MAP OF PERMANENT PHOTO PLOTS
- 2) PHOTOGRAPHS WITH CAPTIONS
- 3) MAP AND PHOTOGRAPHS WITH CAPTIONS OF RELEVANT NATURAL AND MANMADE ACTIVITIES
- 4) OTHER (SPECIFY)


LONG BRANCH INSPECTION REPORT



LONG BRANCH INSPECTION REPORT



LONG BRANCH INSPECTION REPORT



LONG BRANCH INSPECTION REPORT



R-2906 Long Branch

55

Kit Creek Road

55

