

DULA THOROFARE CAMP BRANCH INSPECTION REPORT

MITIGATION SITE NAME Dula Thorofare Camp Branch	TIP # R-2911WM	WBS #	INSPECTION DATE 8/19/2014
--	-------------------	-------	------------------------------

COUNTY Anson	# ACRES 95.81
-----------------	------------------

MONITORING ORGANIZATION NCDOT	INSPECTOR RWG/JCE	PHONE (919) 707-6121	EMAIL ADDRESS rgriffin@ncdot.gov
----------------------------------	----------------------	-------------------------	-------------------------------------

INSPECTION ACTIVITIES: <i>Complete all that apply. Describe location of visited areas if <100%.</i>			
Walked boundaries	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	<input type="checkbox"/> N/A
Walked trails / roads	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> N/A
Walked road frontage	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> N/A
Walked interior	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	<input type="checkbox"/> N/A
Monitored from air	<input type="checkbox"/> YES	<input type="checkbox"/> NO	<input checked="" type="checkbox"/> N/A
Condition of boundaries	<input checked="" type="checkbox"/> GOOD	<input type="checkbox"/> FAIR	<input type="checkbox"/> POOR
<p>COMMENTS: We reviewed the site with EEP personnel since DOT will be working on the stewardship portion of the project. NCDOT has several conservation easements on the property and the land owner will need to be contacted prior to any site visit. The access point gate was locked at the time of inspection. The easement areas are in very good shape. A portion of Easement Area #1 was inadvertently logged previously and the land owner paid restitution for the logging. No additional signing needed at this time. Site looks very good.</p>			

WHICH NATURAL ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION?
Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.

<input type="checkbox"/> FLOODING	<input type="checkbox"/> FIRE	<input type="checkbox"/> STORM	<input type="checkbox"/> EARTH MOVEMENT
<input type="checkbox"/> INVASIVE EXOTIC VEGETATION	<input type="checkbox"/> INSECT INFESTATION	<input type="checkbox"/> ANIMAL ACTIVITY	<input type="checkbox"/> OTHER ACTIVITIES/ CHANGES? <i>(Please Explain)</i>
<input type="checkbox"/> NO CHANGE			

<p>EXPLAIN:</p>

DULA THOROFARE CAMP BRANCH INSPECTION REPORT

WHICH MANMADE ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING?

Check all that apply. Note location and extent. Document with photos.

<input type="checkbox"/> NEW STRUCTURE / CONSTRUCTION	<input type="checkbox"/> DUMPING OR STORING	<input type="checkbox"/> NEW TRAILS OR ROADS
<input type="checkbox"/> TIMBER HARVEST/ VEGETATIVE CUTTING	<input type="checkbox"/> EXCAVATION (DREDGING, FILLING, GRADING, MINING)	<input type="checkbox"/> ALTERATION TO DRAINAGE PATTERNS/WATER QUALITY
<input type="checkbox"/> SUBDIVISION	<input type="checkbox"/> INDUSTRIAL, RESIDENTIAL, OR COMMERCIAL USE	<input type="checkbox"/> LAND CLEARING
<input type="checkbox"/> MOTORIZED VEHICLE DAMAGE	<input type="checkbox"/> TRESPASS/VANDALISM	<input type="checkbox"/> AGRICULTURAL USE
<input type="checkbox"/> ENCROACHMENT FROM ADJACENT PROPERTY	<input type="checkbox"/> ACTIVITY ON ABUTTING LAND	<input type="checkbox"/> OTHER ACTIVITIES / CHANGES? <i>(Please Explain)</i>
<input checked="" type="checkbox"/> NO CHANGE		

EXPLAIN: N/A

REQUEST FOLLOW-UP BY PROGRAM MANAGER FOR POSSIBLE VIOLATIONS.

YES

NO

Were corrective actions completed for previous inspection(s)?	<input type="checkbox"/> YES	<input type="checkbox"/> NO	EXPLAIN:
		<input checked="" type="checkbox"/> N/A	
Are you aware of any plans that may affect property?	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	EXPLAIN:
Are there concerns about boundaries by adjacent property owners?	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	EXPLAIN:
Are there changes in land use on adjacent property?	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	EXPLAIN:
Are deed restrictions being adhered to?	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	EXPLAIN:
If new property owner, do they have a written copy of the restrictions?	<input type="checkbox"/> YES	<input type="checkbox"/> NO	
		<input checked="" type="checkbox"/> N/A	

ATTACHMENTS:

- 1) MAP OF PERMANENT PHOTO PLOTS
- 2) PHOTOGRAPHS WITH CAPTIONS
- 3) MAP AND PHOTOGRAPHS WITH CAPTIONS OF RELEVANT NATURAL AND MANMADE ACTIVITIES
- 4) OTHER (SPECIFY)

DULA THOROFARE CAMP BRANCH INSPECTION REPORT



Entrance off Carpenter Road



Previous cutting area near the pond in Easement Area #1

DULA THOROFARE CAMP BRANCH INSPECTION REPORT



Previous cutting area near the pond in Easement Area #1



Previous cutting area near the pond in Easement Area #1

DULA THOROFARE CAMP BRANCH INSPECTION REPORT



Pond in Easement Area #1



Previous cutting area near the pond in Easement Area #1

DULA THOROFARE CAMP BRANCH INSPECTION REPORT



EEP CE signage in EA #1



Conservation Reserve Enhancement Program (CREP) area near EA #3

DULA THOROFARE CAMP BRANCH INSPECTION REPORT



CREP area adjacent to EA #3



CREP area and adjacent EA #3

DULA THOROFARE CAMP BRANCH INSPECTION REPORT



CREP area and adjacent EA #3



CREP area and adjacent EA #3