DOT Site Inspection Report

Mitigation Site Name	TIP #	WBS #	Inspection Date
Afton Run	U-2009A		7/24/13

County	# Acres
Cabarrus	5.06

Monitoring Organization	Inspector	Phone	Email Address
NCDOT	Pete Stafford, Joe Rauseo	919-878-9560	pstafford@rkk.com

Inspection Activities: *Complete all that apply. Describe location of visited areas if <100%.*

Walked boundaries	☐ Yes	☒ No	☐ N/A	Walked trails / roads	☐ Yes	☒ No	☐ N/A
Walked road frontage	☒ Yes	☐ No	☐ N/A	Walked interior	☐ Yes	☒ No	☐ N/A
Monitored from air	☐ Yes	☒ No	☐ N/A				

Condition of boundaries: ☒ Good ☐ Fair ☐ Poor

Comments:

No major changes were observed.

Which natural activities / changes have taken place since last monitoring inspection?
Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.

☐ Flooding	☐ Fire	☐ Storm	☐ Earth Movement
☐ Invasive Exotic Vegetation	☐ Insect Infestation	☒ Animal Activity	☐ Other activities/ changes? *(Please Explain)*
			☐ No Change

Explain:

Deer trails and homeless person camp. It appears the camp was abandoned.

DOT Site Inspection Report

Which manmade activities / changes have taken place since last monitoring?
Check all that apply. Note location and extent. Document with photos.

☐ New structure / construction	☐ Dumping or storing	☐ New trails or roads
☐ Timber harvest/ Vegetative cutting	☐ Excavation (dredging, filling, grading, mining)	☒ Alteration to drainage patterns/water quality
☐ Subdivision	☐ Industrial, residential, or commercial use	☒ LAND CLEARING
☐ Motorized vehicle damage	☐ Trespass/vandalism	☐ Agricultural use
☐ Encroachment from Adjacent property	☐ Activity on abutting land	☐ Other activities / changes? *(Please Explain)*
		☐ No Change

Explain:
Construction on the northern end of the easement has drainage that flows through silt fence and into the restored channel.

Request follow-up by Program Manager for possible violations. ☐ Yes ☒ No

Were corrective actions completed for previous inspection(s)?	☐ Yes	☐ No ☒ N/A	**Explain:**
Are you aware of any plans that may affect property?	☐ Yes	☒ No	**Explain:**
Are there concerns about boundaries by adjacent property owners?	☐ Yes	☒ No	**Explain:**
Are there changes in land use on adjacent property?	☒ Yes	☐ No	**Explain:** Road construction
Are deed restrictions being adhered to?	☒ Yes	☐ No	**Explain:**
If new property owner, do they have a written copy of the restrictions?	☐ Yes	☐ No ☒ N/A	

Attachments:

1) Map of permanent photo plots
2) Photographs with captions
3) map and photographs with captions of relevant natural and Manmade activities
4) Other (specify)

NCDOT
Stewardship Program Mitigation
Site Reviews
Project Name: Afton Run

TIP No. U-2009A
Division No. 10
County: Cabarrus

November 1st, 2013

0 125 250 500 750 1,000 Feet

Lat/Long: 35.41971, -80.671369