DOT SITE INSPECTION REPORT

MITIGATION SITE NAME	TIP #	WBS #	INSPECTION DATE
Six Mile Creek	U-2510A		8/7/13

COUNTY	# ACRES
Union	0.31

MONITORING ORGANIZATION	INSPECTOR	PHONE	EMAIL ADDRESS
NCDOT	Pete Stafford	919-878-9560	pstafford@rkk.com

INSPECTION ACTIVITIES: *Complete all that apply. Describe location of visited areas if <100%.*

Walked boundaries	■ YES	☐ NO	☐ N/A	Walked trails / roads	■ YES ☐ NO ☐ N/A
Walked road frontage	■ YES	☐ NO	☐ N/A	Walked interior	☐ YES ■ NO ☐ N/A
Monitored from air	☐ YES	■ NO	☐ N/A		
Condition of boundaries	■ GOOD	☐ FAIR	☐ POOR		

COMMENTS:

Site looks good. Cat tails in bmp feature. No substantial human impacts observed.

WHICH NATURAL ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION?
Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.

☐ FLOODING	☐ FIRE	☐ STORM	☐ EARTH MOVEMENT
☐ INVASIVE EXOTIC VEGETATION	☐ INSECT INFESTATION	☐ ANIMAL ACTIVITY	☐ OTHER ACTIVITIES/ CHANGES? *(Please Explain)*
			■ NO CHANGE

EXPLAIN:

No substantial human impacts observed.

DOT SITE INSPECTION REPORT

WHICH MANMADE ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING?
Check all that apply. Note location and extent. Document with photos.

☐ NEW STRUCTURE / CONSTRUCTION	☐ DUMPING OR STORING	☐ NEW TRAILS OR ROADS
☐ TIMBER HARVEST/ VEGETATIVE CUTTING	☐ EXCAVATION (DREDGING, FILLING, GRADING, MINING)	☐ ALTERATION TO DRAINAGE PATTERNS/WATER QUALITY
☐ SUBDIVISION	☐ INDUSTRIAL, RESIDENTIAL, OR COMMERCIAL USE	☐ LAND CLEARING
☐ MOTORIZED VEHICLE DAMAGE	☐ TRESPASS/VANDALISM	☐ AGRICULTURAL USE
☐ ENCROACHMENT FROM ADJACENT PROPERTY	☐ ACTIVITY ON ABUTTING LAND	☒ OTHER ACTIVITIES / CHANGES? *(Please Explain)*
		☐ NO CHANGE

EXPLAIN:
Utility easement maintenance.

REQUEST FOLLOW-UP BY PROGRAM MANAGER FOR POSSIBLE VIOLATIONS. ☐ YES ☒ NO

Were corrective actions completed for previous inspection(s)?	☐ YES	☐ NO ☒ N/A	**EXPLAIN:**
Are you aware of any plans that may affect property?	☐ YES	☒ NO	**EXPLAIN:**
Are there concerns about boundaries by adjacent property owners?	☐ YES	☒ NO	**EXPLAIN:**
Are there changes in land use on adjacent property?	☐ YES	☒ NO	**EXPLAIN:**
Are deed restrictions being adhered to?	☒ YES	☐ NO	**EXPLAIN:**
If new property owner, do they have a written copy of the restrictions?	☐ YES	☐ NO ☒ N/A	

ATTACHMENTS:

1) MAP OF PERMANENT PHOTO PLOTS
2) PHOTOGRAPHS WITH CAPTIONS
3) MAP AND PHOTOGRAPHS WITH CAPTIONS OF RELEVANT NATURAL AND MANMADE ACTIVITIES
4) OTHER (SPECIFY)

PIC 1 SITE OVERVIEW

PIC 2 SITE OVERVIEW

PIC 3 SITE OVERVIEW

PIC 4 SITE OVERVIEW

0 50 100 200 300 400 Feet

NCDOT
Stewardship Program Mitigation
Site Reviews
Project Name: Six Mile Creek

N

TIP No. U-2510A
Division No. 10
County: Mecklenburg

Ecosystem Enhancement Program

November 1st, 2013

RK&K

Lat/Long: 35.036371, -80.767537