

DOT SITE INSPECTION REPORT

MITIGATION SITE NAME	TIP#	WBS#	INSPECTION DATE
UT to Turkey Creek (Middlesex Corporate Center)	N/A	N/A	12/17/2014

COUNTY	#ACRES
Nash	18.0

MONITORING ORGANIZATION	INSPECTOR	PHONE	EMAIL ADDRESS
KCI for NCDOT	MU/TS	(919)278-2508	april.eason@kci.com

INSPECTION ACTIVITIES: Complete all that apply. Describe the location of visited areas if <100%

Walked boundaries	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> N/A	Walked Trails/roads	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> N/A
Walked road frontage	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> N/A	Walked Interior	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> N/A
Monitored from air	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input type="checkbox"/> N/A				

Condition of boundaries Good Fair Poor

Comments: The site remains in excellent condition. There were no signs of trespass during the site visit. A gravel road has been constructed along the southern border of the site. The gate to this road was locked.

WHICH NATURAL ACTIVITIES/CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION?
Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.

<input type="checkbox"/> FLOODING	<input type="checkbox"/> FIRE	<input type="checkbox"/> STORM	<input type="checkbox"/> EARTH MOVEMENT
<input type="checkbox"/> INVASIVE EXOTIC VEGTATION	<input type="checkbox"/> INSECT INFESTATION	<input type="checkbox"/> ANIMAL ACTIVITY	<input type="checkbox"/> OTHER ACTIVITIES/ CHANGES (Explain)
			<input checked="" type="checkbox"/> NO CHANGE

EXPLAIN:

DOT SITE INSPECTION REPORT

WHICH NATURAL ACTIVITIES/CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION?

Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.

<input type="checkbox"/> NEW STURCTURE/ CONSTRUCTION	<input type="checkbox"/> DUMPING OR STORING	<input type="checkbox"/> NEW TRAILS OR ROADS
<input type="checkbox"/> TIMBER HARVEST/ VEGETATIVE CUTTING	<input type="checkbox"/> EXCAVATION (DREDGING, FILLING, GRADING, MINING)	<input type="checkbox"/> ALTERATION TO DRAINAGE PATTERNS/WATER QUALITY
<input type="checkbox"/> SUBDIVISION	<input type="checkbox"/> INDUSTRIAL, RESIDENTIAL OR COMMERCIAL USE	<input type="checkbox"/> LAND CLEARING
<input type="checkbox"/> MOTORIZED VEHICLE DAMAGE	<input type="checkbox"/> TRESSPASS/VANDALISM	<input type="checkbox"/> AGRICULTURAL USE
<input type="checkbox"/> ENCROACHMENT FROM ADJACENT PROPERTY	<input type="checkbox"/> ACTIVITY ON ABUTTING LAND	<input type="checkbox"/> OTHER ACTIVITIES/ CHANGES (Please Explain)
		<input checked="" type="checkbox"/> NO CHANGE
EXPLAIN:		
REQUEST FOLLOW-UP BY PROGRAM MANAGER FOR POSSIBLE VIOLATIONS.		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO


Were corrective actions completed for previous inspection(s)?	<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> N/A	EXPLAIN:
Are you aware of any plans that may affect property?	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	EXPLAIN:
Are there concerns about boundaries by adjacent property owners?	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	EXPLAIN:
Are there changes in land use on adjacent property?	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	EXPLAIN: A corporate center was constructed adjacent to the site, this is not expected to affect the project.
Are deed restrictions being adhered to?	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	EXPLAIN:
If new property owner, do they have a written copy of the restrictions?	<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> N/A	

ATTACHMENTS:

- 1) PHOTOGRAPHS WITH CAPTIONS
- 2) MAP AND PHOTOGRAPHS OF RELEVANT NATURAL AND MANMADE ACTIVITIES

DOT SITE INSPECTION REPORT

Inspection Photographs



Comments: Taken from western side, looking out of easement at new paved road crossing

DOT SITE INSPECTION REPORT



DOT SITE INSPECTION REPORT



Comments: Taken from western side, looking into easement



UT to Turkey Creek (Middlesex)

Nash County

 NC DOT Stewardship Sites

