





Figure 1. Vicinity map.

Land Management Group, Inc.
Environmental Consultants
Wilmington, N.C.
November 2003

The Dale Tract
Wilmington Bypass Project
Brunswick County, NC
Year Three Monitoring Report

Restoration
Enhancement



0 500 1000 2000

SCALE 1" = 1000'

Figure 2. Monitoring gauge locations.

Land Management Group, Inc.
Environmental Consultants
Wilmington, N.C.
November 2003

The Dale Tract
Wilmington Bypass Project
Brunswick County, NC
Year Three Monitoring Report




Figure 3. Location of vegetation monitoring plots.

Land Management Group, Inc.
 Environmental Consultants
 Wilmington, N.C.
 November 2003

The Dale Tract
 Wilmington Bypass Project
 Brunswick County, NC
 Year Three Monitoring Report

↓ View of ditch that was filled in 1999.



↓ Most of tract is thick with fetterbush, gallberry, loblolly bay, and pond pine.



Pictures of site.

Land Management Group, Inc.
Environmental Consultants
Wilmington, N.C.
November 2003

Dale Tract
Wilmington Bypass Project
Brunswick County, NC
Year Three Monitoring Report

↓ Vegetation monitoring plot.



↓ Area near A-Well transect; looking out towards old ditch.



Pictures of site.

Land Management Group, Inc.
Environmental Consultants
Wilmington, N.C.
November 2003

Dale Tract
Wilmington Bypass Project
Brunswick County, NC
Year Three Monitoring Report