

DOT MITIGATION STEWARDSHIP INSPECTION REPORT

MITIGATION SITE NAME Plemmons Kirkpatrick Creek Site	TIP # A-0010	ONEID 057-026	INSPECTION DATE September 10, 2024
---	-----------------	------------------	---------------------------------------

COUNTY Madison	Division 13	# ACRES 2.17
-------------------	----------------	-----------------

INSPECTING ORGANIZATION NCDOT	INSPECTOR Contact: Jason Elliott	PHONE 919-707-6000	EMAIL ADDRESS jcelliot@ncdot.gov
----------------------------------	-------------------------------------	-----------------------	-------------------------------------

INSPECTION ACTIVITIES: <i>Complete all that apply.</i>			
Walked boundaries	No	Walked trails / roads	No
Walked road frontage	Yes	Walked interior	No
Monitored from air	No		
Condition of boundaries	Good		
COMMENTS: Site undisturbed at time of inspection. Fencing is in place and no mow signs present. Adjacent livestock are being kept out of site.			

WHICH NATURAL ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION?

Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.

<input type="checkbox"/> Flooding	<input type="checkbox"/> Fire	<input type="checkbox"/> Storm	<input type="checkbox"/> Earth Movement
<input type="checkbox"/> Invasive or Exotic Vegetation	<input type="checkbox"/> Insect Infestation	<input type="checkbox"/> Animal Activity	<input type="checkbox"/> Other Activity or Changes (Add Comments)
<input checked="" type="checkbox"/> No Change			

EXPLAIN:

DOT MITIGATION STEWARDSHIP INSPECTION REPORT

WHICH MANMADE ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING?

Check all that apply. Note location and extent. Document with photos.

<input type="checkbox"/> New Structure Construction	<input type="checkbox"/> Dumping or Storage	<input type="checkbox"/> New Trails or Roads
<input type="checkbox"/> Timber Harvest or Vegetative Cutting	<input type="checkbox"/> Excavation (Dredging, Filling, Grading, Mining)	<input type="checkbox"/> Alteration To Drainage Patterns or Water Quality
<input type="checkbox"/> Utility Activity	<input type="checkbox"/> Industrial Residential or Commercial Use	<input type="checkbox"/> Land Clearing
<input type="checkbox"/> Motorized Vehicle Damage	<input type="checkbox"/> TRESSPASS/VANDALISM	<input type="checkbox"/> AGRICULTURAL USE
<input type="checkbox"/> ENCROACHMENT FROM ADJACENT PROPERTY	<input type="checkbox"/> ACTIVITY ON ABUTTING LAND	<input type="checkbox"/> OTHER ACTIVITIES/CHANGES <input checked="" type="checkbox"/> NO CHANGE

EXPLAIN:

REQUEST FOLLOW-UP BY PROGRAM MANAGER FOR POSSIBLE VIOLATIONS. Yes No

Were corrective actions completed for previous inspection(s)? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A	EXPLAIN:
Are you aware of any plans that may affect property? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	EXPLAIN:
Are there concerns about boundaries by adjacent property owners? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	EXPLAIN:
Are there changes in land use on adjacent property? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	EXPLAIN:
Are deed restrictions being adhered to? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	EXPLAIN:
If new property owner, do they have a written copy of the restrictions? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A	EXPLAIN:

ATTACHMENTS:

- 1) PHOTOGRAPHS WITH CAPTIONS
- 2) MAP OF PHOTO LOCATIONS AND INSPECTION ROUTE

DOT MITIGATION STEWARDSHIP INSPECTION REPORT

Image #1 Text: Boundary condition.



Date & Time: September 10, 2024 3:30 PM

Location: 35.791493, -82.863386

Photo Direction: North

DOT MITIGATION STEWARDSHIP INSPECTION REPORT

Image #2 Text: Site interior.



Date & Time: September 10, 2024 3:31 PM

Location: 35.791727, -82.863599

Photo Direction: North

DOT MITIGATION STEWARDSHIP INSPECTION REPORT

Image #3 Text: Boundary condition.



Date & Time: September 10, 2024 3:31 PM

Location: 35.791844, -82.863717

Photo Direction: North

DOT MITIGATION STEWARDSHIP INSPECTION REPORT

Image #4 Text: Boundary marker in place.



Date & Time: September 10, 2024 3:32 PM

Location: 35.791933, -82.863809

Photo Direction: North

ONEID: 057-026
TIP: A-0010

Mitigation Site Map 2024

Plemmons Kirkpatrick Creek Site

Division: 13
County: Madison



1" = 83 ft

Center: 82.86281°W 35.79229°N

2.17 Ac.

▶▶▶▶ Inspection Route

▭ Site Boundary