

DOT SITE INSPECTION REPORT

MITIGATION SITE NAME South Fork Big Pine Creek (Charles/McGinnis)	TIP # A-0010WM	WBS # 34634.2.13	INSPECTION DATE 9/21/2016
--	-------------------	---------------------	------------------------------

COUNTY Madison	# ACRES 1.10
-------------------	-----------------

MONITORING ORGANIZATION NCDOT	INSPECTOR Pete Stafford	PHONE 919-878-9560	EMAIL ADDRESS pstafford@rkk.com
----------------------------------	----------------------------	-----------------------	------------------------------------

INSPECTION ACTIVITIES: <i>Complete all that apply. Describe location of visited areas if <100%.</i>			
Walked boundaries ☐ YES ☒ NO ☐ N/A	Walked trails / roads ☐ YES ☒ NO ☐ N/A		
Walked road frontage ☒ YES ☐ NO ☐ N/A	Walked interior ☐ YES ☒ NO ☐ N/A		
Monitored from air ☐ YES ☐ NO ☒ N/A			
Condition of boundaries ☐ GOOD ☒ FAIR ☐ POOR			
COMMENTS: Roadside mowing and yard debris were observed.			

WHICH NATURAL ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION?
Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.

☐ FLOODING	☐ FIRE	☐ STORM	☐ EARTH MOVEMENT
☐ INVASIVE EXOTIC VEGETATION	☐ INSECT INFESTATION	☐ ANIMAL ACTIVITY	☐ OTHER ACTIVITIES/ CHANGES? <i>(Please Explain)</i>
☒ NO CHANGE			
EXPLAIN: No change from previous year.			

DOT SITE INSPECTION REPORT

WHICH MANMADE ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING?

Check all that apply. Note location and extent. Document with photos.

☐ NEW STRUCTURE / CONSTRUCTION	☒ DUMPING OR STORING	☐ NEW TRAILS OR ROADS
☐ TIMBER HARVEST/ VEGETATIVE CUTTING	☐ EXCAVATION (DREDGING, FILLING, GRADING, MINING)	☐ ALTERATION TO DRAINAGE PATTERNS/WATER QUALITY
☐ SUBDIVISION	☐ INDUSTRIAL, RESIDENTIAL, OR COMMERCIAL USE	☐ LAND CLEARING
☐ MOTORIZED VEHICLE DAMAGE	☐ TRESPASS/VANDALISM	☐ AGRICULTURAL USE
☐ ENCROACHMENT FROM ADJACENT PROPERTY	☐ ACTIVITY ON ABUTTING LAND	☐ OTHER ACTIVITIES / CHANGES? <i>(Please Explain)</i>
☐ NO CHANGE		

EXPLAIN:
 Yard debris within the conservation easement boundary.


REQUEST FOLLOW-UP BY PROGRAM MANAGER FOR POSSIBLE VIOLATIONS.

☐ YES ☒ NO

Were corrective actions completed for previous inspection(s)?	☐ YES ☐ NO	☒ N/A	EXPLAIN:
Are you aware of any plans that may affect property?	☐ YES ☒ NO		EXPLAIN:
Are there concerns about boundaries by adjacent property owners?	☐ YES ☒ NO		EXPLAIN:
Are there changes in land use on adjacent property?	☐ YES ☒ NO		EXPLAIN:
Are deed restrictions being adhered to?	☒ YES ☐ NO		EXPLAIN:
If new property owner, do they have a written copy of the restrictions?	☐ YES ☐ NO	☒ N/A	

ATTACHMENTS:

1) MAP OF PERMANENT PHOTO PLOTS
 2) PHOTOGRAPHS WITH CAPTIONS
 3) MAP AND PHOTOGRAPHS WITH CAPTIONS OF RELEVANT NATURAL AND MANMADE ACTIVITIES
 4) OTHER (SPECIFY)



NCDOT
Stewardship Program Mitigation
Site Reviews

Site: South Fork Big Pine Creek (Charles/McGinnis)

TIP No. A-0010 WM
Division No. 13
County: Madison

October 2016

NC NORTH CAROLINA

RK&K

