

DOT SITE INSPECTION REPORT

MITIGATION SITE NAME Mud Creek	TIP # A-0010WM	ONEID 045-002	INSPECTION DATE October 26, 2023
-----------------------------------	-------------------	------------------	-------------------------------------

COUNTY Henderson	# ACRES 39.13
---------------------	------------------

MONITORING ORGANIZATION KCI	INSPECTOR Tommy Seelinger	PHONE (919) 783-9214	EMAIL ADDRESS tommy.seelinger@kci.com
--------------------------------	------------------------------	-------------------------	--

INSPECTION ACTIVITIES: <i>Complete all that apply.</i>			
Walked boundaries	Yes	Walked trails / roads	Yes
Walked road frontage	Yes	Walked interior	Yes
Monitored from air	Yes		
Condition of boundaries	Good		
<p>COMMENTS: The erosion at the entrance has reached the road and is beginning to undermine the asphalt. There are signs of 4 wheelers accessing the site along the powerline but no signs of access off of the powerline easement.</p>			

WHICH NATURAL ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION?

Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.

<input type="checkbox"/> Flooding	<input type="checkbox"/> Fire	<input type="checkbox"/> Storm	<input checked="" type="checkbox"/> Earth Movement
<input type="checkbox"/> Invasive or Exotic Vegetation	<input type="checkbox"/> Insect Infestation	<input type="checkbox"/> Animal Activity	<input type="checkbox"/> Other Activity or Changes (Add Comments)
			<input type="checkbox"/> No Change

<p>EXPLAIN: Erosion at the site entrance is beginning to undercut the road</p>

DOT SITE INSPECTION REPORT

WHICH MANMADE ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING?

Check all that apply. Note location and extent. Document with photos.

<input type="checkbox"/> New Structure Construction	<input type="checkbox"/> Dumping or Storage	<input type="checkbox"/> New Trails or Roads
<input type="checkbox"/> Timber Harvest or Vegetative Cutting	<input type="checkbox"/> Excavation (Dredging, Filling, Grading, Mining)	<input type="checkbox"/> Alteration To Drainage Patterns or Water Quality
<input type="checkbox"/> Utility Activity	<input type="checkbox"/> Industrial Residential or Commercial Use	<input type="checkbox"/> Land Clearing
<input checked="" type="checkbox"/> Motorized Vehicle Damage	<input type="checkbox"/> TRESSPASS/VANDALISM	<input type="checkbox"/> AGRICULTURAL USE
<input type="checkbox"/> ENCROACHMENT FROM ADJACENT PROPERTY	<input type="checkbox"/> ACTIVITY ON ABUTTING LAND	<input type="checkbox"/> OTHER ACTIVITIES/CHANGES <input type="checkbox"/> NO CHANGE

EXPLAIN: 4 wheelers are accessing the powerline easement but don't appear to be trespass beyond it

REQUEST FOLLOW-UP BY PROGRAM MANAGER FOR POSSIBLE VIOLATIONS.

Yes

No

Were corrective actions completed for previous inspection(s)? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A	EXPLAIN:
Are you aware of any plans that may affect property? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	EXPLAIN:
Are there concerns about boundaries by adjacent property owners? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	EXPLAIN:
Are there changes in land use on adjacent property? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	EXPLAIN:
Are deed restrictions being adhered to? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	EXPLAIN:
If new property owner, do they have a written copy of the restrictions? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A	EXPLAIN:

ATTACHMENTS:

- 1) PHOTOGRAPHS WITH CAPTIONS
- 2) MAP OF PHOTO LOCATIONS AND INSPECTION ROUTE

DOT SITE INSPECTION REPORT

Image #1: Site entrance



Date: 2023/10/26

Time: 14:37:45

Longitude: -82.47743297222222

Latitude: 35.372081200000004

DOT SITE INSPECTION REPORT

Image #2: Rill where it has reached the road



Date: 2023/10/26

Time: 14:38:07

Longitude: -82.47742508333333

Latitude: 35.3720949

DOT SITE INSPECTION REPORT

Image #3: Stream on site



Date: 2023/10/26

Time: 14:55:12

Longitude: -82.47607641666667

Latitude: 35.37150611944445

DOT SITE INSPECTION REPORT

Image #4: Aerial view of the site



Date:
Time:
Longitude:
Latitude:

DOT SITE INSPECTION REPORT

Image #5: Aerial view of the site



Date:
Time:
Longitude:
Latitude:

2023 Stewardship Site Map

Mud Creek

ONEID: 045-002
TIP: A-0010WM

Division: 14
County: Henderson



1 inch equals 333 ft

Center: 82.47365°W 35.37054°N

39.13 Ac.

● Site Photos ▶▶▶▶ Inspection Route □ Site Boundary