## PLEMMONS-KIRKPATRICK CREEK SITE INSPECTION REPORT

MITIGATION SITE NAME Plemmons-Kirkpatrick Spring Creek		TIP # A-0010		ONE ID # 057-026		INSPECTION DATE AUGUST 19, 2020	
COUNTY Madison	# ACRES 2.17						
MONITORING ORGANIZATION INSPECTO KCI for NCDOT TS/KOE		-	Рноме (919) 783-9214		EMAIL ADDRESS tommy.seelinger@kci.com		
<b>INSPECTION ACTIVITIES:</b> Complete all that apply. Describe location of visited areas if <100%.							
Walked boundaries YES	No [	N/A	Walked trai	ls / roads	YES	NO N/A	
Walked road frontage XES	No [	] N/A	Walked inte	erior	YES	No N/A	
Monitored from air YES	No [	] N/A					
Condition of boundaries GOOD FAIR POOR							
<b>COMMENTS:</b> Site is in excellent condition. Signs are present and visible.							

## WHICH NATURAL ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION?

*Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.* 

FLOODING	FIRE	STORM	Earth Movement
INVASIVE EXOTIC VEGETATION	INSECT INFESTATION	ANIMAL ACTIVITY	OTHER ACTIVITIES/ CHANGES? (Please Explain)
COMMENTS:			

## PLEMMONS-KIRKPATRICK CREEK SITE INSPECTION REPORT

WHICH MANMADE ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING?

Check all that apply. Note location and extent. Document with photos.							
NEW STRUCTURE / CONSTRUCTION	DUMPING OR STORING			NEW TRAILS OR ROADS			
TIMBER HARVEST/ VEGETATIVE CUTTING	EXCAVATION (DREDGING, FILLING, GRADING, MINING)			ALTERATION TO DRAINAGE PATTERNS/WATER QUALITY			
SUBDIVISION	INDUSTRIAL, RESIDENTIAL, OR COMMERCIAL USE			LAND CLEARING			
MOTORIZED VEHICLE DAMAGE	TRESPASS/VANDALISM			AGRICULTURAL USE			
ENCROACHMENT FROM ADJACENT PROPERTY	ACTIVITY ON ABUTTING LAND			OTHER ACTIVITIES / CHANGES? (Please Explain)			
				No Change			
EXPLAIN:							
<b>R</b> EQUEST FOLLOW-UP BY <b>P</b> ROGRAM MANAGER FOR POSSIBLE VIOLATIONS.				YES	⊠No		
Were corrective actions		No	EXPLAIN:				
completed for previous	YES						
inspection(s)?		N/A	Transa i ana				
Are you aware of any plans that may affect property?	YES	No	EXPLAIN:				
Are there concerns about boundaries by adjacent property owners?	YES	No	EXPLAIN:				
Are there changes in land us on adjacent property?	e 🗌 YES	No	EXPLAIN:				
Are deed restrictions being adhered to?	YES	No	EXPLAIN:				
If new property owner, do they have a written copy of the restrictions?	YES	No					
A		N/A					
ATTACHMENTS:							
1) PHOTOGRAPHS WITH CAPTIONS 2) MAP AND PHOTOGRAPHS OF RELEVANT NATURAL AND MANMADE ACTIVITIES							

## **PLEMMONS-KIRKPATRICK CREEK SITE INSPECTION REPORT**



Photo 1 – View into site from western boundary, signage present.



Photo 2 – Signs present marking boundary of site.

