

DOT SITE INSPECTION REPORT

MITIGATION SITE NAME Sunset Beach Bridge	TIP # B-0682	ONEID 010-005	INSPECTION DATE September 26, 2023
---	-----------------	------------------	--

COUNTY Brunswick	# ACRES 1.5
---------------------	----------------

MONITORING ORGANIZATION DOT	INSPECTOR Jason Elliott	PHONE (919)-707-6114	EMAIL ADDRESS jelliott@ncdot.gov
--------------------------------	----------------------------	-------------------------	-------------------------------------

INSPECTION ACTIVITIES: <i>Complete all that apply.</i>			
Walked boundaries	No	Walked trails / roads	No
Walked road frontage	Yes	Walked interior	No
Monitored from air	No		
Condition of boundaries	Good		
COMMENTS: Site remains in excellent condition. No issues at this time.			

WHICH NATURAL ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION?

Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.

<input type="checkbox"/> Flooding	<input type="checkbox"/> Fire	<input type="checkbox"/> Storm	<input type="checkbox"/> Earth Movement
<input type="checkbox"/> Invasive or Exotic Vegetation	<input type="checkbox"/> Insect Infestation	<input type="checkbox"/> Animal Activity	<input type="checkbox"/> Other Activity or Changes (Add Comments)
			<input checked="" type="checkbox"/> No Change

EXPLAIN:

DOT SITE INSPECTION REPORT

WHICH MANMADE ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING?

Check all that apply. Note location and extent. Document with photos.

<input type="checkbox"/> New Structure Construction	<input type="checkbox"/> Dumping or Storage	<input type="checkbox"/> New Trails or Roads
<input type="checkbox"/> Timber Harvest or Vegetative Cutting	<input type="checkbox"/> Excavation (Dredging, Filling, Grading, Mining)	<input type="checkbox"/> Alteration To Drainage Patterns or Water Quality
<input type="checkbox"/> Utility Activity	<input type="checkbox"/> Industrial Residential or Commercial Use	<input type="checkbox"/> Land Clearing
<input type="checkbox"/> Motorized Vehicle Damage	<input type="checkbox"/> TRESSPASS/VANDALISM	<input type="checkbox"/> AGRICULTURAL USE
<input type="checkbox"/> ENCROACHMENT FROM ADJACENT PROPERTY	<input type="checkbox"/> ACTIVITY ON ABUTTING LAND	<input type="checkbox"/> OTHER ACTIVITIES/CHANGES <input checked="" type="checkbox"/> NO CHANGE

EXPLAIN:

REQUEST FOLLOW-UP BY PROGRAM MANAGER FOR POSSIBLE VIOLATIONS. Yes No

Were corrective actions completed for previous inspection(s)?	<input type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> N/A	EXPLAIN:
Are you aware of any plans that may affect property?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No		EXPLAIN:
Are there concerns about boundaries by adjacent property owners?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No		EXPLAIN:
Are there changes in land use on adjacent property?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No		EXPLAIN:
Are deed restrictions being adhered to?	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No		EXPLAIN:
If new property owner, do they have a written copy of the restrictions?	<input type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> N/A	

ATTACHMENTS:

- 1) PHOTOGRAPHS WITH CAPTIONS
- 2) MAP OF PHOTO LOCATIONS AND INSPECTION ROUTE

DOT SITE INSPECTION REPORT

Image #1: View of interior of site along bridge.



Date: 2023/09/26

Time: 10:31:10

Longitude: -78.50986652777777

Latitude: 33.87758133333333

DOT SITE INSPECTION REPORT

Image #2: View of interior of site on opposite side of bridge.



Date: 2023/09/26

Time: 10:32:02

Longitude: -78.50969205555556

Latitude: 33.877635500000004

DOT SITE INSPECTION REPORT

Image #3: View of site along Sunset Blvd.



Date: 2023/09/26

Time: 10:33:18

Longitude: -78.5096186388889

Latitude: 33.8775783888889

2023 Stewardship Site Map

Sunset Beach Bridge

ONEID: 010-005
TIP: B-0682

Division: 3
County: Brunswick



1 inch equals 144 ft

Center: 78.51023°W 33.87935°N

1.50 Ac.

● Site Photos >>>> Inspection Route □ Site Boundary