

## DOT SITE INSPECTION REPORT

MITIGATION SITE NAME Sunset Beach Bridge	TIP # B-0682	ONEID 010-005	INSPECTION DATE September 16, 2021
---	-----------------	------------------	--

COUNTY Brunswick	# ACRES 1.5
---------------------	----------------

MONITORING ORGANIZATION NCDOT	INSPECTOR David Johnson	PHONE (919)-707-6130	EMAIL ADDRESS ddjohnson@ncdot.gov
----------------------------------	----------------------------	-------------------------	--------------------------------------

<b>INSPECTION ACTIVITIES:</b> <i>Complete all that apply.</i>			
Walked boundaries	No	Walked trails / roads	No
Walked road frontage	Yes	Walked interior	No
Monitored from air	No		
Condition of boundaries	Good		
<b>COMMENTS:</b> Site in fine condition. No evidence of trespass or encroachment.			

### WHICH NATURAL ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION?

*Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.*

<input type="checkbox"/> Flooding	<input type="checkbox"/> Fire	<input type="checkbox"/> Storm	<input type="checkbox"/> Earth Movement
<input type="checkbox"/> Invasive or Exotic Vegetation	<input type="checkbox"/> Insect Infestation	<input type="checkbox"/> Animal Activity	<input type="checkbox"/> Other Activity or Changes (Add Comments)
			<input checked="" type="checkbox"/> No Change
<b>EXPLAIN:</b>			

## DOT SITE INSPECTION REPORT

### WHICH MANMADE ACTIVITIES / CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING?

*Check all that apply. Note location and extent. Document with photos.*

<input type="checkbox"/> New Structure Construction	<input type="checkbox"/> Dumping or Storage	<input type="checkbox"/> New Trails or Roads
<input type="checkbox"/> Timber Harvest or Vegetative Cutting	<input type="checkbox"/> Excavation (Dredging, Filling, Grading, Mining)	<input type="checkbox"/> Alteration To Drainage Patterns or Water Quality
<input type="checkbox"/> Utility Activity	<input type="checkbox"/> Industrial Residential or Commercial Use	<input type="checkbox"/> Land Clearing
<input type="checkbox"/> Motorized Vehicle Damage	<input type="checkbox"/> TRESSPASS/VANDALISM	<input type="checkbox"/> AGRICULTURAL USE
<input type="checkbox"/> ENCROACHMENT FROM ADJACENT PROPERTY	<input type="checkbox"/> ACTIVITY ON ABUTTING LAND	<input type="checkbox"/> OTHER ACTIVITIES/CHANGES <input checked="" type="checkbox"/> NO CHANGE
<b>EXPLAIN:</b>		
<b>REQUEST FOLLOW-UP BY PROGRAM MANAGER FOR POSSIBLE VIOLATIONS.</b> <div style="float: right; text-align: right;"> <input type="checkbox"/> Yes      <input checked="" type="checkbox"/> No         </div>		

Were corrective actions completed for previous inspection(s)? <div style="text-align: right;"> <input type="checkbox"/> Yes      <input type="checkbox"/> No  <input checked="" type="checkbox"/> N/A         </div>	<b>EXPLAIN:</b>
Are you aware of any plans that may affect property? <div style="text-align: right;"> <input type="checkbox"/> Yes      <input checked="" type="checkbox"/> No         </div>	<b>EXPLAIN:</b>
Are there concerns about boundaries by adjacent property owners? <div style="text-align: right;"> <input type="checkbox"/> Yes      <input checked="" type="checkbox"/> No         </div>	<b>EXPLAIN:</b>
Are there changes in land use on adjacent property? <div style="text-align: right;"> <input type="checkbox"/> Yes      <input checked="" type="checkbox"/> No         </div>	<b>EXPLAIN:</b>
Are deed restrictions being adhered to? <div style="text-align: right;"> <input checked="" type="checkbox"/> Yes      <input type="checkbox"/> No         </div>	<b>EXPLAIN:</b>
If new property owner, do they have a written copy of the restrictions? <div style="text-align: right;"> <input type="checkbox"/> Yes      <input type="checkbox"/> No  <input checked="" type="checkbox"/> N/A         </div>	<b>EXPLAIN:</b>
<b>ATTACHMENTS:</b>	
1) PHOTOGRAPHS WITH CAPTIONS 2) MAP OF PHOTO LOCATIONS AND INSPECTION ROUTE	

# DOT SITE INSPECTION REPORT

**Image #1:** View from coastal side of mitigation area.



Date: 2021/09/16

Time: 09:49:53

Longitude: -78.50968369444445

Latitude: 33.87765119444445



# DOT SITE INSPECTION REPORT

**Image #2:** View of temporary impact area.



Date: 2021/09/16

Time: 09:50:47

Longitude: -78.50964380555556

Latitude: 33.87750830555556



# 2021 Stewardship Inspection Map

## Sunset Beach Bridge

ONEID: 010-005

TIP: B-0682

Division: 3

County: Brunswick



Map Center: 78.5102°W 33.8793°N

1 inch equals 220'

1.504709 AC.

● Ground Photo Points    ● UAS Photo Points    ► Inspection Route    ■ Mitigation Site Boundary