

DOT SITE INSPECTION REPORT

MITIGATION SITE NAME	TIP#	WBS#	INSPECTION DATE
Thoroughfare Bay Bridge	B-1098	N/A	12/15/2014

COUNTY	#ACRES
Carteret	3.35

MONITORING ORGANIZATION	INSPECTOR	PHONE	EMAIL ADDRESS
KCI for NCDOT	MU/TS	(919)278-2508	april.eason@kci.com

INSPECTION ACTIVITIES: Complete all that apply. Describe the location of visited areas if <100%							
Walked boundaries	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> N/A	Walked Trails/roads	<input type="checkbox"/> Yes	<input type="checkbox"/> No	<input checked="" type="checkbox"/> N/A
Walked road frontage	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> N/A	Walked Interior	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	<input type="checkbox"/> N/A
Monitored from air	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	<input type="checkbox"/> N/A				
Condition of boundaries	<input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor						
Comments: Mowing is occurring at the site in two locations. See photos below.							

WHICH NATURAL ACTIVITIES/CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION?

Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.

<input type="checkbox"/> FLOODING	<input type="checkbox"/> FIRE	<input type="checkbox"/> STORM	<input type="checkbox"/> EARTH MOVEMENT
<input type="checkbox"/> INVASIVE EXOTIC VEGETATION	<input type="checkbox"/> INSECT INFESTATION	<input type="checkbox"/> ANIMAL ACTIVITY	<input type="checkbox"/> OTHER ACTIVITIES/ CHANGES (Explain)
			<input checked="" type="checkbox"/> NO CHANGE
EXPLAIN:			

DOT SITE INSPECTION REPORT

WHICH NATURAL ACTIVITIES/CHANGES HAVE TAKEN PLACE SINCE LAST MONITORING INSPECTION?

Check all that apply. Note location and extent. Wherever possible, note species of concern. Document with photos.

<input type="checkbox"/> NEW STURCTURE/ CONSTRUCTION	<input type="checkbox"/> DUMPING OR STORING	<input type="checkbox"/> NEW TRAILS OR ROADS
<input type="checkbox"/> TIMBER HARVEST/ VEGETATIVE CUTTING	<input type="checkbox"/> EXCAVATION (DREDGING, FILLING, GRADING, MINING)	<input type="checkbox"/> ALTERATION TO DRAINAGE PATTERNS/WATER QUALITY
<input type="checkbox"/> SUBDIVISION	<input type="checkbox"/> INDUSTRIAL, RESIDENTIAL OR COMMERCIAL USE	<input checked="" type="checkbox"/> LAND CLEARING
<input type="checkbox"/> MOTORIZED VEHICLE DAMAGE	<input type="checkbox"/> TRESSPASS/VANDALISM	<input type="checkbox"/> AGRICULTURAL USE
<input type="checkbox"/> ENCROACHMENT FROM ADJACENT PROPERTY	<input type="checkbox"/> ACTIVITY ON ABUTTING LAND	<input type="checkbox"/> OTHER ACTIVITIES/ CHANGES (Please Explain)
		<input type="checkbox"/> NO CHANGE

EXPLAIN: Mowing activities

REQUEST FOLLOW-UP BY PROGRAM MANAGER FOR POSSIBLE VIOLATIONS.

☐ YES
 ☒ NO

Were corrective actions completed for previous inspection(s)? <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> N/A	EXPLAIN:
Are you aware of any plans that may affect property? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	EXPLAIN:
Are there concerns about boundaries by adjacent property owners? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	EXPLAIN:
Are there changes in land use on adjacent property? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	EXPLAIN:
Are deed restrictions being adhered to? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	EXPLAIN: Mowing activities.
If new property owner, do they have a written copy of the restrictions? <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> N/A	

ATTACHMENTS:

1) PHOTOGRAPHS WITH CAPTIONS
 2) MAP AND PHOTOGRAPHS OF RELEVANT NATURAL AND MANMADE ACTIVITIES

DOT SITE INSPECTION REPORT

Inspection Photographs



Comments: Mowing on the south side of the bridge.



Comments: Mowing on the north side of the bridge.

DOT SITE INSPECTION REPORT





Thoroughfare Bay

Carteret County

 NC DOT Stewardship Sites

0 250 500 1,000 1,500 2,000 Feet

