


- Restoration
- Enhancement
- Reference
- Drainage ditches (filled in 1999)
- Gauge transect
- - - - Power line corridor
- X Vegetation monitoring plot
- A Pre-project monitoring gauges



Note: Gauges D1 and D2 are in the same location as pre-project gauges B and C.

Figure 2. Hydrological gauge transects and vegetation plot locations.

Land Management Group, Inc.
 Environmental Consultants
 Wilmington, N.C.
 December 2004

The Eagle Brunswick Tract
 Wilmington Bypass Project
 Brunswick County, NC
 Year Four Monitoring Report