

**NCDOT Division 13 PROTECT Grant Application  
Supporting Documentation Index**

BRIDGE 100078

1. 100078 – Bridge Routine Inspection Report
2. 100078 – Bridge Scour Report

BRIDGE 100154

1. 100154 – Bridge Routine Inspection Report
2. 100154 – Bridge Scour Report

BRIDGE 100203

1. 100203 – Bridge Routine Inspection Report
2. 100203 – Bridge Scour Report
3. Video - Scour Repair
4. Video - Stream During Tropical Storm Fred
5. Water Diversion for Scour Repair Photo 1
6. Water Diversion for Scour Repair Photo 2

BRIDGE 560149

1. 560149 – Bridge Routine Inspection Report

BRIDGE 560531

1. 560531 – Bridge Scour Report

COUNTY DOCUMENTS

1. Buncombe County Stream Restoration Project Report
2. Comprehensive Transportation Plan for French Broad River MPO and Rural Areas of Buncombe and Haywood Counties
3. Madison County Comprehensive Transportation Plan

STATE DOCUMENTS

1. NCDOT Transportation Asset Management Plan

2. North Carolina Climate Risk Assessment and Resilience Plan
3. North Carolina Erosion and Sediment Control Design and Construction Manual
4. North Carolina Climate Science Report
5. NCDOT Resilience Policy
6. NCDOT Resilience Report

#### PROJECT AREA HISTORY

1. Flood/Bridge Repair History for Project Area
2. Existing Conditions and Public Input History