

Page of

2013 Coverage Count
Code Entry Sequence Order **Enter Code**

1. Is this a retake of a previous count?	R If this is a retake
2. Is there a problem?	M If MACHINE related

T If TUBE related
O If any OTHER event related. **MUST** add remarks to explain
L If LOCATION installed different than shown on map

3. Are you scheduling a retake? S If Yes

NOTE: Enter remarks as needed. If using "O" code, you must enter remarks to describe "OTHER". Examples of

"OTHER" events are weather, construction (remark if road is open or closed), accidents, activities (fairs, races, store grand openings, etc.).

1

Station No.	Route ID	Location	Machine No.	One	Count Two	Three	Codes	Remarks	Install Time
		of							
		of							
		of							
		of							
		of							
		of							
		of							
		of							
		of							
		of							
		of							
		of							
		of							
		of							
		of							
		of							
		of							

End Time:

Data Collector: Tina Pleasant

Date Installed: 12 / 17 / 12

Day of Week: M TU W TH I

County Name: Greene

Special Project #

Start Time:

2013 Coverage Count

Code Entry Sequence Order

Enter Code

1 Is this a retake of a previous count?
2 Is there a problem?

NOTE: Enter remarks as needed. If using "O" code, you must enter remarks to describe "OTHER". Examples of "OTHER" events are weather, construction (remark if road is open or closed), accidents, activities (fairs, races, store, grand openings, etc.).

3 Are you scheduling a retake?

S If Yes

R If this is a retake

M If MACHINE related

T If TUBE related

O If any OTHER event related. MUST add remarks to explain

L If LOCATION installed different than shown on map

A If AUDIT field supervisor to conduct safety audit

Station No.	Route ID	Location	Machine No.	One	Count Two	Three	Codes	Remarks	Install Time
1621	SE1135	E of SE1113	41542	139	166				0731
1623	SE1113	N of SE1132	40790	3288	3390				0742
1626	SE1131	W of SE1113	34657	2717	2661				0751
28	US70	S of SE1131	39296	18707	19307		65	Other side bad count	0803
28	US70	S of SE1131	39425	6534	2		75		0812
1627	SE1113	E of SE1128	39349	4818	4936				0818
16384	SE1116	S of SE2041	35351	2502	2667				0820
29	US70	S of SE1116	39202	13578	13954		05	Other side bad count	0835
29	US70	S of SE1116	39195	13452	10199		75		0840
1584	SE1116	W of SE1900	—	—	—		0	Private Road	—
1609	SE1114	E of SE1113	41229	699	710				0855
1611	SE1112	E of SE1159	41861	279	277				0900
1585	SE1110	W of SE1977	39206	21	21		0	Dead end road	0906
1599	SE1101	S of SE1108	41354	609	721				0913
1598	SE1104	E of SE1101	39174	633	598				0918

End Time:

2013 Coverage Count

Data Collector: Tim Pleasant

Date Installed: 12 / 17 / 12

Day of Week: M TU W TH I

County Name: Calaveras

Special Project #

Start Time:



Code Entry Sequence Order Enter Code

1	Is this a retake of a previous count?	R	If this is a retake
2	Is there a problem?	M	If MACHINE related
		T	If TUBE related
		O	If any OTHER event related. MUST add remarks to explain
		L	If LOCATION installed different than shown on map
		A	If AUDIT field supervisor to conduct safety audit
3	Are you scheduling a retake?	S	If Yes

NOTE: Enter remarks as needed. If using "O" code, you must enter remarks to describe "OTHER". Examples of "OTHER" events are weather, construction (remark if road is open or closed), accidents, activities (fairs, races, state grand openings, etc.).

Station No.	Route ID	Location	Machine No.	One	Two	Three	Codes	Remarks	Install Time
82	US70	N of SE 2018	39180	13146	14150				0924
82	US70	N of SE 2018	41149	13092	13915				0931
1587	SE1187	N of US70	44961	248	261				0937
1688	SE1765	N of SE1778	39145	426	432				0952
39	US70	S of SE1765	41666	12921	13252				0957
39	US70	S of SE1765	41794	12412	12779				1002
40	US70	E of SE1763	46619	15417	15616				1008
40	US70	E of SE1763	41887	14859	15121				1013
41	US70	W of NC101	46819	14327	14585				1018
41	US70	W of NC101	39409	15682	16058				1022
1703	SE1763	E of SE1766	39270	261	226				1030
3412	SE1747	W of SE1746	39430	1077	1199				1038
1591	SE1756	S of SE1745	45559	4733	8053				1043
44	US70	S of NC101	40761	11180	11420			Sidewalk work could not	1051
44	US70	S of NC101	39294	11394	11376			trap	1057

End Time:

2013 Coverage Count

Data Collector: Tim Pleasant

Date Installed: 12 / 17 / 12

Day of Week: (M) TU W TH I

County Name: Garza

Special Project # _____

Start Time: _____



Code Entry Sequence Order _____ Enter Code _____

1. Is this a retake of a previous count? R If this is a retake
 2. Is there a problem? M If MACHINE related
T If TUBE related
O If any OTHER event related. MUST add remarks to explain
L If LOCATION installed different than shown on map
A If AUDIT field supervisor to conduct safety audit

3. Are you scheduling a retake? S If Yes

NOTE: Enter remarks as needed. If using "O" code, you must enter remarks to describe "OTHER". Examples of "OTHER" events are weather, construction (remark if road is open or closed), accidents, activities (fairs, races, store grand openings, etc.).

Station No.	Route ID	Location	Machine No.	One	Count Two	Three	Codes	Remarks	Install Time
42	NC101	W of SE1737	39253	8212	8448				1100
42	NC101	W of SE1737	40782	8479	8581				1153
43	NC101	W of SE1735	39387	5614	5750				1108
43	NC101	W of SE1735	36092	5440	5602				1112
1707	SE1735	S of NC101	39252	2591	2345				1116
46	US70	S of SE1735	41253	14988	15275				1128
45	US70	S of SE1735	39157	15084	15185				1128
24	US70	E of SE1824	39346	11508	11790				1135
24	US70	E of SE1824	41214	11506	11518				1142
23	NC101	S of NC306	40845	8657	8857				1158
70	NC306	W of NC101	34957	2732	2968				1159
1593	SE1715	E of SE1714	40811	764	712				1237
25	NC101	E of SE1715	39348	5261	5344				1213
1594	SE1700	S of SE1708	39341	1751	1839				1214
519	SE1703	W of SE1700	39428	266	297				1232

End Time: _____